Agilent 86122A Programming

- Introduction to Programming (pg. 2)
- Non-Sequential Commands (pg. 20)
- Summary for Experienced GPIB Programmers (pg. 6)
- Status Registers (pg. 22)
- SCPI Syntax Rules (pg. 9)
- Queues (pg. 30)
- Setting the GPIB Address and Initializing the Instrument (pg. 14)
- Programming Commands (pg. 31)
- Remote Measurements (pg. 16)
- Example Programs (pg. 193)
- Sending Remote Commands
 Over LAN (pg. 17)
- Returned Data Format (pg. 208)



Programming examples are written in HP Basic.

Programming Introduction

Related Topics



The easiest way to program this instrument is by using the VXI*plug&play* universal instrument drivers. The VXI*plug&play* universal instrument drivers allow you to develop programs using the following applications: Agilent VEE, LabVIEW, LabWindows/CVI, C, C++, and Microsoft® Visual Basic.

You can control the instrument remotely by using the General Purpose Interface Bus (GPIB) programming commands. GPIB is a system of hardware and software that allows you to control test equipment to make measurements quickly, accurately, and repeatably. You can also use GPIB to perform other functions, such as printing.

The GPIB programming commands are compatible with the Standard Commands for Programmable Instruments (SCPI) standard.




If you have controlled instruments over GPIB, <u>Summary for Experienced GPIB Programmers</u> has information you will find useful

Almost every program that you write will need to monitor the Agilent 86122A for its operating status. This includes querying execution or command errors and determining whether or not measurements have been completed. To learn how to enable and read the registers provided to accomplish these tasks, review the following topics:

- Status Registers
- Queues

The following graphic is a simplified block diagram of the Agilent 86122A. This block diagram lists some of the available programming commands. Each command is placed next to the section of the instrument that it configures or queries data.



After collecting the uncorrected data, the Agilent 86122A searches the data for the first 1000

peak responses.



For WLIMit:OFF, searching starts at 1650 nm and progresses towards 1270 nm.

For WLIMit:ON, searching starts at WLIMit:START and progresses toward WLIMit:STOP.

These peak values are then placed into the corrected data buffer. Each peak value consists of an amplitude and wavelength measurement. Amplitude and wavelength correction factors are applied to this data.

Because there are so many different GPIB control platforms, the in-line code examples use a platform-independent pseudo code.

sendMessage xxxxx

The above example indicates to send the text string xxxxx to the instrument. We recommend that you write your own function that adds error checking around the low level access routines.

- For VISA, the low level write routine is ivWrite().
- For NI 488, the low level routine is ibwrt(). For SICL, use iwrite().
 - For HP Basic for windows, use OUTPUT.



VISA (Virtual Instrument Software Architecture) is an I/O library designed according to the VXI plug and play system alliance.

SICL (Standard Instrument Control Library) is an I/O library developed by Hewlett Packard and Agilent Technologies that is portable across many systems and I/O interfaces.

receiveInteger

The above example indicates to insert a call to a routine that reads an ASCII response from the instrument and converts it to an integer. The routine will return the integer value. Again, we recommend that you write your own function and do your own conversion from text to integer.

- For VISA, the low level read routine is ivRead().
- For NI 488, use ibrd(). For SICL use iread().
 - For HP Basic for windows, use ENTER.

For more detailed information regarding GPIB, the IEEE 488.2 standard, or the SCPI standard, refer to the following books:

SCPI Consortium. SCPI—Standard Commands for Programmable Instruments, 1997.

International Institute of Electrical and Electronics Engineers. *IEEE Standard 488.1-1987, IEEE Standard Digital Interface for Programmable Instrumentation.* New York, NY, 1987.

International Institute of Electrical and Electronics Engineers. *IEEE Standard 488.2-1987, IEEE Standard Codes, Formats, Protocols and Common Commands For Use with ANSI/IEEE Std 488.1-1987.* New York, NY, 1987.

Summary for Experienced GPIB Programmers

Related Topics

If you are familiar with GPIB instrument programming, terms like EOI, command synchronization, and SCPI should be familiar to you. If not, review <u>Introduction to Programming</u>. This section is a summary to get your application operating quickly, focusing on ways in which the multi-wavelength meter differs from other instruments you may have encountered.

The following topics provide more information:

EOI Required

Command Synchronization

Device Clear

Maximum Query Rate

Single Sweep Mode

Watching for Error Messages

EOI required

Before sending remote commands to the instrument, set your GPIB interface to assert the GPIB END message (also called EOI) with the last character of the transmission. There is a separate GPIB signal line dedicated to EOI, and when the multi-wavelength meter sees the EOI, it closes the buffer and begins processing the commands. The multi-wavelength meter will not accept any more commands until it has parsed and launched (but not necessarily completed) all the commands in the buffer.

Most interfaces use EOI by default. If, for example, you are using a National Instruments GPIB card with Visual C or Visual Basic, EOI is probably on. Similarly, if you are using an Agilent GPIB card in a HP-UX workstation, programming in C or C++, EOI is probably on. If you are using HP Basic for Windows, you will need to enable EOI each time you open a session to the instrument. This is done using the ASSIGN @Mwm key words, and associating the END keyword with the session.

Back to top

Use device clear

The multi-wavelength meter uses the Selected Device Clear interface message to free the instrument from error conditions. Clearing the instrument at the start of any control application will avoid confusing the instrument. You may find it useful to write a small program that does nothing but clear the instrument, so you can clear it as needed while you debug your application.

The Selected Device Clear message is not a text message like *CLS. It is an interface level command.

- For VISA, use viClear().
- For NI 488.2, use ibclr(). For HP SICL, use iclear().
- For HP Basic for windows, use CLEAR 720 or CLEAR @Mwm.

Use single sweep mode

When using remote programming, you will want the instrument to take a sweep only after it is set up and you want the sweep to occur. Allowing the instrument to sweep while you are sending commands complicates the logic of the program. In general, unless an operator is tuning a device, it is best to turn continuous sweep off with:

INITiate: CONTinuous OFF

*RST automatically turns continuous sweep off.

Back to top

Command synchronization

The multi-wavelength meter may start executing the next command before finishing the previous one. This is common among GPIB controlled instruments - it allows the instrument's multi-tasking operating system to execute commands as quickly as possible. Because of this, you will need to use *OPC, *OPC? or *WAI to find out when a sweep is finished before attempting to read data from the instrument. Most commonly, you will send: INITiate to take a single sweep, then wait for the sweep to finish before executing the next command.

The recommended technique for waiting is to use the query form of *OPC (*OPC?). This way, after initiating the sweep, you can do other things while waiting for the instrument. When you do wait, make sure your GPIB time-out is longer than what the instrument needs to finish the command. A typical sequence would be:

sendMessage INIT;*OPC? // take a sweep

//perform other tasks while waiting

receiveInteger // wait for "1" indicating end of sweep

Other alternatives involve polling the instrument for status, and that in turn slows the instrument down by making it respond to the queries. If you must poll for status, it is recommended that you send *ESE 1 to enable the OPC bit to set bit 5 of the main status register, then use serial poll to query the main status register.

Serial poll is a GPIB interface level operation, not a command like *STB?. It is accessed using special commands.

- For VISA, use viReadStb.
- For NI 488.2, use ibrsp. For SICL, use ireadstb().
- For HP Basic for Windows, use SPOLL 720 or SPOLL @Mwm.

Once the OPC bit is set, you will need to manually clear the status register. The easiest way to do this is to send *CLS. You can also clear it by reading the register with *ESR?

If you do not need an explicit response from the instrument, *WAI will cause the instrument to finish processing all prior commands before continuing.

Maximum query rate

If you are waiting for a bit in a status byte, avoid writing a tight loop that continuously queries the instrument. This causes the instrument firmware to spend an excessive amount of time responding to your queries rather than running the instrument. Do not query the instrument more than once every 5 ms. For Visual Basic and Visual C, use the sleep command to put 5 ms delay in your query loop. For posix compliant platforms, use the nanosleep() function to delay the loop. For HP Basic for Windows, use WAIT 0.005.

Back to top

Watching for error messages

Whenever an error occurs, it appears briefly on the instrument display and is added to the error queue. Whenever there are messages in the error queue, bit 2 of the status byte is set. The recommended practice is to use serial poll to read the status byte and then use a bitwise 'and' against the value 4 to see if the bit is set. If it is set, you should use SYSTem:ERRor? to read all the error messages until you get a response that begins with "+0", indicating no further errors.

As you are developing your application, you should check the error status every time you read from or write to the instrument.

For more information about error messages, see Messages and Errors.

SCPI Syntax Rules

Related Topics

Most of the commands used for controlling instruments on the GPIB are Standard Commands for Programmable Instruments (SCPI) commands.

The following topics will help you learn how to use SCPI commands in your programs.

•	Adding parameters to a command	•	Querying data
---	--------------------------------	---	---------------

•	Combining commands from	•	Sending a command
	different subsystems		

- Combining commands in the same subsystem
 Sending common commands
- Notation conventions and definitions
 Using upper or lowercase letters
- Numbers

 Using short or long forms
 command names
- Program instruction terminator
 White space

Adding Command Parameters

Many commands have parameters that specify an option. Use a space character to separate the parameter from the command, as shown in the following example.

OUTPUT 720;":INIT:CONT ON"

Notice the space between CONT and ON.

Separate multiple parameters with a comma (,). Spaces can be added around the commas to improve readability.

OUTPUT 720; ":MEASure:SCALar:POWer:FREQuency? 1300, MAXimum"

Back to top

Combining Commands from Different Subsystems

You can send commands and program queries from different subsystems on the same line. Precede the new subsystem with a semicolon followed by a colon. In the following example, the colon and semicolon pair before DISP allows you to send a command from another subsystem.

OUTPUT 720;": CALCulate2:PEXCursion 12;:DISPlay:WINDow:GRAPh:STATus OFF"

Back to top

Combining Commands in the Same Subsystem

You can combine commands from the same subsystem as long as they are both on the same level in the subsystem hierarchy. Commands are separated with a semi-colon (;). For

example, the following two lines,

OUTPUT 720;":CALCulate2:PEXCursion 12"
OUTPUT 720:":CALCulate2:PTHReshold 20"

can be combined into one line.

OUTPUT 720:": CALCulate2:PEXCursion 12: PTHReshold 20"

Notice that the semicolon separates the two functions.

Back to top

Notation Conventions and Definitions

Review the following SCPI notation conventions.

Convention	Description
<>	Angle brackets indicate values entered by the programmer.
I	Vertical bars, or "pipes", can be read as "or". They are used in syntax diagrams to separate alternative parameter options.
[]	Square brackets indicate that the enclosed items are optional. You can omit some keywords without changing the effect of the command. These optional, or default, keywords are used in many subsystems and are identified by brackets in syntax diagrams.
{}	When several items are enclosed by braces, you can only select one of the items.
<integer></integer>	An ASCII string representing an integer. This is defined by the IEEE 488.2 <nr1> format.</nr1>
<real></real>	An ASCII string representing a real number. This is defined by the IEEE 488.2 <nr2> or <nrf> formats.</nrf></nr2>

Back to top

Numbers

All numbers are expected to be strings of ASCII characters. Therefore, when you send the number 9, you would send a byte representing the ASCII code for the character "9" (which is 57). A three-digit number like 102 takes up three bytes (ASCII codes 49, 48, and 50). This is taken care of automatically when you include the entire instruction in a string. Several representations of a number are possible. For example, the following numbers are all equal:

28 0.28E2 280E-1 28000m 0.028K 28E-3K

If a measurement cannot be made, no response is given and an error is placed into the error queue. For example, the following string will timeout the controller and place a *Data stale or corrupt* error in the error queue because no power data has been received.

*RST

FETCh:POWer?

You can use the following multiplier suffixes:

Multiplier	Mnemonic
1E18	EX
1E15	PE
1E12	Т
1E9	G
1E6	MA
1E3	K
1E-3	M
1E-6	U
1E-9	N
1E-12	Р
1E-15	F
1E-18	Α
Back to top	

Program Instruction Terminator

The string of instructions sent to the instrument is executed after the instruction terminator is received. The terminator may be a new-line (NL) character, the End-Or-Identify (EOI) line asserted, or a combination of the two. All three ways are equivalent.

Asserting the EOI sets the EOI control line low on the last byte of the data message. The NL character is an ASCII linefeed (decimal 10). The NL terminator has the same function as an EOS (End Of String) and EOT (End Of Text) terminator.

Back to top

Querying Data

Data is requested from the instrument using a query. Queries can be used to find out how the instrument is currently configured or to get results of measurements made by the instrument, with the query actually activating the measurement. String responses are returned as upper-case letters.

Queries take the form of a command followed by a question mark (?). After receiving a query, the instrument places the answer in its output queue. The answer remains in the output queue until it is read or another command is issued. For example, the following query places the number of points in the data set in the output queue.

OUTPUT 720:":CALCulate2:POINts?"

In HP BASIC, the controller input statement

ENTER 720;Range

passes the value across the bus to the controller and places it in the variable Range. A newline character is appended to the response.



Sending another command or query before reading the result of a query causes the output queue to be cleared and the current response to be lost. This also generates an error in the error queue.

The output of the instrument may be numeric or character data depending on what is queried. Refer to the specific commands for the formats and types of data returned from queries.

You can send multiple queries to the instrument within a single program message, but you must also read them back within a single program message. This can be accomplished by either reading them back into a string variable or into multiple numeric variables. When you read the result of multiple queries into string variables, a semicolon separates each response.

Back to top

Sending a Command

It is easy to send a command to the instrument. Create a command string from the available commands, and place the string in your program language's output statement. For commands other than common commands, be sure to include a colon before the subsystem name. For example, the following string places the cursor on the peak laser line and returns the power level of this peak:

OUTPUT 720:":MEAS:SCAL:POW? MAX"

Back to top

Sending Common Commands

If a subsystem has been selected and the instrument receives a common command, the instrument remains in the selected subsystem. For example, if the following program message is sent to the instrument, the DISPlay subsystem remains selected.

"DISPLAY:MARKer:MAXimum:LEFT;*CLS;DISPlay:MARKer:MAXimum:RIGHt"

If some other type of command is received within a program message, you must reenter the original subsystem after the command.

Back to top

Using Upper or Lowercase Letters

Program headers can be sent using any combination of uppercase or lowercase ASCII

characters. However, instrument responses are always returned in uppercase.

Back to top

Using Short or Long Forms Command Names

Commands and queries may be sent in either long form (complete spelling) or short form (abbreviated spelling). The description of each command shows both versions; the extra characters for the long form are shown in lowercase. The following is a long form of a command:

OUTPUT 720:":MEASure:SCALar:POWer? MAXimum"

This is the short form of the same command:

OUTPUT 720;":MEAS:SCAL:POW? MAX"

Programs written in long form are easily read and almost self-documenting. Using short form commands conserves the amount of controller memory needed for program storage and reduces the amount of I/O activity.

Use mnemonics to create a short form of a command from the long form. The mnemonic is the first four characters of the keyword *unless* the fourth character is a vowel, in which case the mnemonic is the first three characters of the keyword.



This rule is *not* applied if the length of the keyword is exactly four characters.

Examples of long and equivalent short forms:

Long Form	Equivalent Short Form	

DISPlay DISP
DATA DATA
SYSTEM SYST
ERROR ERR

Back to top

White Space

White space is defined as one or more characters from the ASCII set of 0 through 32 decimal, excluding 10 (NL). White space is optional, and can be used to increase the readability of a program.

Setting the GPIB Address and Initializing the Instrument

You will notice that all programming examples in the online help send the commands to instrument address **720**. The programming examples assume the interface card is set to the interface select code "**7**" and the instrument GPIB address is set to "**20**" (default address). Set the output and input functions of your programming language to send the commands to this address. Alternatively, you can change the GPIB address in the <u>GPIB Setup dialog box</u>, located in the Setup menu.

Remote mode and front-panel lockout

When the instrument is in the remote operating mode, the remote indicator located on the lower right corner of the graphical display is lit.



Press to return control of the instrument to the front panel. and AC Power are the only front panel controls active when the instrument is in remote operation.

Initializing the instrument

To make sure the bus and all appropriate interfaces are in a known state, begin every program with an initialization statement. For example, a CLEAR command clears the interface buffer:

CI FAR 720!



Programming examples are written in HP Basic.

When you use GPIB, CLEAR also resets the instrument's <u>parser</u>. After the interface is cleared, you can initialize the instrument to a preset state with *RST.

OUTPUT 720;"*RST"!

*RST also sets the Agilent 86122A into the single measurement acquisition mode. The READ and MEASure data queries expect this measurement mode; therefore, the proper operation of these queries is ensured.

GPIB Setup



This dialog box allows you to select the GPIB address for the multi-wavelength meter. The default value is 20.



How to access: Setup > GPIB Setup > GPIB Address

SCPI command: N/A




Although the default address is 20, addresses from 0 to 30 may be used if the default address is the same as another instrument's GPIB address. Address 21 is usually reserved for the computer interface Talk/Listen address and should not be used as the instrument address.

Remote Operation

You can control the instrument remotely by using the General Purpose Interface Bus (GPIB). GPIB is a system of hardware and software that allows you to control test equipment to make measurements quickly, accurately, and repeatably. You can also use GPIB to perform other functions, such as printing.

The following graphic is a simplified block diagram of the Agilent 86122A. This block diagram lists some of the available programming commands. Each command is placed next to the section of the instrument that it configures or queries data.



After collecting the uncorrected data, the Agilent 86122A searches the data for the first 1000 peak responses.



For WLIMit:OFF, searching starts at 1650 nm and progresses towards 1270 nm.
For WLIMit:ON, searching starts at WLIMit:START and progresses toward WLIMit:STOP.

These peak values are then placed into the corrected data buffer. Each peak value consists of an amplitude and wavelength measurement. Amplitude and wavelength correction factors are applied to this data.

Sending Remote Commands over the LAN

The Standard Instrument Control Library (SICL) Local Area Network (LAN) enables you to control your remote instrument over the LAN as if your local instrument is connected directly to the controller with the GPIB. SICL provides control of your instrument over the LAN, using a variety of computing platforms, I/O interfaces, and operating systems.

Your instrument implements a SICL LAN server. To control the instrument, you need a SICL LAN *client* application running on a computer or workstation that is connected to the instrument over a LAN. Typical applications implementing a SICL LAN client include:

- Agilent VEE
- HP BASIC
 - National Instrument's LabView with Agilent VISA/SICL client drivers



SICL LAN can be used with Windows 95, Windows 98, Windows NT, and HP-UX.

The following topics provide more information about sending remote commands over the LAN.

SICL LAN Setup Information

Set up Controller as SICL LAN Client (HPUX)

Set up Instrument as SICL LAN Server

Limitations of SICL LAN Client

Set up Controller as SICL LAN Client (Windows)

SICL LAN Set-up Information

Before setting up your controller as a SICL LAN client, you will need to collect the following information:

The GPIB name is the name given to a device used to GPIB name

communicate with the instrument. Your instrument is

shipped with hpib7 as the GPIB name.

GPIB logical

unit

The logical unit number is a unique integer assigned to the device to be controlled using SICL LAN. Your instrument is

shipped with the logical unit number set to 7.

GPIB device address

The device address is the GPIB device address (bus address) assigned to the device to be controlled using

SICL LAN. Your instrument is shipped with the GPIB device

address set to 20.

The SICL LAN client uses the GPIB name, GPIB logical unit number, and GPIB address to communicate with the server. You must match these parameters exactly when you set up the SICL LAN client and server.

Your instrument becomes an active SICL LAN server when configured for networking. See <u>SICL LAN Set-up Information</u> for the network setup information. You can change the GPIB address in the <u>GPIB Setup dialog box</u>, located in the Setup menu.

Back to top

Setting Up Your Controller as a SICL LAN Client (Windows)

For Windows 95, Windows 98, and Windows NT:

- 1. Install Agilent I/O Libraries.
- 2. Run I/O configuration.
- 3. Select **LAN Client** from the Available Interface Types.
- 4. Click Configure.
- 5. Click OK.
- 6. Select **VISA LAN Client** from the Available Interface Types.
- 7. Click **Configure**.
- 8. Enter the hostname or IP address of your instrument.
- 9. Enter hpib7 in the remote SICL interface name field.
- 10. Click **OK**.
- 11. Select the new VISA LAN Client then click Edit.
- 12. Click Edit VISA Config.
- 13. Clear the **Unselect Identify devices at run-time** box.
- 14. Click Add Device.
- 15. Enter the GPIB address of your instrument, then Click **OK** three times to exit the application.

Back to top

Setting Up Your Controller as a SICL LAN Client (HPUX)

- 1. Install Agilent SICL Libraries.
- 2. Run iosetup.
- 3. Select **LAN Client** from the Available Interface Types.
- 4. Click Configure.
- 5. Click **OK**.

Back to top

Limitations of LAN Clients

1. There may be a period of up to 5 seconds when you will be unable to open a LAN interface with the Agilent 86122A. It is common for LAN clients to open an Interface Session for

- device actions. If your client application opens an interface session, there will be a delay between the time the interface is closed and when you will be able to open a new interface.
- 2. You will receive separate responses to SCPI queries that are combined on a single line. For example if you send SENS:START?STOP? you will have to read twice to get both responses.

```
iprintf (osa, "SENS:START?;STOP?\n");
iscanf (osa, "%t", startWavelength); /* +6.00000000E-007 */
iscanf (osa, "%t", stopWavelength); /* +1.70000000E-006 */
```

Normally (with GPIB) you would receive both responses separated with a semicolon.

```
iprintf (osa, "SENS:START?;STOP?\n");
iscanf (osa, "%t", startStop); /* +6.00000000E-007;+1.70000000E-006 */
```

3. You must not set a time-out of less then 1-second.

Non-Sequential Commands

The Agilent 86122A normally processes its remote commands sequentially. The instrument waits until the actions specified by a particular command are completed before reading and executing the next command. However, there are a few non-sequential commands where this is not true. Non-sequential commands do not finish executing before the next command is interpreted.

The following is a list of non-sequential commands:

:CALCulate1:TRANsform:FREQuency:POINTs

:CALCulate2:PEXCursion

:CALCulate2:PTHReshold

:CALCulate2:WLIMit:STARt:FREQuency

:CALCulate2:WLIMit:STARt:WAVelength

:CALCulate2:WLIMit:STARt:WNUMber

:CALCulate2:WLIMit:STOP:FREQuency

:CALCulate2:WLIMit:STOP:WAVelength

:CALCulate2:WLIMit:STOP:WNUMber

:CALCulate3:SNR:AUTO

:SENSe:CORRection:ELEVation

:INITiate:CONTinuous

:INITiate[:IMMediate]

:HCOPy:[:IMMediate]

*TRG



The command :SENSe:CORRection:ELEVation provides backwards compatiblity with previous instruments and is not relevant to the 86122A.

The following additional commands are also non-sequential commands if CALCulate3:SNR:AUTO is set to OFF:

:CALCulate3:REFerence:FREQuency

:CALCulate3:REFerence:WAVelength

:CAL Culate3:RFFerence:WNUMber

Non-sequential commands can reduce overall execution time of programs, but can also be the source of annoying errors. Forcing the Agilent 86122A to wait for non-sequential commands to finish eliminates this problem.

Always use *OPC or *WAI with non-sequential commands to ensure your programs execute properly. For example, suppose that you wanted to set the elevation correction value and then

send an :INIT:IMM command. The following programming fragment results in an error "-213 *Init ignored*". This occurs because the :ELEVation command causes the recalculation of the data which is like sending the :INIT:IMM command. When the actual :INIT:IMM is sent, the error occurs because the command is already in progress.

OUTPUT 720;":INIT:IMM"

OUTPUT 720;":SENSe:CORRection:ELEVation 1000"

OUTPUT 720;":INIT:IMM"

Use an *OPC? query to ensure that the :ELEVation command has completed as shown in the following lines:

OUTPUT 720;":INIT:IMM"

OUTPUT 720;":SENSe:CORRection:ELEVation 1000"

OUTPUT 720;"*OPC?"

ENTER 720; Response\$

OUTPUT 720;":INIT:IMM"

Or, the *WAI command could be used:

OUTPUT 720;":INIT:IMM"

OUTPUT 720;":SENSe:CORRection:ELEVation 1000"

OUTPUT 720;"*WAI?"

OUTPUT 720;":INIT:IMM"

Status Registers

The Agilent 86122A provides four registers that you can query to monitor the instrument's condition. These registers allow you to determine the following:

- Status of an operation
- Availability of the measured data
 - Reliability of the measured data

The following topics provide more information about the status registers.

Status Byte

QUEStionable Status

Standard Event Enable

Enabling Register Bits with Masks


OPERation Status

Status Byte Register

The Status Byte Register monitors the status of the other three registers. This register contains summary bits that monitor activity in the other status registers and queues. The Status Byte Register's bits are set and cleared by the presence and absence of a summary bit from other registers or queues. Notice in the following figure that the bits in the Standard Event Status, OPERation Status, and QUEStionable Status registers are "or'd" to control a bit in the Status Byte Register.

If a bit in the Status Byte Register goes high, you can query the value of the source register to determine the cause.

The Status Byte Register can be read using either the *STB? command or the GPIB serial poll command. Both commands return the decimal-weighted sum of all set bits in the register. The difference between the two methods is that the serial poll command reads bit 6 as the Request Service (RQS) bit and clears the bit which clears the SRQ interrupt. *STB? reads bit 6 as the Master Summary Status (MSS) and does not clear the bit or have any effect on the SRQ interrupt. The value returned is the total bit weights of all of the bits that are set at the present time.



The following table defines the bits in the Statue Byte Register.

Bit	Bit Weight	Condition
0	1	Not Used
1	2	Not Used
2	4	Error Queue Status
3	8	Questionable Status
4	16	Message Available (MAV)
5	32	Standard Event Status (ESB)
6	64	Master Summary Status (MSS)
7	128	Operation Status

Standard Event Enable Status Register

The Standard Event Enable Status Register is the standard IEEE 488.2 register. This register monitors the following instrument status events:

- OPC Operation Complete
- RQC Request Control
- QYE Query Error
- DDE Device Dependent Error
- EXE Execution Error
- CME Command Error
- URQ User Request
 - PON Power On

When one of these events occur, the corresponding bit in the register is set. If the bits are enabled in the Standard Event Status Enable Register, the bits set in this register generate a summary bit to set bit 5 (ESB) in the Status Byte Register.

The contents of the Standard Event Status Register can be read and the register cleared by sending the *ESR? query. The value returned is the total bit weights of all of the bits that are set at the present time.


Back to top

OPERation Status Register

The OPERation Status Register contains the bits that report on the instrument's normal operation. You can query the value of the OPERation Status Register using commands in the STATus subsystem.

The STATus subsystem also has transition filter software that gives you the ability to select the

logic transitions that sets bits in the OPERation Status Register.



The following table defines the bits in the OPERation Status Register.

Bit	Definition
0	Not used.
1	Setting indicates that the instrument is waiting for the motor to reach the proper position before beginning data acquisition.
2	Ranging indicates that the instrument is currently gain ranging.
3	Not used.

4	Measuring indicates that the instrument is currently making a measurement.
5 through 8	Not used.
9	Processing indicates that the instrument is currently processing the data acquired.
10	Hardcopy indicates that the instrument is currently printing the data to the parallel port.
11	Averaging indicates that the instrument is in the process of averaging the noise for the signal-to-noise ratio calculation.
10 th rough 15	Notuced


12 through 15 Not used.

Back to top

Bits in Questionable Status Register

The Questionable Status Register contains the bits that report on the instrument's normal operation. You can query the value of the QUEStionable Status Register using commands in the STATus subsystem.

The STATus subsystem also has transition filter software that gives you the ability to select the logic transitions that sets bits in the QUEStionable Status Register. For example, you can define the POWer bit of the QUEStionable Status register to report an event when the condition transitions from false to true. This is a positive transition. You can also specify a negative transition where the bit is set when the condition transitions from true to false.



The following table defines the bits in the OPERation Status Register.

		_			_	_	
Bi	1	_	\ _	fin			
ж	T		Ю	TIN	۱ІТ	חו	n
_	L	_	•				

0, 1, 2 Not used.

3 **Power** indicates that the instrument is measuring

too high of a power.

4 **Over Temperature** indicates the HeNe laser is

over temperature. Shut down instrument. If this condition persists, contact your <u>Agilent Service</u>

Center.

5 through 8 Not used.

9 **Maximum Signals** indicates that the instrument

	has found the maximum number of signals.
10	Drift Reference indicates that during one or more data acquisitions, the number of signals detected differed from the number of reference signals.
11	Delta Reference indicates that there is no delta reference signal.
12	Not Stabilized indicates that the HeNe laser is not stabilized. A measurement cannot be made until the laser is stabilized.
13	Not used
14	Command Warning indicates that the instrument has received some extra, unexpected parameters for one of the measurement functions.
15	Not used.
Back to top	

Enabling Register Bits with Masks

Several masks are available which you can use to enable or disable individual bits in each register. For example, you can disable the Hardcopy bit in the OPERation Status Register so that even though it goes high, it can never set the summary bit in the status byte high.

Use *SRE to set or query the mask for the Status Byte Register.

The masks for the OPERation Status and QUEStionable Status registers are set and queried using the STATus subsystem's ENABle commands.

Use *ESE to set or query the mask for the Standard Event Status Register.

The *CLS common command clears all event registers and all queues except the output queue. If *CLS is sent immediately following a program message terminator, the output queue

is also cleared. In addition, the request for the *OPC bit is also cleared.

For example, suppose your application requires an interrupt whenever any type of error occurs. The error related bits in the Standard Event Status Register are bits 2 through 5. The sum of the decimal weights of these bits is 60. Therefore, you can enable any of these bits to generate the summary bit by sending *ESE 60.

Whenever an error occurs, it sets one of these bits in the Standard Event Status Register. Because the bits are all enabled, a summary bit is generated to set bit 5 in the Status Byte Register.

If bit 5 (ESB) in the Status Byte Register is enabled (via the *SRE command), an SRQ service request interrupt is sent to the external computer.

Standard Event Status Register bits that are not enabled still respond to their corresponding conditions (that is, they are set if the corresponding event occurs). However, because they are not enabled, they do not generate a summary bit to the Status Byte Register.

Queues

There are two queues in the instrument: the output queue and the error queue. You can query the values in either queue.

Output queue

The output queue stores the instrument responses that are generated by certain commands and queries that you send to the instrument. The output queue generates the Message Available summary bit when the output queue contains one or more bytes. This summary bit sets the MAV bit (bit 4) in the Status Byte Register. The method used to read the Output Queue depends upon the programming language and environment. For example, when using HP BASIC, you can read the output queue using the ENTER statement.

Error queue

As errors are detected, they are placed in an error queue. Instrument specific errors are indicated by positive values. General errors have negative values. You can clear the error queue by reading its contents, sending the *CLS command, or by cycling the instrument's power.

The error queue is first in, first out. If the error queue overflows, the last error in the queue is replaced with error -350, "Queue overflow." Any time the queue overflows, the least recent errors remain in the queue, and the most recent error is discarded. The length of the instrument 's error queue is 30 (29 positions for the error messages, and 1 position for the "Queue overflow" message).

The error queue is read with SYSTEM:ERROR?. Executing this query reads and removes the oldest error from the head of the queue, which opens a position at the tail of the queue for a new error. When all the errors have been read from the queue, subsequent error queries return 0, "No error."

See Error Messages for more information on reading the error queue.

Command Types

The programming commands in this instrument can be placed into one of three types: measurement instruction commands, common commands, and subsystem commands.

Click/touch any of the following command types to view more information about the commands in the selected group.

- Measurement Instructions
- Common Commands
- Subsystem Commands

For an overall list of available commands, click/touch the following:

List of Commands

There are a variety of measurements that the Agilent 86122A can perform. The following table shows an example of these different measurements and their associated programming commands. There may be more than one method to obtain the desired data. Refer to the individual command information for the correct command syntax.

Desired Measurement	Configuation Command	Data Query
Wavelength (nm)	CONFigure, FETCh, READ, and MEASure	MEASure:ARRay:POWer:WAVelength?
Frequency (THz)	CONFigure, FETCh, READ, and MEASure	MEASure:ARRay:POWer:FREQuency?
Wave number	CONFigure, FETCh, READ, and MEASure	MEASure:ARRay:POWer:WNUMber?
Power (W, dBm)	CONFigure, FETCh, READ, and MEASure	MEASure:ARRay:POWer:?
Average Wavelength, Wave number, or Frequency	CALCulate2:PWAVerage:STATe	CALCulate2:DATA?
Total Power (W, bDm)	CALCulate2: PWAVerage:STATe	CALCulate2:DATA?
Fabry-Perot Laser	CALCulate3:FPERot	FPERot[:STATe]?
Laser-Line Separation	CALCulate3:DELTa:REFerence	CALCulate3:DATA?
Laser-Line Drift	CALCulate3:DRIFt: STATe	CALCulate3:DATA?
Signal-to-Noise Ratio	CALCulate3:SNR:STATe	CALCulate3:DATA?
Signal-to-Noise Ratio Average	CALCulate3:ASNR:STATe	CALCulate3:DATA?
Time-Domain Data	CALCulate1:TRANsform :FREQuency:POINts	SENSe: DATA?


Uncorrected Frequency Domain Data

CALCulate1:TRANsform :FREQuency:POINts

CALCulate1:DATA?

Measurement Instructions

Use measurement instructions to perform measurements and return the desired results to your computer. The Agilent 86122A uses four basic measurement instructions: CONFigure, FETCh, READ, and MEASure. Measurement instructions have the following hierarchy:





MEASure and READ are identical to combining the following commands:

:MEASure :ABORt;:CONFigure;:READ

:READ :ABORt;:INITiate:IMMediate;:FETCh

To perform a measurement, add a POWer function to the measurement instruction. The POWer functions select power, frequency, wavelength, or wave number measurements.

You can specify whether FETCh, READ, or MEASure returns a single value (:SCALar) or multiple values (:ARRay). The following example specifies SCALar data:


:MEASure:SCALar:POWer:WAVelength? MAX

Click/touch any of the four basic measurement instructions to view more information about the selected instruction group and its associated commands.



:CONFigure Command

Use CONFigure commands to change measurement settings without taking a measurement. The CONFigure commands place the instrument in the Multi-WL or Peak WL display mode. The CONFigure commands have the following hierarchy:



The CONFigure query returns the last configuration setup by CONFigure. The instrument returns a string that represents the current configuration of the instrument. The returned string is in the short command form, and returned values are in base units as in the following examples.

Command :CONFigure:SCALar:POWer:WAVelength 1300NM, MAX

Query "POW:WAV 1.300000e-6,0.01"

Response



The 1300NM and resolution (MAX) values track the actual instrument settings and input signals. Notice that the quotation marks are part of the returned string.

Command :CONFigure:SCALar:POWer –9 dBm

Query "POW 1.196978e-4,DEF"

Response



The power values are always returned in watts.

According to the SCPI command reference, :ARRay causes an instrument to take multiple measurements. The *<size>* parameter indicates the number of measurements to take. However, with the Agilent 86122A, the ARRay command refers to the measurements performed for one measurement sweep; this will result in an array of measured signals. Therefore the *< size>* parameter will not apply to this command and the instrument will ignore any *<*size> parameter sent. A syntax error will not be generated if a *<*size> parameter is sent.

Click/touch any of the following CONFigure commands to view more information about the selected command.



The command trees for each of the four basic <u>measurement instructions</u> are identical.



CONFigure {:ARRay | [:SCALar]} :POWer



CONFigure {:ARRay | [:SCALar]}
:POWer:WAVelength

• CONFigure {:ARRay | [:SCALar]}
:POWer:FREQuency

CONFigure{:ARRay | [:SCALar]}
:POWer:WNUMber

:CONFigure{:ARRay | [:SCALar]} :POWer



The command trees for each of the four basic <u>measurement instructions</u> are identical.

Command :POWer [<expected_value>[,<resolution>]]

Returns amplitude values.

Used With <expected_value> <resolution>

SCALar optional optional ARRay Ignored optional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a power level that is closest to the

<expected_value> parameter.

When used with :ARRay, an array of amplitudes is returned. It the tabular display is on, the display is

placed in the list-by-power mode.

Returned values are in the current power units.

Wavelength units are not affected.

<expected_value> MAXimum

Constants The highest power signal

MINimum

The lowest power signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :CONF:ARR:POW

:CONF:SCAL:POW -10 dBm

The following line is an example of a returned string when :CONFigure:SCALar:POWer MAXimum is sent:

-5.88346500E+000

If six laser lines are located and :CONFigure:ARRay:POWer is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query. The measurement units are in dBm.

6,-1.37444400E+001,-1.10996100E+001,-9.62396600E+000, -7.94024500E+000,-7.01303200E+000,-1.04536200E+001

:CONFigure{:ARRay | [:SCALar]} :POWer:FREQuency



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Command :POWer:FREQuency [<expected_value>[,<resolution>]]

Returns frequency values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a frequency that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are Hz.

When used with :ARRay, an array of frequencies is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :CONFigure. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in Hz. Displayed units are shown in THz. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest frequency signal

MINimum

The lowest frequency signal

DEFault

The signal at the current marker position

<resolution> MAXimum

0.01 recolution

Constants 0.01 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples

:CONF:ARR:POW:FREQ DEF, MAX

:CONF:SCAL:POW:FREQ 230.8THZ, MAX

The following line is an example of a returned string when :CONFigure:SCALar:POWer:FREQuency MAXimum is sent:

+1.94055176E+014

If six laser lines are located and :CONFigure:ARRay:POWer:FREQuency is sent, the following string is an example of the returned data. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.93050000E+014,+1.93250900E+014,+1.93452000E+014, +1.93653000E+014,+1.93854100E+014,+1.94055100E+014

:CONFigure{:ARRay | [:SCALar]} :POWer:WAVelength



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Command

:POWer:WAVelength [<expected value>[,<resolution>]]

Returns wavelength values.

Used With <expected_value> <resolution>
SCALar optional optional

ARRay Ignored optional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wavelength that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in meters.

When used with :ARRay, an array of wavelengths is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :CONFigure. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in meters. Displayed units are shown in nanometers. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest wavelength signal

MINimum

The lowest wavelength signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DFFault

Current resolution

Examples

:CONF:ARR:POW:WAV DEF, MAX

:CONF:SCAL:POW:WAV 1300NM, MAX

The following line is an example of a returned string when :CONFigure:SCALar:POWer:WAVelength MAXimum is sent:

+1.5529258E-006

If six laser lines are located and

:CONFigure:ARRay:POWer:WAVelength is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.54488100E-006,+1.54648400E-006,+1.54809000E-006,+1.54969900E-006,+1.55131100E-006,+1.55292600E-006

:CONFigure{:ARRay | [:SCALar]} :POWer:WNUMber



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Command

:POWer:WNUMber [<expected value>[,<resolution>]]

Returns a wave number value.

Used With <expected_value> <resolution>
SCALar optional optional
ARRay Ignored optional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wave number that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in /m.

When used with :ARRay, an array of wave numbers is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :CONFigure. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in inverse meters. Displayed units are shown in inverse centimeters. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The laser line having the largest wave number

MINimum

The laser line having the smallest wave number

DEFault

The signal at the current marker position

<resolution> MAXimum
Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples

:CONF:ARR:POW:WNUM DEF, MAX

:CONF:SCAL:POW:WNUM 6451, MAX

If :CONFigure:SCALar:POWer:WNUMber 6451 is sent, and a 1550 nm laser line is present, the following response would be returned to the computer:

+6.45286262E+005

Notice that the returned units are /m. If six laser lines are measured and :CONFigure:ARRay:POWer:WNUMber is sent, the following response is returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+6. 43945300E+005,+6.44615600E+005,+6.45286300E+005 +6.45957000E+005,+6.46627900E+005,+6.47298400E+005

:FETCh Command

Use the FETCh command to return data from previously performed measurements. However, this command does not initiate the collection of new data. This makes the FETCh command especially useful when characterizing transient data because new data is not collected. Because FETCh does not configure the instrument or acquire new input data, you can use FETCh repeatedly on the same set of acquired data. For example, use two FETCh commands to return wavelength values and then power values for the same measurement as shown in the following program fragment

OUTPUT 720;":INIT:CONT OFF;"
OUTPUT 720;":CONF:ARR:POW MAX"
OUTPUT 720;":INIT:IMM"

OUTPUT 720;":FETC:ARR:POW?"

ENTER 720:powers\$

OUTPUT 720;":FETC:ARR:POW:WAV?"

ENTER 720:wavelengths\$

In the above example, the data in the power and wavelength arrays are returned in the same order so that powers can be matched to wavelengths. You can also send a MEASure command followed by a FETCh command.




FETCh does not reconfigure the display. For example, if the display is in the Peak WL mode, sending :FETCh:ARRay does not configure the display to the Multi-WL mode even though an array of data is returned to the computer.



If no arguments are specified for :FETCh?, the previously specified arguments will be used.

A common programming error occurs when :FETCh is used after an *RST command. This generates error number – 230, "Data corrupt or stale". In this instance, you must send :INITiate:IMMediate after the *RST command and before:FETCh to capture a new array of measurement data.

The FETCh commands have the following hierarchy:



Click/touch any of the following FETCh commands to view more information about the selected command.



The command trees for each of the four basic measurement instructions are identical.

- FETCh{:ARRay | [:SCALar]} :POWer?
- FETCh {:ARRay | [:SCALar]}
 :POWer:WAVelength?
- FETCh {:ARRay | [:SCALar]}
 :POWer:FREQuency?
- FETCh {:ARRay | [:SCALar]}
 :POWer:WNUMber?

:FETCh{:ARRay | [:SCALar]} :POWer?



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Query :POWer? [<expected value>[,<resolution>]]

Returns amplitude values.

Used With <expected_value> <resolution>

SCALar optional optional ARRay Ignored optional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a power level that is closest to the

<expected_value> parameter.

When used with :ARRay, an array of amplitudes is returned. It the tabular display is on, the display is

placed in the list-by-power mode.

Returned values are in the current power units.

Wavelength units are not affected.

<expected_value> MAXimum

Constants The highest power signal

MINimum

The lowest power signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :FETCh:ARR:POW?

:FETCh:SCAL:POW? MIN

Query Response The following line is an example of a returned string

when :FFTCh:SCAL ar:POWer? MAXimum is sent:

-5.88346500E+000

If six laser lines are located and :FETCh:ARRay:POWer? is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query. The measurement units are in dBm.

6,-1.37444400E+001,-1.10996100E+001,-9.62396600E+000, -7.94024500E+000,-7.01303200E+000,-1.04536200E+001

:FETCh{:ARRay | [:SCALar]} :POWer:FREQuency?



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Query :POWer:FREQuency? [<expected_value>[,<resolution>]]

Returns frequency values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a frequency that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are Hz.

When used with :ARRay, an array of frequencies is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :FETCh. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in Hz. Displayed units are shown in THz. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest frequency signal

MINimum

The lowest frequency signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DFFault

Current resolution

Examples :FETCh:ARR:POW:FREQ? DEF, MIN

:FETCh:SCAL:POW:FREQ? 230.8THz, MIN

Query Response The following line is an example of a returned string

when :FETCh:SCALar:POWer:FREQuency? MAXimum is

sent:

+1.94055176E+014

If six laser lines are located and

:FETCh:ARRay:POWer:FREQuency? is sent, the following string is an example of the returned data. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.93050000E+014,+1.93250900E+014,+1.93452000E+014, +1.93653000E+014,+1.93854100E+014,+1.94055100E+014

:FETCh{:ARRay | [:SCALar]} :POWer:WAVelength?



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Query :POWer:WAVelength? [<expected value>[,<resolution>]]

Returns wavelength values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wavelength that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in meters.

When used with :ARRay, an array of wavelengths is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :FETCh. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in meters. Displayed units are shown in nanometers. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest wavelength signal

MINimum

The lowest wavelength signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :FETCh:ARR:POW:WAV? DEF, MIN

:FETCh:SCAL:POW:WAV? 1300NM, MIN

Query Response The following line is an example of a returned string

when :FETCh:SCALar:POWer:WAVelength? MAXimum is

sent:

+1.5529258E-006

If six laser lines are located and

:FETCh:ARRay:POWer:WAVelength? is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.54488100E-006,+1.54648400E-006,+1.54809000E-006,+1.54969900E-006,+1.55131100E-006,+1.55292600E-006

:FETCh{:ARRay | [:SCALar]} :POWer:WNUMber?



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Query :POWer:WNUMber? [<expected value>[,<resolution>]]

in ottomittelinger [temperous_taluer [t

Returns a wave number value.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wave number that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in /m.

When used with :ARRay, an array of wave numbers is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :FETCh. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in inverse meters. Displayed units are shown in inverse centimeters. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The laser line having the largest wave number

MINimum

The laser line having the smallest wave number

DEFault

The signal at the current marker position

 MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :FETCh:ARR:POW:WNUM? DEF, MIN

:FETCh:SCAL:POW:WNUM? 6451, MIN

Query Response If :FETCh:SCALar:POWer:WNUMber? 6451 is sent, and a

1550 nm laser line is present, the following response

would be returned to the computer:

+6.45286262E+005

Notice that the returned units are /m. If six laser lines are measured and :FETCh:ARRay:POWer:WNUMber? is sent, the following response is returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+6. 43945300E+005,+6.44615600E+005,+6.45286300E+005 +6.45957000E+005,+6.46627900E+005,+6.47298400E+005

:MEASure Command

Use MEASure commands to configure the Agilent 86122A, capture new data, and return the data in one operation. For example, to measure the longest wavelength, send the following command:

:MEASure:SCALar:POWer:WAVelength? MAX



A common programming error is to send :MEASure when the instrument is in the continuous measurement acquisition mode. Because :MEASure contains an :INITiate:IMMediate command, which expects the single measurement acquisition mode, an error is generated, and :INITiate is ignored.




MEASure and READ are identical to combining the following commands:

:MEASure :ABORt;:CONFigure;:READ

:ABORt;:INITiate:IMMediate;:FETCh :READ

The MEASure commands have the following hierarchy:



Click/touch any of the following MEASure commands to view more information about the selected command.



The command trees for each of the four basic measurement instructions are identical.

- MEASure{:ARRay | [:SCALar]} :POWer?
- MEASure{:ARRay | [:SCALar]} :POWer:WAVelength?
- MEASure{:ARRay | [:SCALar]} MEASure{:ARRay | [:SCALar]} :POWer:FREQuency? :POWer:WNUMber?

:MEASure{:ARRay | [:SCALar]} :POWer?



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Query :POWer? [<expected_value>[,<resolution>]]

Returns amplitude values.

Used With <expected_value> <resolution>

SCALar optional optional ARRay Ignored optional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a power level that is closest to the

<expected_value> parameter.

When used with :ARRay, an array of amplitudes is returned. It the tabular display is on, the display is

placed in the list-by-power mode.

Returned values are in the current power units.

Wavelength units are not affected.

<expected_value> MAXimum

Constants The highest power signal

MINimum

The lowest power signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :MEAS:ARR:POW?

:MEAS:SCAL:POW? DEF

Query Response The following line is an example of a returned string

when :MFASure:SCAI ar:POWer? MAXimum is sent:

-5.88346500E+000

If six laser lines are located and :MEASure:ARRay:POWer? is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query. The measurement units are in dBm.

6,-1.37444400E+001,-1.10996100E+001,-9.62396600E+000, -7.94024500E+000,-7.01303200E+000,-1.04536200E+001

:MEASure{:ARRay | [:SCALar]} :POWer:FREQuency?



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Query :POWer:FREQuency? [<expected_value>[,<resolution>]]

Returns frequency values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a frequency that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are Hz.

When used with :ARRay, an array of frequencies is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :MEASure. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in Hz. Displayed units are shown in THz. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest frequency signal

MINimum

The lowest frequency signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :MEAS:ARR:POW:FREQ?

:MEAS:SCAL:POW:FREQ? 230.8THZ

Query Response The following line is an example of a returned string

when :MEASure:SCALar:POWer:FREQuency? MAXimum is

sent:

+1.94055176E+014

If six laser lines are located and

:MEASure:ARRay:POWer:FREQuency? is sent, the following string is an example of the returned data. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.93050000E+014,+1.93250900E+014,+1.93452000E+014, +1.93653000E+014,+1.93854100E+014,+1.94055100E+014

:MEASure{:ARRay | [:SCALar]} :POWer:WAVelength?



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Query :POWer:WAVelength? [<expected_value>[,<resolution>]]

Returns wavelength values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wavelength that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in meters.

When used with :ARRay, an array of wavelengths is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :MEASure. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in meters. Displayed units are shown in nanometers. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest wavelength signal

MINimum

The lowest wavelength signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :MEAS:ARR:POW:WAV?

:MEAS:SCAL:POW:WAV? 1300NM

Query Response The following line is an example of a returned string

when :MEASure:SCALar:POWer:WAVelength? MAXimum is

sent:

+1.5529258E-006

If six laser lines are located and

:MEASure:ARRay:POWer:WAVelength? is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.54488100E-006,+1.54648400E-006,+1.54809000E-006,+1.54969900E-006,+1.55131100E-006,+1.55292600E-006

:MEASure{:ARRay | [:SCALar]} :POWer:WNUMber?



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Query :POWer:WNUMber? [<expected_value>[,<resolution>]]

Returns a wave number value.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wave number that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in /m.

When used with :ARRay, an array of wave numbers is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :MEASure. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in inverse meters. Displayed units are shown in inverse centimeters. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The laser line having the largest wave number

MINimum

The laser line having the smallest wave number

DEFault

The signal at the current marker position

<resolution> MAXimum
Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :MEAS:ARR:POW:WNUM?

:MEAS:SCAL:POW:WNUM? 6451

Query Response If :MEASure:SCALar:POWer:WNUMber? 6451 is sent, and a

1550 nm laser line is present, the following response

would be returned to the computer:

+6.45286262E+005

Notice that the returned units are /m. If six laser lines are measured and :MEASure:ARRay:POWer:WNUMber? is sent, the following response is returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+6. 43945300E+005,+6.44615600E+005,+6.45286300E+005 +6.45957000E+005,+6.46627900E+005,+6.47298400E+005

:READ Command

The READ command is similar to the <u>MEASure</u> except that it does not configure the instrument's settings. Use <u>CONFigure</u> to configure the instrument for a particular measurement without returning any data.



MEASure and READ are identical to combining the following commands:

:MEASure :ABORt;:CONFigure;:READ


:READ :ABORt;:INITiate:IMMediate;:FETCh

If no arguments are specified for :READ?, the previous READ or FETCh arguments will be used.



A common programming error is to send :READ when the instrument is in the continuous measurement acquisition mode. Because READ contains an :INITiate:IMMediate command, which expects the single measurement acquisition mode, an error is generated, and :INITiate is ignored.

The READ commands have the following hierarchy:



Click/touch any of the following READ commands to view more information about the selected command.



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

- READ{:ARRay | [:SCALar]} :POWer?
- READ {:ARRay | [:SCALar]}
 :POWer:WAVelength?
- READ {:ARRay | [:SCALar]}
 :POWer:FREQuency?
- READ {:ARRay | [:SCALar]} :POWer:WNUMber?

:READ{:ARRay | [:SCALar]} :POWer?



The command trees for each of the four basic <u>measurement</u> <u>instructions</u> are identical.

Query :POWer? [<expected_value>[,<resolution>]]

Returns amplitude values.

Used With <expected_value> <resolution>

SCALar optional optional ARRay Ignored optional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a power level that is closest to the

<expected_value> parameter.

When used with :ARRay, an array of amplitudes is returned. It the tabular display is on, the display is

placed in the list-by-power mode.

Returned values are in the current power units.

Wavelength units are not affected.

<expected_value> MAXimum

Constants The highest power signal

MINimum

The lowest power signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :READ:ARR:POW?

:READ:SCAL:POW? MIN

Query Response The following line is an example of a returned string

when :READ:SCALar:POWer? MAXimum is sent:

-5.88346500E+000

If six laser lines are located and :READ:ARRay:POWer? is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query. The measurement units are in dBm.

6,-1.37444400E+001,-1.10996100E+001,-9.62396600E+000, -7.94024500E+000,-7.01303200E+000,-1.04536200E+001

:READ{:ARRay | [:SCALar]} :POWer:FREQuency?



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Query :POWer:FREQuency? [<expected value>[,<resolution>]]

Returns frequency values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a frequency that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are Hz.

When used with :ARRay, an array of frequencies is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :READ. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in Hz. Displayed units are shown in THz. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest frequency signal

MINimum

The lowest frequency signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :READ:ARR:POW:FREQ?

:READ:SCAL:POW:FREQ? 230.8THZ

Query Response The following line is an example of a returned string

when :READ:SCALar:POWer:FREQuency? MAXimum is sent:

+1.94055176E+014

If six laser lines are located and

:READ:ARRay:POWer:FREQuency? is sent, the following string is an example of the returned data. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.93050000E+014,+1.93250900E+014,+1.93452000E+014, +1.93653000E+014,+1.93854100E+014,+1.94055100E+014

:READ{:ARRay | [:SCALar]} :POWer:WAVelength?



The command trees for each of the four basic <u>measurement instructions</u> are identical.

Query :POWer:WAVelength? [<expected_value>[,<resolution>]]

Returns wavelength values.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wavelength that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in meters.

When used with :ARRay, an array of wavelengths is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :READ. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in meters. Displayed units are shown in nanometers. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The highest wavelength signal

MINimum

The lowest wavelength signal

DEFault

The signal at the current marker position

<resolution> MAXimum

Constants 0.01 resolution

EXTended1

0.0001 resolution

DFFault

Current resolution

Examples :READ:ARR:POW:WAV?

:READ:SCAL:POW:WAV? 1300NM

Query Response The following line is an example of a returned string

when :READ:SCALar:POWer:WAVelength? MAXimum is sent:

+1.5529258E-006

If six laser lines are located and

:READ:ARRay:POWer:WAVelength? is sent, the following string could be returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+1.54488100E-006,+1.54648400E-006,+1.54809000E-006,+1.54969900E-006,+1.55131100E-006,+1.55292600E-006

:READ{:ARRay | [:SCALar]} :POWer:WNUMber?



The command trees for each of the four basic <u>measurement</u> instructions are identical.

Query

:POWer:WNUMber? [<expected value>[,<resolution>]]

Returns a wave number value.

Used With<expected_value><resolution>SCALaroptionaloptionalARRayIgnoredoptional

When used with :SCALar, a single value is returned. If the tabular display is on, the display is placed in the single-wavelength mode. The marker is then placed on the signal having a wave number that is closest to the <expected_value> parameter. Default units for the <expected_value> parameter are in /m.

When used with :ARRay, an array of wave numbers is returned. It the tabular display is on, the display is placed in the list-by-wavelength mode.

The <resolution> parameter sets the number of points for :CALCulate1:TRANsforn:FREQuency:POINts. This parameter provides backwards compatiblity with previous instruments. It does not affect the resolution or speed of :READ. This parameter is a unitless number whose value will be limited to either 0.01, 0.001, or 0.0001.

Returned values are in inverse meters. Displayed units are shown in inverse centimeters. Power units are not affected.



When using :ARRay, the <expected_value> is ignored. However, this argument must be present if the resolution argument is specified.

You can use DEF to specify the default value.

<expected_value> MAXimum

Constants The laser line having the largest wave number

MINimum

The laser line having the smallest wave number

DEFault

The signal at the current marker position

<resolution> MAXimum
Constants 0.01 resolution

MINimum

0.001 resolution

EXTended1

0.0001 resolution

DEFault

Current resolution

Examples :READ:ARR:POW:WNUM?

:READ:SCAL:POW:WNUM? 6451

Query Response If :READ:SCALar:POWer:WNUMber? 6451 is sent, and a

1550 nm laser line is present, the following response

would be returned to the computer:

+6.45286262E+005

Notice that the returned units are /m. If six laser lines are measured and :READ:ARRay:POWer:WNUMber? is sent, the following response is returned. Notice that the first returned number indicates the number of laser-line values returned in the query.

6,+6. 43945300E+005,+6.44615600E+005,+6.45286300E+005 +6.45957000E+005,+6.46627900E+005,+6.47298400E+005

Common Commands

Use common commands to control general device functions that are common among many different types of instruments. Common commands are defined by the IEEE 488.2 standard. They control functions that are common to all IEEE 488.2 instruments. Common commands can be received and processed by the instrument, whether they are sent over the GPIB as separate program messages or within other program messages.

These commands include

*CLS	• *RCL	● <u>*STB?</u>
------	--------	----------------

● <u>*IDN?</u>	● <u>*SRE</u>	• <u>*WAI</u>
----------------	---------------	---------------

● <u>*OPC</u>

*CLS - Clear Status

Command *CLS

Clears the instrument status byte by emptying the error queue and clearing all event registers. This command does not alter the instrument settings. After the *CLS command, the instrument is left in the idle state. This command also cancels any preceding *OPC command or query.

*CLS cannot be issued as a query.

Back to top

*ESE - Event Status Enable

Command *ESE <integer>

Sets the bits in the event status enable register.

<integer> A mask value from 0 to 255.

Example The following example sets ESB (event summary bit) bit 5

of the event status enable register. Therefore, when an incorrect programming command is received, the CME (command error bit) in the status byte register is set.

OUTPUT 720:"*ESE 32"

See <u>Status Enable Register</u> for more information about event status enable register bits.

Back to top

*ESR? - Event Status Register Query

Query *ESR?

Returns the value of the event status register. When you read the standard event status register, the value returned is the total of the bit weights of all of the bits that are set to

one (1) at the time you read the byte.

Example OUTPUT 720;"*ESR?"

ENTER 720; Event PRINT Event

See Status Enable Register for more information about

event status enable register bits.

Back to top

*IDN? - Indentification Number Query

Query *IDN?

Returns a string that uniquely identifies the instrument.

The string is in the form of

Agilent Technologies,86122A,<serial number>,<software revision>

This query must be the last query in a program message.

Any queries after *IDN? are ignored.

The maximum length of the identification string is 50 bytes.

Example DIM Id\$[50]

OUTPUT 720;"*IDN?"

ENTER 720;Id\$
PRINT Id\$

Back to top

*OPC - Operation Complete

Command *OPC

Sets the operation complete bit in the event status register when all pending device operations have finished.

This command is useful when the computer is sending commands to other instruments. The computer can poll

the event status register to check when the

Agilent 86122A has completed the operation.

Query *OPC?

Places an ASCII "1" in the output queue when all pending device operations have finished.

Use *OPC? query to ensure all operations have completed before continuing the program. By following a command with *OPC? and an ENTER statement, the program will pause until the response (ASCII "1") is returned by the instrument.

Be sure the computer's timeout limit is at least two seconds, since some of the Agilent 86122A commands take approximately one second to complete.

Example OUTPUT 720;"*OPC?"

ENTER 720;Op\$

Back to top

*RCL - Recall

Command *RCL <integer>

Recalls a saved instrument state. This command is

backward compatible with the 86120B/C.

For a more general save/recall function, see :MMEMory:LOAD

and $\underline{: MMEMory : STORe}.$

<integer> A n

A number from 1 to 4.

Back to top

*RST - Reset

Command *RST

Returns the Agilent 86122A to a known condition.

See <u>Instrument Preset Conditions</u> for a list of reset

conditions.

This command places the instrument in single measurement acquisition mode. Therefore, any current data is marked as invalid and a measurement query results in an error. For example, :FETCh? results in error number – 230, "Data corrupt or stale". You must then initiate a new sweep with :INITiate:IMMediate before you can use :FETCh.

Back to top

*SAV - Save

Command *SAV <integer>

Stores the current state of the instrument in a save

register.

<integer> A number from 1 to 4.

Back to top

*SRE - Service Request Enable

Command *SRE <integer>

Sets the bits in the service request enable register.

<integer> A mask value from 0 to 63 or from 128 to 191.

See Status Event Enable Register for more information

about service request enable register bits.

Query *SRE?

Example The following example enables ESB (event summary) bit 5

in the status byte register to generate a service request.

OUTPUT 720;"*SRE 32"

ENTER 720;Op\$

Back to top

*STB? - Status Byte

Query *STB? <integer>

Returns the current value of the status byte register.

The master summary status (MSS) bit 6 indicates whether or not the device has at least one reason for requesting service. When you read the status byte register, the value returned is the total of the bit weights of all of the bits set to one at the time you read the byte. *STB? does not affect the

contents of the status byte register.

See Status Byte Register for more information about each

bit in the status byte register.

<integer> A number from 0 to 255.

Example OUTPUT 720;"*STB?"

ENTER 720; Value PRINT Value

Back to top

*TRG - Trigger

Command *TRG

Acquires data according to the current settings. If a measurement is already in progress, a trigger is ignored,

and an error is generated.

Example The following example starts the data acquisition according

to the current settings.

OUTPUT 720;"*TRG"



Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential Commands, click/touch



Back to top

*TST? - Test

Query *TST?

Starts a a self-test on the instrument. The result of the test is placed in the output queue. A zero indicates the test passed and a non-zero value indicates the test failed. The instrument will initiate a measurement and check for any hardware errors after the measurement is complete.

Example OUTPUT 720;"*TST?"

ENTER 720; Result
PRINT Result

Back to top

*WAI - Wait

Command *WAI

Prevents the instrument from executing any further commands until the current command and all pending

commands have completed.

Back to top

Subsystem Commands

Use subsystem commands to control specific device functions.

Click/touch any of the subsystems to view more information about the selected subsystem and its associated commands.

CALCulate1

CALCulate2

CALCulate3

DISPlay

HCOPy

MMEMory

SENSe

STATus


SYSTem

TRIGger

UNIT UNIT

:CALCulate1 Subsystem

Use CALCulate1 commands to query *uncorrected* frequency-spectrum data. The measurement update returns 30,093 values. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following CALCulate1 commands to view more information about the selected command.

- <u>DATA?</u>
- TRANsform:FREQuency:Points

:CALCulate1:DATA?

Query :CALCulate1:DATA?

Queries uncorrected frequency-spectrum data of the input

laser line.

Attribute Preset State: not affected

Summary SCPI Compliance: instrument specific

Query Only

Query Response The returned values are proportional to squared Watts (linear) units. No amplitude or frequency correction is applied to the values. To obtain the logarithmic (dB) result, normalize the returned values by the largest value, then take five times the logarithm of the normalized values.

Be prepared to process a large amount of data when this query is sent. The amount of data returned can be set using CALCulate1:TRANsform:FREQuency:POINts or the resolution argument of a configure measurement

instrument function. The following floating point values can

be returned:

Mode	Number of Points	Frequency Spacing	Start Frequency	Stop Frequency
MINimum	7525	7.226756134 GHz	181.6878 THz	236.061989 THz
MAXimum	15047	3.6133378067 GHz	181.691489 THz	236.058375 THz
EXTended1	30093	1.806689033 GHz	181.691489 THz	236.058375 THz

The following string is a typical example of the first few returned values:

+4.02646500E+001,+6.78125100E+001,+6.17986600E+001,+4.26768200E+001,+4.8 0245300E+001,+3.1

0491300E+001,+1.13409400E+001,+5.07832500E+001,+2.77746200E+001,+3.89150 500E+001.+3.50217 600E+001.+7.34649800E-001.+5.64983800E+000.

Notice that only measurement values are returned to the computer. There is no first value that indicates the number of values contained in the string as there is, for example, with the :FETCh, :READ, and :MEASure.

Use:CALCulate1:TRANsform:FREQuency:POINTs? to query the number of points :CALC1:DATA? returns.



If your program is aborted or interrupted after sending this query, the Agilent 86122A continues to process the data but does not place it in the output buffer. Because of the amount of data processed, the instrument *will not respond* to any new commands in its input buffer for up to 20 seconds.



This query will generate a "Settings Conflict" error if the instrument is in the signal-to-noise application, with averaging turned on.

:CALCulate1:TRANsform:FREQuency:POINts

Command :CALCulate1:TRANsform:FREQuency:POINts{?] {<integer> | MINimum

| MAXimum | EXTended1}}

Sets the size of the Fast Fourier transform (FFT)

performed by the instrument.

<integer> Sets FFT size. Must be either 30,093, 15,047 or 7,525.

Other values result in an error.

MINimum: 7,525 MAXimum: 15,047 EXTended1: 30,093

A MAXimum data points mode corresponds to an FFT size of 15,047. A MINimum data points mode corresponds to an FFT size of 7,525. The EXTended1 mode corresponds to an FFT size of 30,093. These values are a subset of the

uncorrected-data buffer described in Remote

Measurements. Changing the number of points causes the

instrument to reprocess the current set of data.



These settings are for backward compatibility to the 86120 family and no longer affect the accuracy, resolution or update rate of the instrument.

Attribute Non-sequential command

Summary Preset State: array size set to 15,047

*RST State: 15.047

SCPI Compliance: instrument specific

Query Response Returns the number of points in the data set. This is the number of measurement points that will be returned by

CALCulate1:DATA?.


MINimum: +7,525 MAXimum: +15,047 EXTended1: +30,093





:CALCulate2 Subsystem

Use CALCulate2 commands to query *corrected* values for frequency-spectrum data. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following CALCulate2 commands to view more information about the selected command.

- <u>DATA?</u>
- PEXCursion
- POINts?
- PTHReshold:ABSolute
- PTHReshold:MODe
- <u>PTHReshold[:RELative]</u>
- <u>PWAVerage[:STATe]</u>

- WLIMit:STARt:FREQuency
- WLIMit:STARt[:WAVelength]
- WLIMit:STARt:WNUMber
- WLIMit[:STATe]
- WLIMit:STOP:FREQuency
- WLIMit:STOP[:WAVelength]
- WLIMit:STOP:WNUMber

:CALCulate2:DATA?

Query :CALCulate2:DATA? {FREQuency | POWer | WAVelength | WNUMber}

Queries the corrected peak data of the input laser line.

Constant FREQuency

Queries the array of laser-line frequencies after the peak search is completed. If :CALCulate2:PWAVelength:STATe is on, the power-weighted average frequency is returned.

POWer

Queries the array of laser-line powers after the peak search is completed. If :CALCulate2:PWAVelength:STATe is on, the total input power is returned.

WAVelength

Queries the array of laser-line wavelengths after the peak search is completed. If :CALCulate2:PWAVelength:STATe is on, the power-weighted average wavelength is returned.

WNUMber

Queries the array of laser-line wave numbers after the peak search is completed. If :CALCulate2:PWAVelength:STATe is on, the power-weighted average wave number is returned.

Attribute Summary

Preset State: not affected SCPI Compliance: standard

Query Only

Use <u>CALCulate2:POINts?</u> to determine the number of points CALCulate2:DATA? will return. The following string is a typical example of the first few returned values when WAVelength is specified:

+1.54488600E-006,+1.54649100E-006,+1.54808300E-006,+1.54969600E-006,+1.55131200E-006,+1.55293000E-006

This next string resulted by specifying the WNUMber argument:

+6.47296600E+005,+6.46625000E+005,+6.45959900E+0
05,+6.45287500E+005,+6.44615500E+005,+6.4
3943900E+005

Notice that only measurement values are returned to the computer. There is no first value that indicates the number of values contained in the string as there is, for example, with :FETCh, :READ, and :MEASure.

When there is no input signal, :POWer? returns –200 dBm; and :WAVelength? returns 100 nm.



The value for WAVelength? is corrected for temperature and pressure, and for air or vaccum.

:CALCulate2:PEXCursion

Command :CALCulate2:PEXCursion{?| {<integer> | MINimum | MAXimum |

DEFault}}

Sets the peak excursion limit used by the instrument to determine valid laser line peaks. A laser line is identified as a valid peak if its amplitude is greater than the peak excursion plus the amplitudes of the closest local minima on either side of the peak. This command works in conjunction with the peak threshold setting. Changing the peak excursion limit causes the instrument to reprocess

the current set of data.

<integer> Represents logarithmic value in dB. Valid range is 1 - 30

dB.

Constant MINimum: 1 dB

MAXimum: 30 dB DEFault: 15 dB

Attribute Non-sequential command

Summary Preset State: 15 dB *RST State: 15 dB

SCPI Compliance: instrument specific

Query Returns the current value of the peak excursion limit. For Response example, if the current value is set to 15 dB, then **15** is

example, if the current value is set to 15 dB, then **15** is returned.

returned





:CALCulate2:POINts?

Query :CALCulate2:POINts?

Queries the number of points in the data set. This is the number of points that will be returned by <u>CALCulate2:DATA?</u>.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

Query Returns the number of points in the data set. For example,

Response if six laser lines are located, the value **+6** is returned.

:CALCulate2:PTHReshold:ABSolute

Command

:CALCulate2:PTHReshold:ABSolute {?| {<real> | <power units suffix>} | MINimum | MAXimum | DEFault}}

Sets the peak threshold limit used by the instrument to determine valid laser line peaks. When in Absolute peak threshold mode, a laser line is identified as a valid peak if its amplitude is above the absolute peak threshold value in the units specified by the <u>UNIT:POWer</u> command. If a units suffix is included, the units suffix will take precedence over that specified by UNIT:POWer.

This setting works in conjunction with the peak excursion setting to determine which responses are valid peaks. Changing the peak threshold limit causes the instrument to reprocess the current set of data.

<real> Represents power units in dBm. Valid range is - 40 to 0.

Value is in dBm or W, and can include a multiplier.

<power units
suffix>

WIIIA

Constant MINimum: -40 dBm

MAXimum: 10 dBm DEFault: -20 dBm

Attribute Non-sequential command Summary Preset State: -20 dBm

*RST State: -20 dBm

SCPI Compliance: instrument specific

Query Response Returns the current peak threshold value in units specified by UNIT:POWer, or by the power units suffix. For example, if the current value is set to -15 dBm and:UNIT:POWer is set to

dBm, then **-15** is returned.





:CALCulate2:PTHReshold:MODe

Command :CALCulate2:PTHReshold:MODe{?| {RELative | ABSolute}}

Sets the peak threshold mode of the instrument. If RELative is selected, then the peak threshold value is treated as a relative number in dB. If absolute is selected, then the peak threshold value is treated as an absolute power in

dBm. See PTHReshold[:RELative] or

PTHReshold: ABSolute for more information.

Attribute Non-sequential command Summary Preset State: RELative

*RST State: RELative

SCPI Compliance: instrument specific

Query Response Returns the current peak threshold mode.





:CALCulate2:PTHReshold[:RELative]

Command :CALCulate2:PTHReshold[:RELative] {?| {<integer> | MINimum |

MAXimum | DEFault}}

Sets the peak threshold limit used by the instrument to determine valid laser line peaks.

When in Relative (default) peak threshold mode, a laser line is identified as a valid peak if its amplitude is above the maximum amplitude minus the peak threshold value.

This subtraction is performed in dB.

This setting works in conjunction with the peak excursion setting to determine which responses are located.

Changing the peak threshold limit causes the instrument to

reprocess the current set of data.

<integer> Represents logarithmic value in dB. Valid range is 0 to 40.

Constant MINimum: 0 dB

MAXimum: 40 dB DEFault: 10 dB

Attribute Non-sequential command

Summary Preset State: 10 dB *RST State: 10 dB

SCPI Compliance: instrument specific

Query Returns the current peak threshold value in dB. For example, if the current value is set to 15 dB, then **15** is

returned.





:CALCulate2:PWAVerage[:STATe]

Command :CALCulate2:PWAVerage[:STATe]{?| {ON | OFF | 1 | 0}}

Places the instrument in the power-weighted average

mode.

When the state is on, CALCulate2:DATA? POWer returns the total power and CALCulate2:DATA? WAVelength, FREQuency, or WNUMber returns the power-weighted average wavelength,

frequency, or wave number values.

Turning power-weighted average mode on while making delta, Fabry-Perot, or signal-to-noise measurements

results in a "-221 Settings Conflict" error.

Attribute Preset State: off Summary *RST State: off

:CALCulate2:WLIMit:STARt:FREQuency

Command :CALCulate2:WLIMit:STARt:FREQuency {?|{<real> | MINimum |

MAXimum }}

Sets the start frequency for the wavelength limit range.

<real> Frequency value within the following limits:

MINimum: 181.6924 THz (1650 nm) MAXimum: frequency limit stop value

The default units are Hz. The start frequency value must be less than or equal to the stop frequency value or the start frequency will be set to the stop frequency and a

"Data out of range" error will be generated.

Attribute Non-sequential command
Summary Preset State: 181.6924 THz
*RST State: 181.6924 THz

SCPI Compliance: instrument specific





:CALCulate2:WLIMit:STARt[:WAVelength]

Command :CALCulate2:WLIMit:STARt[:WAVelength] {?|{<real> | MINimum |

MAXimum}}

Sets the start wavelength for the wavelength limit range.

<real> Wavelength value within the following limits:

MINimum: 1270 nm

MAXimum: wavelength limit stop value

The default units are meters. The start wavelength value must be less than or equal to the stop wavelength value or the start wavelength will be set to the stop wavelength and a "Data out of range" error will be generated. Setting the

start wavelength is equivalent to setting the stop frequency/wave number because of the inverse

relationship of frequency to wavelength.

Attribute Non-sequential command Summary Preset State: 1270 nm

*RST State: 1270 nm

SCPI Compliance: instrument specific





:CALCulate2:WLIMit:STARt:WNUMber

Command :CALCulate2:WLIMit:STARt:WNUMber {?]{<real> | MINimum |

MAXimum}}

Sets the start wave number for the wavelength limit range.

<real> Wave number value within the following limits:

MINimum: 6060 /cm (1650 nm)

MAXimum: wave number limit stop value

The default units are inverse meters. The start wave number value must be less than or equal to the stop wave number value or the start wave number will be set to the stop wave number and a "Data out of range" error will be

generated.

Attribute Non-sequential command Summary Preset State: 6.060606E5 /m

*RST State: 6.060606E5 /m

SCPI Compliance: instrument specific





:CALCulate2:WLIMit[:STATe]

Command :CALCulate2:WLIMit[:STATe]{?| {ON | OFF | 1 | 0}}

Turns wavelength limiting on and off. When this function is on, the instrument has an input range from WLIMit STARt to

WLIMit STOP values. When this function is off, the

instrument displays peaks over the full wavelength range. The graphics display always shows the range between WLIMit:STARt and WLIMit:STOP, regardless of the state of this

command.

When the instrument receives this command, it

reprocesses the data and performs a new peak search.

Attribute Non-sequential command Summary Preset State: on

Preset State: on *RST State: on

SCPI Compliance: instrument specific





:CALCulate2:WLIMit:STOP:FREQuency

Command :CALCulate2:WLIMit:STOP:FREQuency {?|{<real> | MINimum |

MAXimum }}

Sets the stop frequency for the wavelength limit range.

<real> Frequency value within the following limits:

MINimum: start wavelength limit MAXimum: 236.0571 THz (1270 nm)

The default units are Hz. The stop frequency value must be greater than or equal to the start frequency value or the stop frequency will be set to the start frequency and a

"Data out of range" error will be generated.

Attribute Non-sequential command
Summary Preset State: 236.0571 THz
*RST State: 236.0571 THz

SCPI Compliance: instrument specific





:CALCulate2:WLIMit:STOP[:WAVelength]

Command :CALCulate2:WLIMit:STOP[:WAVelength] {?|{<real> | MINimum |

MAXimum }}

Sets the stop wavelength for the wavelength limit range.

<real> Wavelength value within the following limits:

MINimum: start wavelength limit

MAXimum: 1650.0 nm

The default units are meters. The stop wavelength value must be greater than or equal to the start wavelength value or the stop wavelength will be set to the start wavelength and a "Data out of range" error will be generated. Setting the stop wavelength is equivalent to setting the start frequency/wave number because of the inverse relationship of frequency to wavelength.

Non-sequential command

Preset State: 1650 nm *RST State: 1650nm

SCPI Compliance: instrument specific

9

Attribute

Summary



:CALCulate2:WLIMit:STOP:WNUMber

Command :CALCulate2:WLIMit:STOP:WNUMber {?|{<real> | MINimum |

MAXimum }}

Sets the stop wave number for the wavelength limit range.

<real> Wave number value within the following limits:

MINimum: start wavelength limit MAXimum: 7874 /cm (1270 nm)

The default units are inverse meters. The stop wave number value must be less than or equal to the start wave number value or the stop wave number will be set to the start wave number and a "Data out of range" error will be

generated.

Attribute Non-sequential command
Summary Preset State: 7.87401E5 /m
*RST State: 7.87401E5 /m

SCPI Compliance: instrument specific




Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential

Commands, click/touch



:CALCulate3 Subsystem

Use the CALCulate3 commands to perform delta, drift, signal-to-noise, and Fabry-Perot measurements. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following CALCulate3 commands to view more information about the selected command.

- ASNR:CLEar
- ASNR:COUNt
- ASNR[:STATe]
- <u>DATA?</u>
- DELTa:POWer[:STATe]
- DELTa:PRESet
- DELTa:REFerence:FREQuency
- DELTa:REFerence:POWer?

- DRIFt:REFerence:RESet
- DRIFt:REFerence[:STATe]
- FPERot[:STATe]
- FPERot:FWHM?
- FPERot:MEAN?
- FPERot:MODE:SPACing?
- FPERot:PEAK?
- FPERot:POWer?

- DELTa:REFerence[:WAVelength]
- DELTa:REFerence:WNUMber
- DELTa:WAVelength[:STATe]
- DELTa:WPOWer[:STATe]
- DRIFt:DIFFerence[:STATe]
- <u>DRIFt:MAXimum[:STATe]</u>
- DRIFt:MINimum[:STATe]
- DRIFt:PRESet
- DRIFt[:STATe]

- FPERot:SIGMa?
- POINts?
- PRESet
- SNR:AUTO
- SNR:REFerence:FREQuency
- SNR:REFerence[:WAVelength]
- SNR:REFerence:WNUMber
- SNR[:STATe]



To select a delta, drift, or signal-to-noise measurement, see Measuring Delta, Drift, and SNR.

:CALCulate3:ASNR:CLEar

Command :CALCulate3:ASNR:CLEar

Clears the number of measurements used in the average signal-to-noise calculation. The current measurement is used as the new reference for the average signal-to-noise

calculation.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

:CALCulate3:ASNR:COUNt

Command :CALCulate3:ASNR:COUNt {?|{<integer> | MINimum | MAXimum }}

Sets the number of measurements to be used for the average signal-to-noise calculation. If this count is changed while the average signal calculation is on, and the new count is less than the number of measurements

already taken, the instrument will go into single

measurement mode.

<integer> Value within the following limits:

MINimum: 10 MAXimum: 900

Attribute Preset State: 100 Summary *RST State: 100

SCPI Compliance: instrument specific

:CALCulate3:ASNR[:STATe]

Command :CALCulate3:ASNR[:STATe] {?|{ ON | OFF | 1 | 0 }}

Turns the average signal-to-noise ratio on or off. Only one of the :CALCulate3 calculations (ASNR, DELTa, DRIFt, or SNR) can be turned on at a time. Turning on the ASNR calculation while another calculation is on will generate a "Settings Conflict" error.

When the calculation is first turned on, the lines measured in the current measurement will be used as the reference values for the signal-to-noise ratio. Subsequent measurements will average the noise values. The signal values are not updated until the number of measurements used to average the noise is greater than or equal to the COUNt value.



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time results in a "-221 Settings Conflict" error.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

:CALCulate3:DATA?

Query :CALCulate3:DATA? {POWer | FREQuency | WAVelength | WNUMber |

DROPped}

Queries the data resulting from delta, drift, data logging,

and signal-to-noise measurements.

Argument POWer

Queries the array of laser-line powers after the calculation

is completed.

FREQuency

Queries the array of laser-line frequencies after the

calculation is completed.

WAVelength

Queries the array of laser-line wavelengths after the

calculation is completed.

WNUMber

Queries the array of laser-line wave numbers after the

calculation is completed.

DROPped

This applies only to the drift application. This query returns an array of values corresponding to the peaks in the reference sweep. The value for each element in the array will be

- 0 if there have been no drops on the peak
- 1 if the peak is currently below the peak threshold
- 2 if the peak previously dropped and is currently above the peak threshold.

Attribute Summary

Preset State: not affected *RST State: not affected

Query Only

The data returned by the query depends upon which calculation state is on. An error is generated if no calculation state is on. The returned data is comma

delimited.

In the SNR or ASNR calculation, only the POWer argument is valid. The other arguments will generate a "Settings Conflict" error. Use CALCulate2:DATA? to retrieve the signal wavelengths and powers.

Query Response The following string is a typical example of six values returned when POWer is specified from a delta power measurement:

-7.42833100E+000,-1.00087200E+000,-

2.52121400E+000,

-3.41918900E+000,-3.80437200E+000,-

6.36282900E+000

Notice that only measurement values are returned to the computer. There is no first value that indicates the number of values contained in the string as there is, for example, with FETCh, READ, and MEASure commands. Use CALCulate3:POINts? to determine the number of points CALCulate3:DATA? returns.

:CALCulate3:DELTa:POWer[:STATe]

Command :CALCulate3:DELTa:POWer[:STATe]{?| {ON | OFF | 1 | 0}}

Turns the delta-power measurement mode on and off. When this state is on, the power value of the reference laser line is subtracted from the power values of all laser lines except the reference. The power of the reference laser line is returned as an absolute power (unnormalized).

The frequency data returned is the array of absolute

frequency values.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

results in a "-221 Settings Conflict" error.

:CALCulate3:DELTa:PRESet

Command :CALCulate3:DELTa:PRESet

Turns off all delta measurement states.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Command Only

:CALCulate3:DELTa:REFerence:FREQuency

Command :CALCulate3:DELTa:REFerence:FREQuency{?| {<real> | MINimum |

MAXimum}}

Selects the reference laser line for DELTa calculations. The reference will be the laser line at the frequency closest to the frequency entered. Subsequent measurements will use the frequency closest to the reference frequency used

for the previous measurement.

<real> Frequency value within the following limits:

MINimum: 181.6924 THz MAXimum: 236.0571 THz

Attribute Preset State: 236.0571 THz (1270 nm) Summary *RST State: 236.0571 THz (1270 nm)

SCPI Compliance: instrument specific

Query The query returns the reference laser line frequency. The

Response default units are Hz.

:CALCulate3:DELTa:REFerence:POWer?

Query :CALCulate3:DELTa:REFerence:POWer?

Queries the reference laser line's power level.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

:CALCulate3:DELTa:REFerence[:WAVelength]

Command :CALCulate3:DELTa:REFerence[:WAVelength]{?| {<real> | MINimum |

MAXimum}}

Selects the reference laser line for DELTa calculations. The reference will be the laser line at the wavelength closest to the wavelength entered. Subsequent measurements will use the wavelength closest to the reference wavelength

used for the previous measurement.

<real> Wavelength value within the following limits:

MINimum: 1270 nm MAXimum: 1650 nm

Attribute Preset State: 1270 nm (236.0571 THz)

Summary *RST State: 1270 nm (236.0571 THz) laser line

SCPI Compliance: instrument specific

Query The query returns the current wavelength of the reference

Response laser line. The default units are meters.

:CALCulate3:DELTa:REFerence:WNUMber

:CALCulate3:DELTa:REFerence:WNUMber{?| {<real> | MINimum | Command

MAXimum}}

Selects the reference laser line for delta calculations. The reference will be the laser line at the wave number closest to the wave number entered. Subsequent measurements will use the wave number closest to the reference wave

number used for the previous measurement.

<real> Wave number value within the following limits:

> MINimum: 6,060 /cm (1650 nm) MAXimum: 7,824 /cm (1270 nm)

Attribute Preset State: 7,824 /cm (1270 nm) Summary *RST State: 7,824 /cm (1270 nm)

SCPI Compliance: instrument specific

Query The query returns the current wave number of the Response

reference laser line. The default units are /m.

:CALCulate3:DELTa:WAVelength[:STATe]

Command :CALCulate3:DELTa:WAVelength[:STATe]{?| {ON | OFF | 1 | 0}}

Turns the delta wavelength measurement mode on and off. When turned on, the wavelength of the reference laser line is subtracted from the wavelength values of all laser

lines except the reference.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query When this command is set to on, the power data returned Response from CALCulate3:DATA? is the array of absolute powers

measured for each laser line, the frequency data is the array of frequency values normalized to the frequency of the reference laser line, and the frequency of the reference

laser line is returned as an absolute frequency

(unnormalized).



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:CALCulate3:DELTa:WPOWer[:STATe]

Command

Turns the delta wavelength and power measurement mode on and off. When turned on, the wavelength of the reference laser line is subtracted from the wavelength values of all laser lines except the reference. The power value of the reference is subtracted from the power values of all laser lines except the reference.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query Response When this command is set to on, the power data returned from CALCulate3:DATA? is the array of powers normalized to the power of the reference laser line, the power of the reference laser line is returned as an absolute power (unnormalized), the frequency data is the array of frequency values normalized to the frequency of the reference laser line, and the frequency of the reference laser line is returned as an absolute frequency (unnormalized).



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time results in a "-221 Settings Conflict" error.

:CALCulate3:DRIFt:DIFFerence[:STATe]

Command :CALCulate3:DRIFt:DIFFerence[:STATe]{?| {ON | OFF | 1 | 0}}

Sets the drift calculation to subtract the minimum values

measured from the maximum values measured.

Use :CALCulate3:DRIFt:PRESet to turn off all the drift states

before turning on this state.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query When this command is set to on, CALCulate3:DATA? returns Response the maximum power, frequency, or wavelength minus the

minimum power, frequency, or wavelength.



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:CALCulate3:DRIFt:MAXimum[:STATe]

Command :CALCulate3:DRIFt:MAXimum[:STATe]{?| {ON | OFF | 1 | 0}}

Sets the drift calculation to return the maximum power,

frequency, and wavelength values measured.

Use :CALCulate3:DRIFt:PRESet to turn off all the drift states

before turning on this state.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query When this command is set to on, CALCulate3:DATA? returns

Response the maximum power, frequency, or wavelength.



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:CALCulate3:DRIFt:MINimum[:STATe]

 $\textbf{Command} \qquad : CALCulate 3: DRIFt: MINimum [:STATe] \cite{Converse of the converse of the co$

Sets the drift calculation to return the minimum power,

frequency, and wavelength values measured.

Use :CALCulate3:DRIFt:PRESet to turn off all the drift states

before turning on this state.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query When this command is set to on, CALCulate3:DATA? returns

Response the minimum power, frequency, or wavelength.



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time results in a "-221 Settings Conflict" error.

:CALCulate3:DRIFt:PRESet

Command :CALCulate3:DRIFt:PRESet

Turns off all the drift states for DIFFerence, MAXimum,

MINimum, and REFerence.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Command Only



When this command is set to on, the query CALCulate3:DATA? returns the difference between the current measurement and the reference.

:CALCulate3:DRIFt:REFerence:RESet

Command :CALCulate3:DRIFt:REFerence:RESet

Places the current list of laser lines into the reference list.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

:CALCulate3:DRIFt:REFerence[:STATe]

:CALCulate3:DRIFt:REFerence[:STATe]{?| {ON | OFF | 1 | 0}} Command

Turns on and off the drift reference state.

Use :CALCulate3:DRIFt:PRESet to turn off all the drift states

before turning on the drift reference state.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query When this command is set to on, :CALCulate3:DATA? returns

Response the reference laser lines.



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:CALCulate3:DRIFt[:STATe]

Command :CALCulate3:DRIFt[:STATe]{?| {ON | OFF | 1 | 0}}

Turns on and off the drift measurement calculation.

When the drift mode is first turned on, the current list of laser lines is placed into the reference. All subsequent measurements take the new data, subtract the reference data, and display the differences in wavelengths and

powers.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific

Query When this command is set to on, CALCulate3:DATA? returns Response the power and frequency of the current measurement

minus the power and frequency of the reference.



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:CALCulate3:FPERot[:STATe]

Command :CALCulate3:FPERot[:STATE] {? | {ON | OFF | 1 | 0}}

Turns on and off the Fabry-Perot measurement mode.

When the state is ON, the Agilent 86122A measures characteristics of the Fabry-Perot laser modes. The modes are defined by the peak excursion and peak threshold

commands.

Attribute Preset State: off Summary *RST State: off

SCPI Compliance: instrument specific



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:CALCulate3:FPERot:FWHM?

Query :CALCulate3:FPERot:FWHM{[:WAVelength] | :FREQuency |

:WNUMber}?

Queries the full width half-maximum data of the selected

modes.

Argument WAVelength

Queries the array of laser-line wavelengths after the calculation is completed. Returned values are in meters

(m).

FREQuency

Queries the array of laser-line frequencies after the calculation is completed. Returned values are in Hz.

WNUMber

Queries the array of laser-line wave numbers after the calculation is completed. Returned values are in inverse

meters (/m).

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

Example WAVelength

Query +5.47128800E-009

Response FREQuency

+6.93436400E+011

WNUMber

+2.31306200E+001

:CALCulate3:FPERot:MEAN?

Query :CALCulate3:FPERot:MEAN{[:WAVelength] | :FREQuency |

:WNUMber}?

Queries the mean data of the selected modes.

Argument WAVelength

Returns the mean wavelength of the selected modes.

FREQuency

Returns the mean frequency of the selected modes.

WNUMber

Returns the mean wave number of the selected modes.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

Example WAVelength

Query +1.53878000E-006

Response FREQuency

+1.94824800E+014

WNUMber

+6.49865400E+003

:CALCulate3:FPERot:MODE:SPACing?

:CALCulate3:FPERot:MODE:SPACing{[:WAVelength] | :FREQuency | Query

:WNUMber}?

Queries the mode spacing data of the selected modes.

Argument WAVelength

Queries the mode spacing wavelength after the calculation

is completed. Returned values are in meters (m).

FREQuency

Queries the mode spacing frequency after the calculation

is completed. Returned values are in Hz.

WNUMber

Queries the mode spacing wave number after the calculation is completed. Returned values are in inverse

meters (/m).

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

Example WAVelength

Query +3.18277200E- 010

Response FREQuency

+4.02787400E+011

WNUMber

+1.34356200E+001

:CALCulate3:FPERot:PEAK?

Query :CALCulate3:FPERot:PEAK{[:WAVelength] | :FREQuency | :WNUMber

|:POWer{[:DBM]|:WATTs}}?

Queries the peak data of the selected modes.

Argument WAVelength

Returns the peak wavelength of the selected modes.

FREQuency

Returns the peak frequency of the selected modes.

WNUMber

Returns the peak wave number of the selected modes.

POWer

Returns the peak amplitude of the selected modes in dBm

or watts.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

ExampleQuery WAVelength

Response +1.54073400E- 006

FREQuency +1.94577600E+014

WNUMber

++6.49041000E+003

POWer

- 9.09446600E+000 (dBm), +1.23183800E-004 (watts)

:CALCulate3:FPERot:POWer?

Query :CALCulate3:FPERot:POWer{[:DBM]|:WATTs}}?

Queries the total power data of the selected modes.

Argument DBM

Returns the total power in dBm.

WATTs

Returns the total power in watts.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

ExampleQuery dBm (DBM)

Response -4.46895600E+000

watts (WATTs) +3.57358800E-004

:CALCulate3:FPERot:SIGMa?

Query :CALCulate3:FPERot:SIGMa{[:WAVelength] | :FREQuency |

:WNUMber}?

Queries the sigma data of the selected modes.

Argument WAVelength

Returns the sigma wavelength of the selected modes.

FREQuency

Returns the sigma frequency of the selected modes.

WNUMber

Returns the sigma wave number of the selected modes.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

ExampleQuery WAVelength

Response +2.32784700E- 009

FREQuency +2.94452900E+011

WNUMber

+9.82124900E+000

:CALCulate3:POINts?

Query :CALCulate3:POINts?

Queries the number of points in the data set.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Query Only

Query Returns the number of points returned by the

Response CALCulate3:DATA? query.

:CALCulate3:PRESet

Command :CALCulate3:PRESet

Turns off any CALCulate3 calculation (delta, drift, Fabry-Perot,

or signal-to-noise) that is on.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

:CALCulate3:SNR:AUTO

 $\textbf{Command} \hspace{1cm} : CALCulate 3: SNR: AUTO \{? \mid \{ON \mid OFF \mid 1 \mid 0\}\}$

Selects the reference frequency value for measuring noise

in the signal-to-noise calculation.

The command argument allows you to select either an internally generated or a user-entered frequency reference for measuring the noise. To enter a value to use as the

reference, use:SNR:REFerence:FREQuency,

:SNR:REFerence:WAVelength, and :SNR:REFerence:WNUMber.

Constant ON

Selects internally generated reference frequency.

OFF

Selects user-entered reference frequency.

Attribute Preset State: on Summary *RST State: on

:CALCulate3:SNR:REFerence:FREQuency

Command :CALCulate3:SNR:REFerence:FREQuency{?| {<real> | MINimum |

MAXimum}}

Enters a frequency that can be used for the noise measurement reference in signal-to-noise calculations.

<real> Frequency value within the following limits:

MINimum: 181.6924 THz MAXimum: 236.0571 THz

After entering the frequency value, use SNR:AUTO to configure the instrument to use this value in subsequent signal-to-noise calculations. The default units are Hz.

Attribute Preset State: not affected

Summary *RST State: 193.4145 THz (1550.0 nm in a vacuum)

:CALCulate3:SNR:REFerence[:WAVelength]

Command :CALCulate3:SNR:REFerence[:WAVelength]{?| {<real> | MINimum |

MAXimum}}

Sets the wavelength used for the noise measurement

reference in the signal-to-noise calculation.

<real> Wavelength value within the following limits:

MINimum: 1270 nm MAXimum: 1650 nm

After entering the wavelength value, use SNR:AUTO to configure the instrument to use this value in subsequent signal-to-noise calculations. The number entered is converted internally to the corresponding frequency. The

default units are meters.

Attribute Preset State: not affected

Summary *RST State: 1550.0 nm in a vacuum

:CALCulate3:SNR:REFerence:WNUMber

Command :CALCulate3:SNR:REFerence:WNUMber{?] {<real> | MINimum |

MAXimum}}

Sets the wave number used for the noise measurement

reference in the signal-to-noise calculation.

<real> Wave number value within the following limits:

MINimum: 6060 /cm (1270 nm) MAXimum: 7874 /cm (1650 nm)

After entering the wavelength value, SNR:AUTO to configure the instrument to use this value in subsequent signal-to-noise calculations. The wave number entered is converted internally to the corresponding frequency. The default units

are /m.

Attribute Preset State: not affected

*RST State: 6451.614 cm⁻¹ (1550 nm)

:CALCulate3:SNR[:STATe]

 $\textbf{Command} \hspace{1cm} : CALCulate 3: SNR[:STATe] \cite{STATe} \cite{STA$

Turns the signal-to-noise calculation on and off.

Attribute Preset State: off Summary *RST State: off


SCPI Compliance: instrument specific



Only one STATe command can be turned on at any one time. Attempting to turn more than one state on at a time

:DISPlay Subsystem

Use DISPlay commands to control the display of data on the instrument. This subsystem is divided into two windows: the default, tabular view ([:WINDow]) and the graphical display window (:WINDow2). The commands in this subsystem have the following command hierarchy:



Click/touch any of the following DISPlay commands to view more information about the selected command.

- MARKer:MAXimum
- MARKer:MAXimum:LEFT
- MARKer:MAXimum:NEXT
- MARKer:MAXimum:PREVious
- MARKer:MAXimum:RIGHt
- UNIT:WAVelength

- [WINDow]:GRAPhics:STATe
- [WINDow]:STATe
- WINDow2:STATe
- WINDow2:TRACe[:SCALe]:AUTO
- WINDow2:TRACe[:SCALe]:LEFT[:WAVe length]
- WINDow2:TRACe[:SCALe]:RIGHt[:WAV elength]

:DISPlay:MARKer:MAXimum

Command :DISPlay:MARKer:MAXimum

Sets the marker to the laser line that has the maximum

power.

Attribute Preset State: marker set to maximum-power laser line *RST State: marker set to maximum-power laser line

SCPI Compliance: instrument specific

:DISPlay:MARKer:MAXimum:LEFT

Command :DISPlay:MARKer:MAXimum:LEFT

Moves the marker from the current marker position to the next laser line having the following characteristics:

- shorter wavelength
- lower frequency
- lower wave number

If the display is in the List by Ampl mode, it will change to List by WL before the marker is moved.

Attribute Summary Preset State: marker set to maximum-power laser line *RST State: marker set to maximum-power laser line

SCPI Compliance: instrument specific

:DISPlay:MARKer:MAXimum:NEXT

Command :DISPlay:MARKer:MAXimum:NEXT

Moves the marker to the laser line with the next lower

power level.

If the display is in the List by WL mode, it will change to List

by Ampl before the marker is moved.

Preset State: marker set to maximum-power laser line Attribute Summary

*RST State: marker set to maximum-power laser line

SCPI Compliance: instrument specific

:DISPlay:MARKer:MAXimum:PREVious

Command :DISPlay:MARKer:MAXimum:PREVious

Moves the marker to the laser line that has the next higher

power level.

If the display is in the List by WL mode, it will change to List

by Ampl before the marker is moved.

Attribute Preset State: marker set to maximum-power laser line Summary

*RST State: marker set to maximum-power laser line

SCPI Compliance: instrument specific

:DISPlay:MARKer:MAXimum:RIGHt

Command :DISPlay:MARKer:MAXimum:RIGHt

Moves the marker from the current marker position to the next laser line having the following characteristics:

- longer wavelength
- higher frequency
 - higher wave number

If the display is in the List by Ampl mode, it will change to List by WL before the marker is moved.

Attribute Summary Preset State: marker set to maximum-power laser line *RST State: marker set to maximum-power laser line

SCPI Compliance: instrument specific

:DISPlay:UNIT:WAVelength

Command :DISPlay:UNIT:WAVelength { ? | THZ | NM | ICM }

Sets the wavelength units on the front panel display.

This command only affects the units displayed on the front panel and has no effect of the remote interface. It also takes precedence over other commands that would affect

the units on the display.

Attribute Preset State: NM Summary *RST State: NM

:DISPlay[:WINDow]:GRAPhics:STATe

Command :DISPlay[:WINDow]:GRAPhics:STATe{?| {ON | OFF | 1 | 0}}

Turns on and off the display of the power bars. When turned on, the power bars are displayed in all modes except the drift and signal-to-noise modes. When turned off, this command prevents the display of power bars for

all instrument modes.

Attribute Preset State: on Summary *RST State: on

:DISPlay[:WINDow]:STATe

Command :DISPlay[:WINDow]:STATe{?| {ON | OFF | 1 | 0}}

Turns the tabular display on and off. ON activates the tabular display. If the graphical display (:WINDow2) is on, the tabular display is shown below the graphical display. OFF turns off the tabular display and allows the graphical

display to occupy the entire data display area.

Attribute Preset State: on Summary *RST State: on

:DISPlay:WINDow2:STATe

Command :DISPlay:WINDow2:STATe{?| {ON | OFF | 1 | 0}}

Turns the graphical display on and off. ON activates the graphical display. If the tabular display ([:WINDow]) is on, the graphical display is shown above the tabular display. OFF turns off the graphical display and allows the tabular

display to occupy the entire data display area.

Attribute Preset State: on Summary *RST State: on

:DISPlay:WINDow2:TRACe[:SCALe]:AUTOmeasure

Command :DISPlay:WINDow2:TRACe[:SCALe]:AUTOmeasure

Initiates an AutoMeasure on the input signal.

The mulit-wavelength meter will measure the input signal and format the display for optimal viewing. The split graph/table display will be selected. The graphical display limits will be adjusted to fit the entire input signal into the window. A tabular format will be selected based on the

number of lines detected in the input signal.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

:DISPlay:WINDow2:TRACe[:SCALe]:LEFT[:WAVelength]

Command :DISPlay:WINDow2:TRACe[:SCALe]:LEFT[:WAVelength] {?|{<real>|

MINimum | MAXimum}}

Sets or queries the value represented by the left edge of the trace x-axis. If the left scale value given is greater than the right scale value, the right scale value will be set to the

left scale value.

<real> Wavelength value within the following limits:

MINimum: 1270 nm

MAXimum: :DISPlay:WINDow2:TRACe:SCALe:RIGHt value

Attribute Preset State: 1270 nm Summary *RST State: 1270 nm

SCPI Compliance: instrument specific

:DISPlay:WINDow2:TRACe[:SCALe]:RIGHt[:WAVelength]

Command :DISPlay:WINDow2:TRACe[:SCALe]:RIGHt[:WAVelength] {?|{<real>|

MINimum | MAXimum}}

Sets or queries the value represented by the right edge of the trace x-axis. If the right scale value given is less than the left scale value the left scale value will be set to the

right scale value.

<real> Wavelength value within the following limits:

MINimum: :DISPlay:WINDow2:TRACe:SCALe:LEFT value


MAXimum: 1650 nm

Attribute Preset State: 1650 nm Summary *RST State: 1650 nm

SCPI Compliance: instrument specific

:HCOPy Subsystem

Use HCOPy commands to print the displayed measurement results to a printer. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following HCOPy commands to view more information about the selected command.

DESTination[:IMMediate]MODEPRINters

:HCOPy:DESTination

Command :HCOPy:DESTination {<pri>cprinter_number> | "<pri>rinter_string>"}

Selects the default printer. Either number or string

name can specify the default printer.

<printer_number> Integer representing the attached printer. This number

corresponds to the number returned with each printer

name by HCOPy:PRINters?.

<printer_string> Alphanumeric string representing the attached printer.

The printer string must exactly match either the

character strings in the File, Print Setup dialog boxes,

or the strings returned by HCOPy:PRINters?.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

:HCOPy[:IMMediate]

Command :HCOPy[:IMMediate]

Initiates a printout on the currently selected printer.

Printing to file is not supported. Do not use a printer driver

that is configured to print to file.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Command Only



Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential Commands, click/touch



:HCOPy:MODE

Command :HCOPy:MODE {? | TABLe | SCReen | ALL }

Selects the output for all for hardcopy printouts.

Constant TABLe

Outputs all measured data in tabular form.

SCReen

Outputs the graph and the portion of the tabular data that

is on the screen.

ALL

Outputs both the tabular data and the screen.

Attribute Preset State: TABLe Summary *RST State: TABLe

SCPI Compliance: instrument specific

:HCOPy:PRINters?

Query :HCOPy:PRINters?

Queries the currently available printers.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Query Only

Query Returns a list of the currently available printers.

Response

Returned <printer_count><NL><printer_data><NL>[,<printer_data><NL>]

Format

<printer_count> Number of printers currently installed.

<NL> New line character.


<directory> List of available printers, each line separated by a <NL>.

Example 3<NL>1,"HP LaserJet 8000 PS",DEF<NL>2,"HP LaserJet 4050 TN

PS"<NL>3,"HP DeskJet 870Cxi"<NL><NL>

:MMEMory Subsystem

Use MMEMory commands to manage the mass storage capabilities of this instrument. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following MMEMory commands to view more information about the selected command.

- CATalog?
- CDIRectory
- DATA
- <u>DELete</u>

- LOAD
- MDIRectory
- <u>PWDirectory?</u>
- STORe

:MMEMory:CATAlog?

Query :MMEMory:CATalog? ["<directory>" | { ROOT | SIMages | DATA |

SETups }]

Returns a listing of the contents of a directory.

The directory may be specified as a string, such as

"D:\User Files\Data", or as a parameter. If no parameter is used, a listing of the present working directory is returned.



The file times will be Greenwich Mean Time.

Constant ROOT

Root of user directory structure on hard drive.

SIMages

Directory where screen images are stored.

DATA

Directory where all instrument and application generated

data is stored.

SETups

Directory where instrument setup data is stored.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Query Only

Query Returns the following:

Response

<n><NL><directory>

Example 6 <NL>

Directory of D:\User Files\Data<NL>

<NL>

<n> Number of lines in the directory listing.

<NL> New line character.

<directory> List of directories and filenames, each line separated by

an <NL>.

:MMEMory:CDIRectory

Command :MMEMory: CDIRectory ["<directory>" | { ROOT | SIMages | DATA |

SETups }]

Changes the present working directory to the specified directory name. The desired directory can be specified either by name or by a parameter. "<directory>" is a character-quoted ASCII string, which can include the subdirectory designation. You must separate the directory

name and any subdirectories with a backslash (\).

Constant ROOT

Root of user directory structure on hard drive.

SIMages

Directory where screen images are stored.

DATA

Directory where all instrument and application generated

data is stored.

SETups

Directory where instrument setup data is stored.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Command Only

Query Returns an error if specified directory does not exist. Response



You can execute MMEM:CDIR "A:\". If you attempt to execute :MMEM:CDIR "C:\", the present working directory (PWD) is not changed. The directory specified *must* be below "D:\User Files\".

:MMEMory:DATA

:MMEMory:DATA {? "<filename>" | "<filename>",<data> Command

> Loads the specified data into the file "<filename>". The destination directory is the working directory. <data> is in

IEEE 4888.2 block data format.

This command operates only on files in the user file

directory.

<filename> Name of the file. A maximum of 254 characters including

> the path name can be used. The filename assumes the present working directory if a path does not preceed the

file name.

An error will be generated if the filename includes subdirectories with the name of the file. An error will also be generated if a file exists with the same name as the

working directory.

<data> The command can use either the IEEE 4888.2 data

formats

Definite Length Arbitrary Block Response Data

Indefinite Length Arbitrary Block Response

Data

The :MMEMory:DATA guery uses only the IEEE 4888.2

"Definite Length Arbitrary Block Response Data" format.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Command Only

:MMEMory:DELete

Command MMEMory:DELete "<filename>"

Deletes a specified file from the disk. An error is generated

if the requested file does not exist.

<filename> Name of the file. A maximum of 254 characters including

the path name can be used. The filename assumes the present working directory if a path does not preceed the

file name.

The file name can include subdirectories with the name of

the file.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Command Only



You can execute MMEM:CDIR "A:\". If you attempt to execute :MMEM:CDIR "C:\", the present working directory (PWD) is not changed. The directory specified *must* be

below "D:\User Files\".

:MMEMory:LOAD

Command :MMEMory:LOAD "<file_name>"

Loads the specified instrument setup file from the disk.

<file_name> Name of the file. A maximum of 254 characters including

the path name can be used. The filename assumes the present working directory if a path does not preceed the

file name.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Command Only

Query Returns an error if the file does not exist.

Response



You can execute MMEM:CDIR "A:\". If you attempt to execute :MMEM:CDIR "C:\", the present working directory (PWD) is not changed. The directory specified *must* be below "D:\User Files\".

:MMEMory:MDIRectory

Command :MMEMory:MDIRectory "<directory>"

Creates a directory in the present working directory, with

the designated directory name.

Attribute Preset State: not affected Summary *RST State: not affected

SCPI Compliance: instrument specific

Command Only



You can execute MMEM:CDIR "A:\". If you attempt to execute :MMEM:CDIR "C:\", the present working directory (PWD) is not changed. The directory specified *must* be

below "D:\User Files\".

:MMEMory:PWDirectory?

Query :MMEMory:PWD?

Returns the name of the present working directory,

including the full path.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Query Only

Query Returns the following:

Response <pr

<NL> New line character.

:MMEMory:STORe

Command :MMEMory:STORe <source>,"<file_name>"

Stores an instrument setup or tabular results to the disk. The file name does not include a suffix. The instrument

supplies the suffix.

<source> {TABLe | SETup}

<file_name> Name of the file. A maximum of 254 characters including

the path name can be used. The filename assumes the present working directory if a path does not preceed the

file name.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: instrument specific

Command Only

Query Returns an error if a file exists with the same name in the

Response specified directory.




You can execute MMEM:CDIR "A:\". If you attempt to execute :MMEM:CDIR "C:\", the present working directory (PWD) is not changed. The directory specified *must* be

below "D:\User Files\".

[:SENSe] Subsystem

Use SENSe commands to select between measurements in air or vacuum. You can also enter an amplitude offset. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following SENSe commands to view more information the selected command.

- CORRection: DEVice
- CORRection: ELEVation
- CORRection:MEDium

- CORRection:OFFSet[:MAGNitude]
- DATA?

[:SENSe]:CORRection:DEVice

Command [:SENSe]:CORRection:DEVice{?| {NARRow | BROad}}

Selects the wavelength measurement algorithm.

Constant NARRow

Selects wavelength measurements for narrowband devices such as DFB lasers and modes of FP lasers.

BROad

Selects wavelength measurements for broadband devices such as optical filters and LEDs.

The narrow bandwidth algorithm, used for measuring lasers, determines the wavelength based upon the peak.

The broad bandwidth algorithm, used for LEDs, filters, and chirped lasers, determines the wavelength based upon the center-of-mass of the power spectrum. The peak excursion function is used to determine the value of the integration limits. Care must be taken to ensure that the integration limits are above any noise. This is especially true when measuring devices with sloping noise floors, like an EDFA amplifier. For more information on peak excursion, refer to the <u>PEXCursion</u> command.



Instrument specifications apply when the device is set to NARRow. Specifications do not apply in BROad mode.

Attribute Non-sequential command Summary Preset State: NARRow

*RST State: NARRow

SCPI Compliance: instrument specific

Query Returns the previously selected device. For example,

Response NARRow



Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential Commands, click/touch



[:SENSe]:CORRection:ELEVation



This command is available for backward compatibility to the 86120 family and no longer affects the accuracy, resolution or update rate of the instrument.

Command [:SENSe]:CORRection:ELEVation{?| {<integer> | MINimum |

MAXimum}}

Sets the elevation value used by the instrument to

compensate for air dispersion.

<integer> Altitude in meters.

MINimum: 0 m MAXimum: 5000 m

Attribute Non-sequential command Summary Preset State: not affected

*RST State: sets this value to the minimum

SCPI Compliance: instrument specific

Query Returns the current elevation setting as shown in the

Response following example:

+1500



Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential Commands, click/touch



[:SENSe]:CORRection:MEDium

Command [:SENSe]:CORRection:MEDium{?| {AIR | VACuum}}

Sets the Agilent 86122A to return wavelength readings in

a vacuum or standard air.

Standard air is defined to have the following

characteristics:

barometric pressure - 760 torr

temperature - 15°C

• relative humidity - 0%

Constant AIR

Selects wavelength values in standard air.

VACuum

Selects wavelength values in a vacuum.

Attribute Preset State: VAC Summary *RST State: VAC

SCPI Compliance: instrument specific

[:SENSe]:CORRection:OFFSet[:MAGNitude]

Command [:SENSe]:CORRection:OFFSet:MAGNitude{?| {<real> | MINimum |

MAXimum}}

Enters an offset for amplitude values.



With the Agilent 86122A, the power offset value is applied to measured power values. This includes data values displayed on the instrument front panel and those returned via remote commands (for example, CALC2:DATA? POW or

FETC:SCAL:POW?).

Please note that the Agilent 86120C applied this offset to front panel data and only to the CALC2:DATA? POW command when in the power weighted average mode (for example, CALC2:PWAV:STAT ON).

<real> Logarithmic value in dB.

MINimum: -40.0 dB MAXimum: 40.0 dB

Attribute Preset State: 0.0 Summary *RST State: 0.0

SCPI Compliance: instrument specific

Query Returns the current offset setting as shown in the following

Response example:

+5.0000000E+000

[:SENSe]:DATA?

Query [:SENSe]:DATA?

Queries the time domain samples of the input laser line.

Be prepared to process a large amount of data when this query is sent. The amount of data returned can be set using CALCulate1:TRANsform:FREQuency:POINts. The following number of values can be returned:

MINimum: 2¹⁶
 MAXimum: 2¹⁷
 EXTended1: 2¹⁸

The floating point values are scaled from 1.000 to 1.999756 (1 + 4095/4096). Amplitude values are not calibrated.

The input laser line(s) generate an interference pattern on the photodetector as a function of the Michelson interferometer optical path delay. The time domain data is sampled at uniform optical path delay increments of the reference laser wavelength, or 0.632991 microns.

If your program is aborted or interrupted after sending this query, the Agilent 86122A continues to process the data but does not place it in the output buffer. Because of the amount of data processed, the instrument *will not respond* to any new commands in its input buffer *for 30 or 40 seconds*.

Attribute Summary

Preset State: none

SCPI Compliance: instrument specific

Query Only


Query Response The following string shows an example of the first few measurements returned by this query.

+1.51367200E+000,+1.51855500E+000,+1.49902300E+0
00,+1.47949200E+000,+1.50488300E+000,+1.53320300
E+000,+1.50097700E+000,+1.47265600E+000,+1.50293
000E+000,+1.50781300E+000,+1.51171900E+000,+1.48
242200E+000,+1.50097700E+000,+1.51855500E+000,+1
.50683600E+000,+1.48632800E
+000,+1.50488300E+000

Notice that only values are returned to the computer. There is no first value that indicates the number of values contained in the string as there is, for example, with FETCh, READ, and MEASure.

:STATus Subsystem

Use STATus commands to control the Agilent 86122A's status-reporting structures. These structures provide registers that you can use to determine if certain events have occurred. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following STATus commands to view more information about the selected command.

- <u>{OPERation |</u> <u>QUEStionable}:CONDition?</u>
- {OPERation | QUEStionable}:ENABle
- {OPERation | QUEStionable}[:EVENt]
- <u>{OPERation |</u>
 <u>QUEStionable}:NTRansition</u>
- <u>{OPERation |</u>
 <u>QUEStionable}:PTRansition</u>
- PRESet

:STATus:{OPERation | QUEStionable}:CONDition?

Query :STATus:{OPERation | QUEStionable}:CONDition?

Queries the value of the questionable or operation condition register. Use this query to read the value of the

OPERation Status or OUEStionable Status registers.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query Only

Query 0 to 32767

Response

Example OUTPUT 720;":STATUS:OPERATION:CONDITION?"

:STATus:{OPERation | QUEStionable}:ENABle

Command :STATus:{OPERation | QUEStionable}:ENABle{?| <value>}

Sets the enable mask for the questionable or operation

event register.

The enable mask selects which conditions in the event register cause the summary bit in the status byte to be set.

If a bit in the enable mask is set true and the

corresponding event occurs, the summary bit (bit 3 for the questionable status or bit 7 for the operation status) in the

status byte will be set.

<integer> Number from 0 to 65535.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query The largest value that can be returned is 32767, because

Response the most-significant register bit cannot be set true.

Example OUTPUT 720;":STATUS:QUESTIONABLE:ENABLE 1024"

:STATus:{OPERation | QUEStionable}[:EVENt]

Command :STATus:{OPERation | QUEStionable}:EVENt?

Queries the contents of the questionable or operation

event registers.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query Returns a number from 0 to 32767 indicating which bits

Response are set. Reading the register clears the register.

Example OUTPUT 720;":STATUS:OPERATION:EVENT?"

:STATus:{OPERation | QUEStionable}:NTRansition

Command :STATus:OPERation:NTRansition{?| < integer>}

Selects bits in the event register which can be set by negative transitions of the corresponding bits in the

condition register.

Changes in the state of a condition register bit cause the associated OPERation Status or QUEStionable Status register bits to be set. This command allows you to select a negative bit transition to trigger an event to be recognized. A negative transition is defined to occur whenever the

selected bit changes states from a 1 to a 0

<integer> Number from 0 to 65535.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query When queried, the largest value that can be returned is Response 32767 because the most significant register bit cannot be

set true.

Example OUTPUT 720;":STATUS:OPER:NTRansition 16"

:STATus:{OPERation | QUEStionable}:PTRansition

Command :STATus:OPERation:PTRansition{?| < integer>}

Selects bits in the event register which can be set by positive transitions of the corresponding bits in the

condition register.

Changes in the state of a condition register bit cause the associated OPERation Status or QUEStionable Status event register bits to be set. This command allows you to select

a positive bit transition to trigger an event to be recognized. A positive transition is defined to occur whenever the selected bit changes states from a 0 to a 1.

<integer> Number from 0 to 65535.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query When queried, the largest value that can be returned is Response 32767 because the most significant register bit cannot be

set true.

Example OUTPUT 720;":STATUS:OPER:PTRansition 16"

:STATus:PRESet

Command :STATus:PRESet

Presets the enable registers and the PTRansition and

NTRansition filters.

This Preset command is defined by SCPI to affect the enable register. If you want to clear all event registers and

queues, use *CLS..

See <u>Instrument Preset Conditions</u> for a list of preset

conditions.

Attribute Preset State: none Summary *RST State: none


SCPI Compliance: standard

Command Only

Example OUTPUT 720;":STATUS:PRESET"

:SYSTem Subsystem

Use SYSTem commands to preset the Agilent 86122A, set instrument utilities, and query error messages. The commands in this subsystem have the following command hierarchy:



Click/touch any of the following SYSTem commands to view more information the selected command.

● <u>DATE</u>

PRESet

● <u>ERRor?</u>

• TIME

HELP:HEADers?

VERSion

:SYSTem:DATE

Command :SYSTem:DATE {? | <year>,<month>,<day>}

Sets or queries the system date. This command is not

affected by *RST.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query <year><month><day><NL>

Response

<year> Specifies the year in the format <yyyy>.

<month> Specifies the month in the format <1,2,...12> | <JAN, FEB,

MAR,...>.

<day> Specifies the day in the format, for example, <1...31>.

ERRor?

Query :SYSTem:ERRor?

Queries an error from the error queue.

The Agilent 86122A has a 30 entry error queue. The queue is a first-in, first-out buffer. If you repeatedly send the SYSTEM:ERROR?, the instrument returns the error numbers and descriptions in the order in which they occur until the queue is empty. Any further queries return +0, "No

errors" until another error occurs.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query Only

Query <value>, <string>

Response The following is an example of a response:

-113,"Undefined header"

<value> Integer value that represents the error message number.

<string> Quoted text of the error message.

Example DIM Error\$[250]

OUTPUT 720;":SYSTEM:ERROR?"

ENTER 720; Error\$ PRINT Error\$

See Error Messages to view a complete list of error messages.

:SYSTem:HELP:HEADers?

:SYSTem:HELP:HEADers? Querv

Queries a listing of all the remote programming commands

available for the Agilent 86122A.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query Only

Example The following is an example of the first few lines and last

> few lines returned in the string. The term *nguery* indicates that a command cannot be sent as a query. The term *qonly* indicates that a command can only be sent as a query.

Each command in the listing is separated by a line feed

character.



The returned ASCII string of commands is in the IEEE 488.2 arbitrary-block data format. The first line indicates the total number of bytes returned to the computer. That is, the # character is followed by one digit which indicates how many of the following digits convey the byte count. The next digits give the actual byte count. For example, in the listing below, 4387 bytes are indicated in the file.

#44387

:ABORt/nguery/

:CALCulate:DATA?/qonly/

:CALCulate:TRANsform:FREQuency:POINts

:CALCulate1:DATA?/gonly/

:CALCulate1:TRANsform:FREQuency:POINts

:CALCulate2:DATA?/gonly/

*IDN?/gonly/

*OPC

*RCL/nquery/

*RST/nquery/

*SAV/nquery/

*SRE

*STB?/gonly/

*TRG/nguery/

*TST?/qonly/

*WAI/nguery/

:SYSTem:PRESet

Command :SYSTem:PRESet

Returns the Agilent 86122A to a known condition.

See <u>Instrument Preset Conditions</u> for a list of reset

conditions.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Command Only

:SYSTem:TIME

Command :SYSTem:TIME {? | <hour>, <minute>, <second>}

Sets or queries the system time. This command is not

affected by *RST.

Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query <hour><minute><second><NL>

Response

<hour> Specifies the hour in the format <0..23>.</hd>
<hr/>
<minute> Specifies the minute in the format <0..59>.</hr>

<second> Specifies the second in the format <0..59>.

:SYSTem:VERSion?

Query :SYSTem:VERSion

Queries the version of SCPI that the instrument complies with. The SCPI version used in the Agilent 86122A is

1999.0.


Attribute Preset State: none Summary *RST State: none

SCPI Compliance: standard

Query Only

[:TRIGger] Subsystem

Use TRIGger commands to stop the current measurement and allow the instrument to acquire new measurement data. You can also use the TRIGger commands to select single or continuous acquisition of measurement data. The commands in this subsystem have the following command hierarchy:





The SCPI definition defines the :TRIGger subsystem to include :ABORt, :ARM, :INITiate, and :TRIGger commands. The Agilent 86122A uses no :ARM or :TRIGger commands.

Click/touch any of the following TRIGger commands to view more information about the selected command.

- ABORt
- <u>INITiate:CONTinuous</u>
- <u>INITiate[:IMMediate]</u>

:ABORt

Command :ABORt

Halts the current measurement sequence and places the

instrument in the idle state.

If the instrument is configured for continuous

measurements, a new measurement sequence will begin. Otherwise, the instrument stays in the idle state until a

new measurement is initiated.

Attribute Preset State: not affected Summary SCPI Compliance: standard

Command Only

:INITiate:CONTinuous

Command :INITiate:CONTinuous{?| {ON | OFF | 1 | 0}}

Selects single or continuous measurement acquisition mode. When ON, the instrument continuously measures

the input spectrum.

Attribute Non-sequential command

Summary Preset State: on

*RST State: off

SCPI Compliance: standard



Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential Commands, click/touch



:INITiate[:IMMediate]

Command :INITiate:IMMediate

Initiates a new measurement sequence.

Attribute Non-sequential command

Summary Preset State: none

SCPI Compliance: standard

Command Only



Non-sequential command: Always use an *OPC? query or a *WAI command to ensure that this command has the time to complete before sending any more commands to the instrument. For more information about non-sequential Commands, click/touch



:UNIT Subsystem

Use UNIT commands to set the amplitude units to watts or dBm. The commands in this subsystem have the following command hierarchy:

:UNIT | |:POWer]



Use the $\underline{:\!DISPlay:\!UNIT:\!WAVelength}$ command, to set the wavelength units.

[:POWer]

 $\textbf{Command} \qquad : UNIT[:POWer]\{?|\{W \mid DBM\}\}$

Sets the power units to watts (linear) or dBm (logarithmic).

Attribute Preset State: dBm Summary *RST State: dBm

SCPI Compliance: standard

List of Commands



Codes: "S" indicates a standard SCPI command. "I" indicates an instrument specific command.

Common Command	Description	Code
*CLS	Clears all event registers and the error queue.	
*ESE	Sets the bits in the standard-event status enable register.	
*ESR?	Queries value standard-event status register.	
*IDN?	Queries instrument model number and firmware version.	
*OPC	Sets operation complete bit of the standard-event status register.	
*RCL	Recalls a saved instrument state.	
*RST	Resets instrument.	
*SAV	Saves an instrument state.	
*SRE	Sets bits in service-request enable register.	
*STB	Queries value of status byte.	
*TRG	Triggers acquisition of measurement data.	
*TST?	Performs an instrument self test.	
*WAI	Causes instrument to finish processing current command before continuing.	
Measurement Instructions	Description	Code
:CONFigure	Configures instrument for wavelength, wavenumber, frequency, power, and measurements.	I
:FETCh	Queries wavelength, wavenumber, frequency, power, and measurements that have already been captured.	I
:MEASure	Configures, measures, and queries wavelength, wavenumber, frequency, power, and measurements.	I
:READ	Measures and queries wavelength, wavenumber, frequency, power, and	1

measu	$r \Delta m$	าคก	tc
IIIcasui	CII		ιo.

	moded officials.	
CALCulate1 Subsystem	Description	Code
:CALCulate1:DATA?	Queries the uncorrected frequency-spectrum data of the input signal.	S
:CALCulate1:TRANsform: FREQuency:POINts?	Sets and queries the number of points in the data set.	S
CALCulate2 Subsystem	Description	Code
:CALCulate2:DATA?	Queries the corrected frequency-spectrum data of the input signal.	S
:CALCulate2:PEXCursion	Sets the peak excursion limit.	1
:CALCulate2:POINts?	Queries the number of points in the data set.	I
:CALCulate2:PTHReshold	Sets the peak threshold limit.	1
:CALCulate2:PWAVerage [:STATe]?	Places the instrument in the average-wavelength mode. Data queries return the power-weighted average frequency, wavelength, or wavenumber or total power.	I
:CALCulate2:WLIMit[:STATe]	Turns wavelength limiting on and off.	1
:CALCulate2:WLIMit:STARt: FREQuency	Sets the starting frequency for the wavelength limit range.	I
:CALCulate2:WLIMit:STARt [:WAVelength]	Sets the starting wavelength for the wavelength limit range.	I
:CALCulate2:WLIMit:STARt: WNUMber	Sets the starting wavenumber for the wavelength limit range.	I
:CALCulate2:WLIMit:STOP: FREQuency	Sets the stopping frequency for the wavelength limit range.	I
:CALCulate2:WLIMit:STOP [:WAVelength]	Sets the stopping wavelength for the wavelength limit range.	I
:CALCulate2:WLIMit:STOP: WNUMber	Sets the stopping wavenumber for the wavelength limit range.	I
CALCulate3 Subsystem	Description	Code
:CALCulate3:ASNR:CLEar	Resets and restarts the signal-to-noise ratio averaging.	I
:CALCulate3:ASNR:COUNt	Sets the number of measurements to	1

:CALCulate3:ASNR:COUNt		
	average the signal-to-noise ratio.	
:CALCulate3:ASNR:[:STATe]	Turns signal-to-noise ratio averaging mode on and off.	I
:CALCulate3:DATA?	Queries the data resulting from delta, drift, and signal-to-noise measurements.	S
:CALCulate3:DELTa:POWer [:STATe]	Turns the delta power measurement mode on and off.	I
:CALCulate3:DELTa:REFerence: FREQuency	Selects the signal to be used as the reference for the DELTa calculations.	I
:CALCulate3:DELTa:REFerence: POWer?	Queries the power level of the reference signal.	I
:CALCulate3:DELTa:REFerence [:WAVelength]	Selects the signal to be used as the reference for the DELTa calculations.	I
:CALCulate3:DELTa:REFerence: WNUMber	Selects the signal to be used as the reference for the DELTa calculations.	I
:CALCulate3:DELTa:WAVelength [:STATe]	Turns the delta wavelength measurement mode on and off.	I
:CALCulate3:DELTa:WPOWer [:STATe]	Turns the delta wavelength and power measurement mode on and off.	I
:CALCulate3:DRIFt:DIFFerence [:STATe]	Sets the drift calculation to subtract the minimum values measured from the maximum values measured.	I
:CALCulate3:DRIFt:MAXimum [:STATe]	Sets the drift calculation to return the maximum power (frequency) values measured.	I
:CALCulate3:DRIFt:MINimum [:STATe]	Sets the drift calculation to return the minimum power (frequency) values measured.	I
:CALCulate3:DRIFt:PRESet	Turns off all the drift states for DIFFerence, MAXimum, MINimum, and REFerence.	I
:CALCulate3:DRIFt:REFerence: RESet	Places the current list of signals into the reference list.	I
:CALCulate3:DRIFt:REFerence [:STATe]	Turns the drift state on and off so that CALC3:DATA? will return the reference signal list.	I
:CALCulate3:DRIFt[:STATe]	Turns the drift measurement calculation on and off.	I

:CALCulate3:FPERot[:STATe]	Turns the Fabry-Perot measurement mode on and off.	I
:CALCulate3:FPERot:MEAN [:WAVelength]?	Queries the mean wavelength of the selected modes.	I
:CALCulate3:FPERot:MEAN: FREQuency?	Queries the mean frequency of the selected modes.	I
:CALCulate3:FPERot:MEAN: WNUMber?	Queries the mean wavenumber of the selected modes.	I
:CALCulate3:FPERot:PEAK [:WAVelength]?	Queries the peak wavelength of the selected modes.	I
:CALCulate3:FPERot:PEAK: FREQuency?	Queries the peak frequency of the selected modes.	I
:CALCulate3:FPERot:PEAK: WNUMber?	Queries the peak wavenumber of the selected modes.	I
:CALCulate3:FPERot:PEAK: POWer?	Queries the peak power of the selected modes.	I
:CALCulate3:FPERot:FWHM [:WAVelength]?	Queries full width half-max wavelength of selected modes.	I
:CALCulate3:FPERot:FWHM: FREQuency?	Queries full width half-max frequency of selected modes.	I
:CALCulate3:FPERot:FWHM: WNUMber?	Queries full width half-max wavenumber of selected modes.	I
:CALCulate3:FPERot:MODE: SPACing[:WAVelength]?	Queries the mode spacing wavelength of the selected modes.	I
:CALCulate3:FPERot:MODE: SPACing:FREQuency?	Queries the mode spacing frequency of the selected modes.	I
:CALCulate3:FPERot:MODE: SPACing:WNUMber?	Queries the mode spacing wavenumber of the selected modes.	I
:CALCulate3:FPERot:POWer [:WAVelength]?	Queries the power wavelength of the selected modes.	I
:CALCulate3:FPERot:POWer: FREQuency?	Queries the power frequency of the selected modes.	I
:CALCulate3:FPERot:POWer: WNUMber?	Queries the power wavenumber of the selected modes.	I
:CALCulate3:FPERot:SIGMa	Queries the sigma wavelength of the selected modes.	I

[:WAVelength]?	selected modes.	
:CALCulate3:FPERot:SIGMa: FREQuency?	Queries the sigma frequency of the selected modes.	I
:CALCulate3:FPERot:SIGMa: WNUMber?	Queries the sigma wavenumber of the selected modes.	I
:CALCulate3:POINts?	Queries the number of points in the data set.	I
:CALCulate3:PRESet	Turns off any CALCulate3 calculation that is on.	I
:CALCulate3:SNR:AUTO	Selects the internal or externally entered frequency value for the noise measurement reference in the SNR calculation.	I
:CALCulate3:SNR:REFerence: FREQuency	Sets the frequency used for the noise measurement reference in the SNR calculation.	I
:CALCulate3:SNR:REFerence [:WAVelength]	Sets the wavelength used for the noise measurement reference in the SNR calculation.	I
:CALCulate3:SNR:REFerence: WNUMber	Sets the wave number used for the noise measurement reference in the SNR calculation.	I
:CALCulate3:SNR[:STATe]	Turns the SNR calculation on and off.	I
DISPlay Subsystem	Description	Code
:DISPlay:MARKer:MAXimum	Sets the marker to the signal with the largest power.	I
:DISPlay:MARKer:MAXimum: LEFT	Moves marker to signal with the next lower wavelength or frequency.	I
:DISPlay:MARKer:MAXimum: NEXT	Moves the marker to the signal with the closest power level just below the power level of the signal at the current marker position.	I
:DISPlay:MARKer:MAXimum: PREVious	Moves the marker to the signal with the closest power level just above the power level of the signal at the current marker position.	I
:DISPlay:MARKer:MAXimum: RIGHt	Moves marker to the next higher wavelength or frequency.	I
:DISPlay[:WINDow]:GRAPhics: STATe	Turns the instrument display of the power bars on and off.	S

HCOPy Subsystem	Description	Code
:HCOPy:DESTination	Selects the default printer.	S
:HCOPy[:IMMediate]	Starts a printout.	S
:HCOPy:MODE	Selects the output for all for hardcopy printouts.	S
:HCOPy:PRINters?	Queries the currently available printers.	S
SENSe Subsystem	Description	Code
:SENSe:CORRection:DEVice	Configures wavelength measurements for narrowband or wideband devices.	I
:SENSe:CORRection:ELEVation	Sets the elevation value used by the instrument to compensate for air dispersion.	I
:SENSe:CORRection:OFFSet: MAGNitude	Sets the power offset value used by the instrument.	S
:SENSe:CORRection:MEDium	Sets the instrument to return the wavelength reading in a vacuum when the parameter is on. Parameters are VAC and AIR.	I
:SENSe:DATA?	Queries the time domain samples of the input signal.	I
STATus Subsystem	Description	Code
:STATus:{OPERation QUEStionable}:CONDition?	Returns the value for the condition register for the node.	S
:STATus:{OPERation QUEStionable}:EVENt?	Returns the value of the event register for the node.	S
:STATus:{OPERation QUEStionable}:ENABle	Sets the enable register.	S
:STATus:{OPERation QUEStionable}:PTRansition	Sets the positive transition filter register.	S
:STATus:{OPERation QUEStionable}:NTRansition	Sets the negative transition filter register.	S
:STATus:PRESet	Presets the enable registers for all status nodes.	S
SYSTem Subsystem	Description	Code
:SYSTem:ERRor?	Queries an error from the error queue.	S
:SYSTem:HELP:HEADers?	Queries an ASCII listing of all Agilent 86120C remote commands.	I

:SYSTem:PRESet	Performs the equivalent of a front-panel PRESET key press.	S
:SYSTem:VERSion	Queries the version of SCPI with which this instrument is compliant.	S
TRIGger Subsystem	Description	Code
:ABORt	Stops the current measurement sequence.	S
:INITiate:IMMediate	Places the instrument into the initiated state and initiates a new measurement sequence.	S
:INITiate:CONTinuous	Sets the instrument for single or continuous measurement.	S
UNIT Subsystem	Description	Code
:UNIT[:POWer]	Sets the power units to watts (linear) or dBm (logarithmic).	S

Example Programs

The following programs provide examples of remote programming commands used in typical situations. These programs are not meant to teach general programming techniques or provide ready-to-use solutions. They provide an understanding of how measurements are performed and how to return data to the computer.



All of the following examples are written in the HP BASIC programming language.

- Measuring a DFB laser
- Measuring WDM channels
- Measuring WDM channel drift
- Measuring WDM channel separation
- Measuring signal-to-noise ratio of each WDM channel
 - Increasing a source's wavelength accuracy



To select a delta, drift, or signal-to-noise measurement, see Measuring Delta, Drift, and SNR.

Measuring a DFB Laser

The following example program measures the power and wavelength of a DFB laser. It first sets the Agilent 86122A in the single acquisition measurement mode. It then triggers the instrument with the MEASure command to capture measurement data of the input spectrum. Because the data is stored in the instrument's memory, it can be queried as needed.

This example uses the <u>Set_ese</u>, <u>Err_mngmt</u>, and <u>FNIdentity function</u> subroutines.

```
COM /Instrument/ @Mwm
ASSIGN @Mwm TO 720
PRINT USING "37A,33A"; "Multi-Wavelength Meter Identity is: "; FNIdentity$
OUTPUT @Mwm:":INIT:CONT OFF"
ON TIMEOUT 7,5 CALL Err_mngmt
OUTPUT @Mwm;":MEAS:SCAL:POW:WAV?"
ENTER @Mwm;Current_wl
OUTPUT @Mwm;":FETC:SCAL:POW?"
ENTER @Mwm;Current_pwr
OFF TIMEOUT
PRINT USING "20A,4D.3D,3A,19A,M2D.2D,4A"; "The wavelength is: ";Current_wl /1.0E-9;" nm";" with a power of:
";Current_pwr;" dBm"
END
Err_mngmt:SUB Err_mngmt
    COM /Instrument/ @Mwm
    DIM Err_msq$[255]
    INTEGER Cme
    CLEAR 7
    REPEAT!
        OUTPUT @Mwm:"*FSR?"
        ENTER @Mwm;Cme
        OUTPUT @Mwm;":SYST:ERR?"
        ENTER @Mwm; Err_msq$
        PRINT Err_msq$
    UNTIL NOT BIT(Cme,2) AND NOT BIT(Cme,4) AND NOT BIT(Cme,5) AND POS(Err_msq$,"+0")
Subend:SUBEND
Set_ese:SUB Set_ese
    COM /Instrument/ @Mwm
    OUTPUT @Mwm;"*ESE ";IVAL("00110100",2)
SUBFND
Identity:DEF FNIdentity$;
    COM /Instrument/ @MwmV
    DIM Identity$[50]
    Identity$=""
    OUTPUT @Mwm;"*RST"
    OUTPUT @Mwm:"*OPC?"
    ENTER @Mwm;Opc_done
    OUTPUT @Mwm;"*IDN?"
```

ENTER @Mwm;Identity\$ RETURN Identity\$ FNEND

Measuring WDM Channels



To select a delta, drift, or signal-to-noise measurement, see Measuring Delta, Drift, and SNR.

The following example program measures the multiple laser lines of a WDM system. It measures both the power and wavelengths of each line. First, the program sets the Agilent 86122A in the single acquisition measurement mode. It then triggers the Agilent 86122A with the MEASure command to capture measurement data of the input spectrum. Because the data is stored in the instrument's memory, it can be queried as needed.

This example uses the <u>Set_ese</u>, <u>Error_msg</u>, <u>Err_mngmt</u>, and <u>FNIdentity function</u> subroutines.

```
COM /Instrument/ @Mwm
ASSIGN @Mwm TO 720
ON ERROR GOTO Error_msg,
Set ese
PRINT USING "37A,33A"; "Multi-Wavelength Meter Identity is: "; FNIdentity$
OUTPUT @Mwm;":INIT:CONT OFF"
ON TIMEOUT 7,5 CALL Err_mngmt
OUTPUT @Mwm;":MEAS:ARR:POW:WAV?"
ENTER @Mwm USING "#,K";Nb_wl
ALLOCATE Current_wl(1:Nb_wl)
ENTER @Mwm USING "#,K";Current_wl(*)
OUTPUT @Mwm;":FETC:ARR:POW?"
ENTER @Mwm USING "#,K";Nb_wl
ALLOCATE Current_pwr(1:Nb_wl)
ENTER @Mwm USING "#,K";Current_pwr(*)
FOR I=1 TO Nb wl
    PRINT USING "22A,2D,6A,4D.2DE,4A,S2D.2D,3A";"The wavelength number ";Current_wl(I);" at ";Current_pwr(I);"dBm"
NFXT I
OFF TIMEOUT
STOP
Error_msq:
    PRINT "the prgm is aborted due to: ";ERRM$
END
Err_mngmt:SUB Err_mngmt
    COM /Instrument/ @Mwm
    DIM Err_msq$[255]
    INTEGER Cme
    CLEAR 7
    REPEAT
        OUTPUT @Mwm; "*ESR?"
        ENTER @Mwm:Cme
        OUTPUT @Mwm; ":SYST:ERR?"
        ENTER @Mwm; Err_msg$
        PRINT Err_msg$
        UNTIL NOT BIT(Cme,2) AND NOT BIT(Cme,4) AND NOT BIT(Cme,5) AND Err$,"+0")
Subend:SUBFND
```

```
Set_ese:SUB Set_ese
    COM /Instrument/ @Mwm
    OUTPUT @Mwm; "*ESE";IVAL("00110100",2)
SUBEND

Identity:DEF FNIdentity$;
    COM /Instrument/ @Mwm
    DIM Identity$[50]
    Identity$=""
    OUTPUT @Mwm;"*RST"
    OUTPUT @Mwm;"*OPC?"
    ENTER @Mwm;Opc_done
    OUTPUT @Mwm;"*IDN?"
    ENTER @Mwm;Identity$
    RETURN Identity$
```

FNEND

Measuring WDM Channel Drift



To select a delta, drift, or signal-to-noise measurement, see Measuring Delta, Drift, and SNR.

The following example program measures the drift of channels in a WDM system. It measures drift in both power and wavelength of each line. First, the program sets the Agilent 86122A in the continuous-acquisition measurement mode. It then measures drift using commands from the CALCulate3 subsystem.

This example uses the <u>Error_msg</u>, <u>Set_ese</u>, <u>Err_mngmt</u>, <u>Cmd_opc</u>, <u>Tempo</u>, and <u>FNIdentity</u> function subroutines.

You will notice the use of the Tempo subroutine to pause the program for 10 seconds while the instrument measures the drift on the system.



The use of the Err_mngmt subroutine is optional. Err_mngmt was modified for the programming example to allow this subroutine to indicate the last command that was sent to the instrument before an error occurred.

COM /Instrument/ @Mwm
ASSIGN @Mwm TO 720
DIM Key\$[1]
ON ERROR GOTO Error_msg
Set_ese
PRINT USING "37A,33A";"Multi-Wavelength Meter Identity is: " ;FNIdentity\$
ON TIMEOUT 7,5 CALL Err_mngmt
Cmd_opc("*RST")
Cmd_opc(":INIT:IMM")
Cmd_opc("*OPC")
Cmd_opc(":CONF:ARR:POW:WAV")

! Turn on the drift calculation

Cmd_opc(":CALC3:DRIF:STAT ON")
Err_mngmt(":CALC3:DRIF:STAT ON")

! Turn off all drift states

Cmd_opc(":CALC3:DRIF:PRES")
Err_mngmt(":CALC3:DRIF:PRES")

! Turn on drift reference state

Cmd_opc(":CALC3:DRIF:REF:STAT ON")
Err_mngmt(":CALC3:DRIF:REF:STAT ON")

! Query the number of data points

OUTPUT @Mwm;":CALC3:POIN?" ENTER @Mwm USING "#,K";Nb_pt ALLOCATE Current_ref_wl(1:Nb_pt)

```
ALLOCATE Current_ref_pwr(1:Nb_pt)
! Query reference wavelengths and powers
OUTPUT @Mwm;":CALC3:DATA? WAV"
ENTER @Mwm USING "#,K";Current_ref_wl(*)
OUTPUT @Mwm;":CALC3:DATA? POW"
ENTER @Mwm USING "#,K";Current_ref_pwr(*)
! Turn off drift reference state
Cmd_opc(":CALC3:DRIF:REF:STAT OFF")
Err_mngmt(":CALC3:DRIF:REF:STAT OFF")
! Turn on drift max min calculation
Cmd_opc(":CALC3:DRIF:DIFF:STAT ON")
Err_mngmt(":CALC3:DRIF:DIFF:STAT ON")
Tempo(10)
ALLOCATE Current_diff_wl(1:Nb_pt)
ALLOCATE Current_diff_pw(1:Nb_pt)
! Query drift wavelengths and powers
OUTPUT @Mwm;":CALC3:DATA? WAV"
ENTER @Mwm USING "#,K";Current_diff_wl(*)
OUTPUT @Mwm;":CALC3:DATA? POW"
ENTER @Mwm USING "#,K";Current_diff_pw(*)
OFF TIMEOUT
FOR I=1 TO Nb_pt
    PRINT USING "18A,2D,6A,M4D.2DE,3A,21A,MDD.3DE,3A"; "Wavelength number"
    ;I;" is: ";Current_ref_wl(I);" m";" with a drift from: ";Current_diff_wl(I);" m"
    PRINT USING "28A, SDD.2DE, 4A, 20A, MDD.3DE, 3A, /";"it has a power level of
    : ";Current_ref_pwr(I);" dBm";" with a drift from : ";Current_diff_pw(I);" dB";
NEXT I
STOP
Error_msg: !
    PRINT "The program is aborted due to: ";ERRM$
END
Err_mngmt:SUB Err_mngmt(OPTIONAL Cmd_msg$)
    COM /Instrument/ @Mwmt
    DIM Err_msq$[255]
    INTEGER Cme
    CLEAR @Mwm
    REPEAT
        OUTPUT @Mwm:"*FSR?"
        ENTER @Mwm:Cme
        OUTPUT @Mwm;":SYST:ERR?"
```

ENTER @Mwm; Err_msg\$

```
IF NPAR>0 AND NOT POS(Err_msg$,"+0") THEN PRINT "This command ";Cmd_msg$;" makes the following error :"
        IF NOT POS(Err_msg$,"+0") THEN PRINT Err_msg$
    UNTIL NOT BIT(Cme,2) AND NOT BIT(Cme,4) AND NOT BIT(Cme,5) AND POS(Err_msg$,"+0")
Subend:SUBEND
Set_ese:SUB Set_ese
    COM /Instrument/ @Mwm
    OUTPUT @Mwm;"*ESE ";IVAL("00110100",2)
SUBEND
Identity: DEF FNIdentity$;
    COM /Instrument/ @Mwm
    DIM Identity$[50]
    Identity$=""
    OUTPUT @Mwm;"*RST"
    OUTPUT @Mwm;"*OPC?"
    ENTER @Mwm;Opc_done
    OUTPUT @Mwm;"*IDN?"
    ENTER @Mwm;Identity$
    RETURN Identity$
FNEND
Cmd_opc:SUB Cmd_opc(Set_cmd$)
    COM /Instrument/ @Mwm
    OUTPUT @Mwm;Set_cmd$
    OUTPUT @Mwm;"*OPC?"
    ENTER @Mwm;Opc_done$
SUBEND
Tempo:SUB Tempo(Temp)
    FOR I=Temp TO 0 STEP -1)
        DISP "Waiting for "; VAL$(I); " sec . . . "
        WAIT 1
    NEXTI
    DISP ""
SUBEND
```

Measuring WDM Channel Separation



To select a delta, drift, or signal-to-noise measurement, see Measuring Delta, Drift, and SNR.

The following example program measures the line separations on a WDM system. It measures separation (delta) between power and wavelength of each line using commands from the <u>CALCulate3</u> subsystem.

This example uses the <u>Error_msg</u>, <u>Set_ese</u>, <u>Err_mngmt</u>, <u>Cmd_opc</u>, and <u>FNIdentity function</u> subroutines.



The use of the Err_mngmt subroutine is optional. Err_mngmt was modified for the programming example to allow this subroutine to indicate the last command that was sent to the instrument before an error occurred.

COM /Instrument/ @Mwm
ASSIGN @Mwm TO 720
DIM Key\$[1]
ON ERROR GOTO Error_msg
Set_ese
PRINT USING "37A,33A";"Multi-Wavelength Meter Identity is : ";FNIdentity\$
ON TIMEOUT 7,5 CALL Err_mngmt
Cmd_opc("*RST")

! Change to list-by-wavelength display

Cmd_opc(":CONF:ARR:POW:WAV")

! Trigger and wait for one measurement

Cmd_opc(":INIT")
Cmd_opc("*WAI")

! Turn on delta mode

Cmd_opc(":CALC3:DELT:WPOW:STAT ON")

! Set first wavelength as reference

Cmd_opc(":CALC3:DELT:REF:WAV MIN")

! Query number of data points

OUTPUT @Mwm;":CALC3:POIN?"
ENTER @Mwm USING "#,K";Nb_pt
ALLOCATE Delta_wl(1:Nb_pt)
ALLOCATE Delta_pwr(1:Nb_pt)

! Query wavelengths and powers

OUTPUT @Mwm;":CALC3:DATA? WAV"

```
ENTER @Mwm;Delta_wl(*)
OUTPUT @Mwm:":CALC3:DATA? POW"
ENTER @Mwm;Delta_pwr(*)
OFF TIMEOUT
FOR I=1 TO Nb_pt-1
          PRINT USING "6A,2D,17A,M4D.3D,31A,S2D.2D,4A";"Line :";I;" wavelength is : ";(Delta_wl(I)+((NOT
          I=1)*Delta\_wl(1)))/1.0E-9;" nm. Absolute line level is : "; Delta\_pwr(I)+(NOT I=1)*Delta\_pwr(1);" dBm" level is : "; Delta\_pwr(I)+(NOT I=1)*Delta\_pwr(1);" dBm" level is : "; Delta\_pwr(I)+(NOT I=1)*Delta\_pwr(I)+(NOT I=1)*Delta_pwr(I)+(NOT I=1)*Delta_p
          PRINT USING "17A,2D,6A,M4D.3D,23A,2D,6A,S2D.2D,3A";"Delta WI to line ",I+1," is : ";(Delta_wI(I+1)-(NOT
         I=1)*Delta_wI(I))/1.E-9;" nm, Delta Pwr to line ",I+1," is : ";(I=1)*(Delta_pwr(I+1))+(NOT I=1)*(Delta_pwr(I+1)-Delta_pwr(I));"
          dB"
NEXT I
          PRINT USING "6A,2D,17A,M4D.3D,31A,S2D.2D,4A";"Line: ";I;" wavelength is: ";(Delta_wl(1)+Delta_wl(Nb_pt))/1.0E-9;"
         nm. Absolute line level is: ";Delta_pwr(1)+Delta_pwr(Nb_pt);" dBm"
STOP
Error_msq:!
          PRINT "The program is aborted due to: ";ERRM$
FND
Err_mngmt:SUB Err_mngmt(OPTIONAL Cmd_msg$)
          COM /Instrument/ @Mwmt
          DIM Err_msq$[255]
          INTEGER Cme
          CLEAR @Mwm
          RFPFAT
                    OUTPUT @Mwm:"*ESR?"
                    ENTER @Mwm:Cme
                    OUTPUT @Mwm:":SYST:ERR?"
                    ENTER @Mwm; Err_msq$
                   ": IF NPAR>0 AND NOT POS(Err_msg$,"+0") THEN PRINT "This command ";Cmd_msg$;" makes the following error:
                   IF NOT POS(Err_msg$,"+0") THEN PRINT Err_msg$
          UNTIL NOT BIT(Cme,2) AND NOT BIT(Cme,4) AND NOT BIT(Cme,5) AND POS(Err_msg$,"+0")
Subend:SUBEND
Set_ese:SUB Set_ese
          COM /Instrument/ @Mwm
          OUTPUT @Mwm;"*ESE ";IVAL("00110100",2)
SUBEND
Identity: DEF FNIdentity$;
          COM /Instrument/ @Mwm
          DIM Identity$[33]
          Identity$=""
          OUTPUT @Mwm;"*RST"
          OUTPUT @Mwm:"*OPC?"
          ENTER @Mwm;Opc_done
          OUTPUT @Mwm;"*IDN?"
          ENTER @Mwm;Identity$
          RETURN Identity$
FNEND
Cmd_opc:SUB Cmd_opc(Set_cmd$)
          COM /Instrument/ @Mwm
          OUTPUT @Mwm;Set_cmd$
```

OUTPUT @Mwm;"*OPC?" ENTER @Mwm;Opc_done\$ SUBEND

Measure Signal-to-Noise Ratio of Each WDM Channel



To select a delta, drift, or signal-to-noise measurement, see Measuring Delta, Drift, and SNR.

The following example program measures signal-to-noise ratio on a WDM system. It measures the ratio for each line using commands from the CALCulate3 subsystem.

This example uses the Error_msg, Set_ese, Err_mngmt, Cmd_opc, and FNIdentity function subroutines.



The use of the Err_mngmt subroutine is optional. Err_mngmt was modified for the programming example to allow this subroutine to indicate the last command that was sent to the instrument before an error occurred.

COM /Instrument/ @Mwm ASSIGN @Mwm TO 720 DIM Key\$[1] ON ERROR GOTO Error_msg, Set_ese PRINT USING "37A,33A"; "Multi-Wavelength Meter Identity is: "; FNIdentity\$ ON TIMEOUT 7,5 CALL Err_mngmt Cmd_opc("*RST") OUTPUT @Mwm;":MEAS:ARR:POW:WAV?" ENTER @Mwm USING "#,K";Nb_pt ALLOCATE Current_wl(1:Nb_pt) ENTER @Mwm USING "#,K";Current_wl(*) OUTPUT @Mwm:":FETC:ARR:POW?" ENTER @Mwm USING "#,K";Nb_pt ALLOCATE Current_pwr(1:Nb_pt) ENTER @Mwm USING "#,K";Current_pwr(*)

! Turn signal-to-noise ratio on

Cmd_opc(":CALC3:SNR:STAT ON")
Err_mngmt(":CALC3:SNR:STAT ON")

! Set first wavelength as noise reference

Cmd_opc(":CALC3:SNR:REF:WAV MIN")
Err_mngmt(":CALC3:SNR:REF:WAV MIN")

! Query number of data points

OUTPUT @Mwm;":CALC3:POIN?" ENTER @Mwm USING "#,K";Nb_pt ALLOCATE Snr_pwr(1:Nb_pt)

! Query signal-to-noise values

OUTPUT @Mwm;":CALC3:DATA? POW" ENTER @Mwm;Snr_pwr(*)

```
OFF TIMEOUT
FOR I=1 TO Nb_pt
    PRINT USING "7A,2D,17A,M4D.3D,25A,S2D.2D,22A,2D.2D,3A";"Line: ";|;" wavelength is: ";Current_wl(I)/1.0E-9;" nm,
    absolute level is: ";Current_pwr(I);" dBm, with a SNR of: ";Snr_pwr(I);" dB"
NEXTI
STOP
Error_msg: !
    PRINT "The program is aborted due to: ";ERRM$
END
Err_mngmt:SUB Err_mngmt(OPTIONAL Cmd_msg$)
    COM /Instrument/ @Mwmt
    DIM Err_msg$[255]
    INTEGER Cme
    CLEAR @Mwm
    REPEAT!
        OUTPUT @Mwm;"*ESR?"
        ENTER @Mwm;Cme
        OUTPUT @Mwm;":SYST:ERR?"
        ENTER @Mwm; Err_msq$
        IF NPAR>0 AND NOT POS(Err_msq$,"+0") THEN PRINT "This command ";Cmd_msq$;" makes the following error :"
        IF NOT POS(Err_msg$,"+0") THEN PRINT Err_msg$
    UNTIL NOT BIT(Cme,2) AND NOT BIT(Cme,4) AND NOT BIT(Cme,5) AND POS(Err_msg$,"+0")
Subend:SUBEND
Set_ese:SUB Set_ese
    COM /Instrument/ @Mwm
    OUTPUT @Mwm;"*ESE ";IVAL("00110100",2)
SUBEND
Identity: DEF FNIdentity$;
    COM /Instrument/ @Mwm
    DIM Identity$[50]
    Identity$=""
    OUTPUT @Mwm;"*RST"
    OUTPUT @Mwm;"*OPC?"
    ENTER @Mwm;Opc_done
    OUTPUT @Mwm;"*IDN?"
    ENTER @Mwm;Identity$
    RETURN Identity$
FNEND
Cmd_opc:SUB Cmd_opc(Set_cmd$)
    COM /Instrument/ @Mwmd
    OUTPUT @Mwm;Set_cmd$
    OUTPUT @Mwm;"*OPC?"
    ENTER @Mwm;Opc_done$
SUBEND
```

Increasing a Source's Wavelength Accuracy

The following example program uses the Agilent 86122A to increase the absolute wavelength accuracy of Agilent 8167A, 8168B, and 8168C tunable laser sources. Essentially, the Agilent 86122A transfers its accuracy to the tunable laser source.

For more information about the absolute accuracy of this instrument, refer to Specifications.



In order to run this program, the firmware of the tunable laser source must support the automatic alignment command, WAVEACT.

The example program uses the following measurement algorithm:

Identify and initialize the Agilent 86122A and tunable laser source

Ask user for desired wavelength

Set wavelength of tunable laser source

Turn tunable laser source's output on

Enter loop

Measure wavelength

Compare wavelength to desired wavelength

Realign tunable laser source's wavelength

Check if wavelength changed from last pass

Repeat until (delta wavelength < 0.0015 nm *or* wavelength is stable)

COM Current_wl,Diff_wl.Target_wl,Previous_diff,Diff_diff Current_wl=0 Diff_wl=0 Target_wl=0 Previous_diff=O Diff_diff=0

ASSIGN @TIS TO 724 ASSIGN @Mwm TO 720

! Initialize instrument

DIM Identity\$[50]
Identity\$=""
OUTPUT @TIs;"*CLS"
OUTPUT @TIs;"*IDN?"
ENTER @TLS;identity\$
PRINT "TLS IS A ";identity\$
OUTPUT @Mwm;"*RST"
OUTPUT @Mwm;"*CLS"
OUTPUT @Mwm;"*IDN?"
ENTER @Mwm;Identity\$
PRINT "MWM IS A ";identity\$

! Ask user for desired wavelength

INPUT "What wavelength (nm)do you wish to have", Target_wl Target_wl=Target_wl*1.0E-9
PRINT "the target wavelength is: "; Target_wl

! Set wavelength of tunable laser source

OUTPUT @TIs; ":WAVE ";VAL\$(Target_wl)
OUTPUT @TIs; ":OUTP ON"

! Enter realignment loop

REPEAT

OUTPUT @Mwm;":MEAS:SCAL:POW:WAV?"
ENTER @Mwm;Current_wl
PRINT "The current wavelength is : ";VAL\$(Current_wl)
Diff_wl=PROUND(ABS(Target_wl-Current_wl),-16)
PRINT "Diff between target & Current is (+ or -) : ";VAL\$(Diff_wl)
OUTPUT @TIs;":WAVEACT ";VAL\$(Current_wl)
Diff_diff=PROUND(ABS(Diff_wl-Previous_diff),-16)
PRINT "differential difference between two turn : ";VAL\$(Diff_diff)
Previous_diff=Diff_wl
UNTIL (Diff_wl<1.5*1.0E-12) OR (Diff_diff=0)

END

Returned Data Format

Review the following information to understand the returned data format from a query.

Measurements are returned as strings

All measurement values are returned from the Agilent 86122A as ASCII strings. When an array is returned, the comma character separates the individual values.

Determining the number of data points

When FETCh, READ, or MEASure is used (with ARRay specified), the first returned value indicates the total number of measurement values returned in the query.

If you use :CALCulate1:DATA?, :CALCulate2:DATA?, or :CALCulate3:DATA? to query data, first send :POINts? to determine the number of values returned in the string. The string does not contain a first value, which specifies the string length. This is shown in the following example:

OUTPUT 720;":CALCulate1:POINts?" ENTER 720;Length OUTPUT 720;":CALCulate1:DATA?" ENTER 720:Result\$

Correcting for elevation and vacuum

The Agilent 86122A contains an internal weather station that provides temperature and barometric pressure values. This allows the instrument to automatically correct for differences in elevation and temperature. Use:SENSe:CORRection:MEDium to select readings in air or vacuum.

Setting amplitude units

The default amplitude units are dBm. If you need measurements in watts, use :UNIT:POWer. When the Agilent 86122A is turned on, the amplitude units are automatically set to the units used before the instrument was last turned off.