

### Field Bill of Material (FBM)

Installation of Microcode Level F12720 and other Suffix On 3746-900 attached to 3745-XXA or on 3746-950 Alone With Service Processor Type 6275 (FC 5053), 7585-P02 (FC 5052), or 3172-P90 (FC 5021)

Written by: C. Vallee
Checked by: C. Franoux
Approved by: A.Badino
Reviewed by: R. Lympany

3746 PN 42L2446 FBM 1 of 36

EC F70015 17 MAY 1999

# **IBM** Installation Instructions

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	2 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



## **Before Installation (Steps 1-8)**

#### 1.0 Machines Affected

3746 Models 9X0

- With Service Processor Type: 6275 Model 56U or 83U (FC 5053), or 7585-P02 (FC 5052), or 3172-P90 (FC 5021)
- Without Microcode Level F12720.

Checkpoint: Check that the APPN EC level is F12721.000.

If level is not present you must upgrade the Service Processor and the 3746-9x0 according to this instruction.

Note: Refer to Chapter 3, Displaying the EC Level of Code in the Service Processor Installation and Maintenance (Based on 7585, 3172, and 9585), SY33-2120, or to Chapter 2, Displaying the EC Level of Code in the Service Processor and Network Node Processor Service User's Guide for service processor based on 6275.

#### 2.0 Related BMs and ECs

### 2.1 Prerequisites

None

### 2.2 Co-requisite

(Must be installed together)

None

### 2.3 Companion

(May be installed together)

None

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	3 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



#### 3.0 BMs to be Installed

FBM Title

42L2446 Installation of Microcode level F12720 on 3746-9x0 attached to

3745-XXA, and/or an 3746-950 stand-alone.

### 4.0 Preparation

- Familiarize yourself with the purpose and details of the installation instruction before negotiating machine time with the customer (refer to 7.0, "Installation Time" on page 5).
- Check all items listed on the BM(s) to determine that all parts have been received.
- Call your Support Center to obtain the Microcode Fixe(s) (MCF) to be installed with the new LIC.
  - Or, connect to **http://www.lagaude.ibm.com/3746pe** and download the mandatory fixe(s).
- · Obtain the maintenance password from the Customer.
- Ensure that both the 3745 and 3746-9x0, types and models, are registered in RETAIN (CCPF).

For U.S.A machines, please call the Raleigh Multiplexor Support Center and verify your machine's registration in CCPF for:

- The seven digit serial number of the 3745 and 3746-9x0 are correct.
- The three digit model designation for the 3745 and 3746-9x0 are correct.

## 4.1 Minimum Documentation Required

- MultiAccess Enclosure Installation and Maintenance (Starting from EC F12720) SY33-2124-01
- Service Processor Installation and Maintenance (based on 7585, 3172, or 9585) SY33-2120-01.

#### or

Service Processor Installation and Maintenance (based on 6275)
 SY33-2125-00, and Service Processor and Network Node Processor Service User's Guide SY33-2127.

PN 42L2446	EC F52322	EC F64822	EC F70015
4 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999



## 5.0 Programming

None.

### 6.0 Purpose and Description

Install the new level microcode level F12720.

- On the Service Processor, NNP(s) and MAE (if any), and
- Install on the 3746-9x0(s).

#### 7.0 Installation Time

The installation time depends on the number of 3746-9x0 and if any NNP and MAE are installed. In the case of multiple 3746-9x0 connected to a Service Processor, global maintenance window must be requested to the customer. This will allow the customer to upgrade the 3746-900, and/or the 3746-950. This global maintenance will be divided in up to 3 sub windows, one corresponding to each phase of the upgrade:

- 1. Phase 1 is used to upgrade the Service Processor, the NNP and the MAE (if any). The upgrades of the NNP and MAE are disruptive for the traffic running thru these units.
- 2. Phases 2 and 3, are used to update each 3746-9x0 machine attached to the Service Processor.

These phases are disruptive, but may be performed serially to avoid disrupting all machines at the same time.

The procedure used to reload the code is the 'LIC restore' and this procedure is disruptive for the traffic. Only the load of the code on the SP can be done while the traffic is still running.

- Nondisruptive operation estimated time: 3746-9x0/MOSS-E Code level upgrade on the Service Processor: 35 up-to 60 minutes for LIC install.
- Disruptive operation estimated times per 3746-9x0:
  - Update the NNP: about 45 minutes.
  - Update the MAE: about 30 minutes.
  - 3746-9x0 General IML: 6 minutes.
  - 3746-9x0 EEPROM Upgrade: 6 minutes.

FB/M Installed	Machine Hrs	System Hrs	CE Hour	Nbr of CE
42L2446	2 to 3	0.0	3	1

	PN 42L2446
FBM	5 of 36

EC F52322	EC F64822	EC F70015	
09 OCT 1998	19 MAR 1999	17 MAY 1999	



# 8.0 Tools/Materials Required

None

6	EC F52322
	09 OCT 1998



## **Installation (Steps 9-12)**

## 9.0 Safety

Not applicable.

### 10.0 Details of Installation

The largest configuration will be upgraded in 3 phases:

Phase 1: 3746-9x0/MOSS-E code level upgrade on the Service Processor as described in 10.1, "Procedure 1 - 3746-9x0/MOSS-E Code Level Upgrade."

Phase 2: Code level upgrade on the first 3746-9x0, as described in 10.3, "Procedure 2 - 3746-9x0 Code Level Upgrade.."

Phase 3: Code level upgrade on the second 3746-9x0 (if any), as described in 10.3, "Procedure 2 - 3746-9x0 Code Level Upgrade.."




Figure 1. Service Processor Maximum Configuration.

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	7 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



### 10.1 Procedure 1 - 3746-9x0/MOSS-E Code Level Upgrade

− Go To −

What is the EC level of the code currently installed on your SP?

- Microcode EC F12380 or above (microcode available on CD-ROM), go to 10.1.5, "Saving Configuration on Diskette" on page 11
- Any other EC level prior to F12380 (microcode available on OD) , go to 10.1.1, "Saving the Configuration on the Optical Disk."

### 10.1.1 Saving the Configuration on the Optical Disk

	1. If not already logged, enter the <b>Service Processor maintenance password</b> (default is IBM3745).
	2. Double click on the "Service Processor icon".
	3. Click on "Operation Management".
	4. Double click on "Manage Disks and Databases"
	5. Click on Save databases on optical disk radio button.
	6. Click on "OK" and follow the prompts.
	7. When prompted, Insert the optical disk.
	8. When completed, click on <b>OK</b> , then click on <b>"Cancel"</b> to exit from the function.
дΜ	ES Data Save Function.

### 10.1.2 Installing

 <ol> <li>Insert the Customer Data Migration diskette (PN 02L3850) in the Service Processor diskette drive.</li> </ol>
 2. Click on "Change Management".
 3. Double click on "Manage Microcode Fixes"
 4. Click on "OK" for use of PE function.
 <ol> <li>On Manage Microcode Fixes window, click on "View" (On function bar)</li> <li>Then, click on "Change directory path" (On pull down menu)</li> </ol>
6. On Change Directory Path window, enter A:\*.*. Then, click on "OK".

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	8 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



\_\_\_ 7. On **Manage Microcode Fixes** window, click on the **fixes** to be applied.

Driver	If LIC EC Level	Apply MCF
607	D2251X	MD22426.418
810	D2256X	MD22726.418
830	D4612X	MD22526.418
840	D4613X	MD22326.418

 8. Click on "File" (On the function bar).	Then, click on "Move" (On pull
down menu).	

 9. On the Move Microcode	Fix files window,	enter J:\MCF\.	Then, click on
"OK".			

:\MCF\	 	 	

\_\_ 10. On the **Change Directory Path** window, enter **J:\MCF\ALL**. Then, click on "**OK**".

1.\MCT\ALI		 
J:\MCF\ALL	 	 

\_\_ 11. Remove the diskette from the drive.


EC F52322	EC F64822	EC F70015	
09 OCT 1998	19 MAR 1999	17 MAY 1999	



\_\_ 12. On the Manage Microcode Fixes window, Click on the lines of the MCFs to be applied "MES-Data Migration", click on "Options" (On function bar).

Then, click on Activate microcode fix (On pull down menu).

\_\_ 13. Answer 'YES' to reboot and shutdown



#### 10.1.3 Verifying the MCF status.

6. Exit the Change Management functions

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	10 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



#### 10.1.4 Saving Customer Data on Diskette.

	1.	On the MOSS-E View window, click on Program.
	2.	Double click on <b>Log OFF MOSS-E</b> , then double click on <b>Log ON MOSS-E</b> .
—	3.	Insert the <b>backup</b> optical disk on the ODD (backup of the current microcode).
	4.	Double click on the "Service Processor object icon".
	5.	Click on "Functions to Use Under PE Guidance Only".
	6.	Double click on "Save Customized data on diskette"
	7.	When prompted, insert the <b>Configuration Parameters diskette</b> (PN 02L3427) (can be any blank 1.44 diskette) into the diskette drive.
		<b>Note:</b> Only <b>one</b> diskette is provided, if more than one diskette is required obtain an additional blank diskette (1.44Mb).
—	8.	Click on " <b>OK</b> " follow the prompts and wait for the following message 'operation is successfully completed'.
	9.	Click on "Close".
	10.	Remove the diskette and the optical disk.

Go to, 10.1.6, "Shutdown the Service Processor" on page 13.

### 10.1.5 Saving Configuration on Diskette

The following procedures must be done when coming from EC F12380 or above

1. Reboot the service processor by pressing simultaneously the Ctrl/Alt/Del keys.

2. For logging on, enter the Service Processor maintenance password (default is IBM3745).

3. Double click on the "Service Processor icon".

4. Click on "Operation Management".

5. Double click on "Manage Disks and Databases"

6. Click on Save database on diskette radio button.

7. Click on "OK" and follow the prompts.

8. When prompted, Insert the Configuration Parameters diskette (PN 02L3427) in the diskette drive.

Note: Only one Configuration Parameters diskette is provided, if more than one diskette is required, obtain an additional blank diskette (1.44Mb).

9. When completed, click on "OK" and remove the diskette.

3746 PN 42L2446 FBM 11 of 36

EC F52322	EC F64822	EC F70015	
09 OCT 1998	19 MAR 1999	17 MAY 1999	



Go to, 10.1.6, "Shutdown the Service Processor" on page  $13\ .$ 

		EC F52322			
FBM	12 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



#### 10.1.6 Shutdown the Service Processor

1. On the MOSS-E View window, click on Program.

2. Double click on shut-down, then enter the maintenance password (default is IBM3745), and click on OK.

3. When the pop-up appears saying shut down has completed, power OFF the Service Processor.

#### What is the type of your Service Processor?

6275

Go to 10.1.8, "LIC Installation" on page 14

7585-P02

- The **OD** drive is **installed**, Go to 10.1.7, "Removing the Optical Disk Drive (ODD) from a 7585."
- The OD drive is not installed and did you receive the FBM 25L4401?
  - YES, using the FBM 25L4401 install the MPA card then, Go to 10.1.8, "LIC Installation" on page 14.
  - NO, Go to 10.1.8, "LIC Installation" on page 14.

3172

- The CD is not installed (EC prior to F12380), install Service Processor Upgrade MES (FC 5051) FFBM 08J5516. Then, go to 10.1.8, "LIC Installation" on page 14
- The CD is installed on the SP (EC F12380 or F12380A), go to 10.1.8, "LIC Installation" on page 14

#### 10.1.7 Removing the Optical Disk Drive (ODD) from a 7585

	1. <b>On t</b>	he rear	side	of	the	ODD,	turn	OFF	the	power	switch	(0	)
--	----------------	---------	------	----	-----	------	------	-----	-----	-------	--------	----	---

- 2. Disconnect the ODD Power cord from the ac Outlet Distribution Box or from the wall ac outlet, and the other end from the rear side of the ODD.
- 3. On the rear side of the Service Processor, disconnect the signal cable from SCSI adapter (Position 3).
- 4. Remove the ODD. Then, pack it into the return box (PN 32H0346) provided with this FBM

Did you receive the FBM 25L4401?

- YES, using the FBM 25L4401, install the MPA card. Then, Go to 10.1.8, "LIC Installation" on page 14.
- NO, Go to 10.1.8, "LIC Installation" on page 14.

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	13 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	


### 10.1.8 LIC Installation

_	1.	Insert the Service Processor installation diskette:
		• PN 26L0236, if your SP is a 7585-P02 or a 3172-P90
		• PN 26L0456, if your SP is a 6275
	2.	Then, power <b>ON</b> the Service Processor and while the system is starting, insert the <b>CD-ROM</b> into the drive.
	3.	When the diskette is booted, follow the prompts on the screen.
	4.	Wait for a while several messages will appear: Build hardisk, reboot, format
		Note: If you get the following messages:
		SYS0627: Drive c: was improperly stopped. From the OS/2 command
		prompt, run CHKDSK with the /F parameter on the specified drive
		<ul> <li>SYS0318: Message file OSO001.msg cannot be found for message 1467</li> </ul>
		Ignore these messages and press enter to continue.
	5.	When prompted, Insert the Configuration Parameters diskette (PN 02L3427) in the diskette drive.
	6.	Wait for a while, when prompted insert the Service Processor installation diskette PN 26L0236 or 26L0456 in the diskette drive.
_	7.	Message: Number of bytesRemaining computed time goes to 00 mn 00s is displayed but wait and stays on for an extra 5 minutes until message: LIC Restoration has successfully completed is displayed. Then, press <b>Enter</b> to continue.
_	8.	When prompted remove the diskette from the diskette drive. Then, press <b>Enter</b> key and remove the CD.
_	9.	The system re-boot, wait for a while, click on <b>OK</b> button when the message <b>'Do you want to customize your SP'</b> is displayed.
		Note: If not prompted automatically, select the function 'SP customization' from the service processor configuration menu.
	10.	On the Service Processor (SP) Customization screen:
		<ul> <li>Click on every View Customize check boxes to verify the configura- tion parameters. With this level of code two new options are available:</li> </ul>
		a. A link definition for a <b>Java console</b> .
		<ul> <li>Note: This link is exclusive with the DCAF link/operation.</li> <li>According to your customer choice, select the option to define a DCAF or JAVA link.</li> <li>b. Screen resolution option (800x600 or 640x480)</li> <li>This option is only enabled for the screens which support this option. It is mandatory to select 800x600 when an MAE is installed.</li> </ul>


3746 PN 42L2446 EC F52322 EC F64822 EC F70015 FBM 14 of 36 09 OCT 1998 19 MAR 1999 17 MAY 1999
--



 Click on Modem type drop down list, then select (click on) the modem and connection type of the modem used. Then, click on Next>> button.




11. On the Customer Information Customization screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.






\_\_ 12. On the SP Time and Date Customization screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.




\_\_ 13. On the Service LAN Addresses screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.






\_\_ 14. On the Netview Link(s)/Reporting Customization screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.




\_\_ 15. On the Token-Ring 3270 Session Customization screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.






\_ 16. On the Retain Customization screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.



Which link have you selected in step 10 on page 14

- DCAF Link/Operations, go to step 17
- JAVA Link/Operations, go to step 18 on page 19
- \_\_ 17. On the DCAF Customization screen, verify the information recorded and make the necessary changes. Then, click on Next>> button.



Go to step 20 on page 21

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	18 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	




- \_\_\_ 18. On the **JAVA Customization** screen, enter/select the following options:
  - a. Click on NO to reject any incoming call.
  - Local Phone number which is the phone number of the modem connected to the SP.
  - c. The IP addresses of:
    - 1) The **PPP-server**. This is PPP address of the **service processor**.
    - 2) The PPP-client. This is PPP address of the remote station.

**Note:** These IP addresses must be in the same subnet than the IP addresses of the units connected to the service LAN.


d. The **DTE speed** which must set according to the type of the modem installed (use the helps for more details).

Then, click on Next>> button.




\_\_ 19. On JAVA Console Configuration screen, do not modify the passwords this the responsibility of your customer. Click on Next>> button.









\_\_ 20. On SP Customization Message screen, click on Close, then click on Yes button to validate your customization.



21. The Service Processor customization start, follow the progress on the following screen. wait until completion.



22. When completed, click on **OK** button.



\_\_ 23. If necessary, the Service Processor will reboot automatically, then you are prompted to log On the MOSS-E. Otherwise go to next step

**Note:** If an error occurs, note the displayed message and press **Enter**. Keep the diskette available for investigation (log files: EULHIERR.LOG, OUT\_BAK.1 and OUT\_BAK.2), stored on diskette and hard disk for PE.

#### Have you any NNP installed?

- YES, go to 10.1.9, "Upgrading the NNP(s) on 3746-9x0." on page 22.
- NO, go to 10.2.1, "Applying the Latest MCFs Received." on page 30.

		1
EC F52322	EC F64822	EC F70015
09 OCT 1998	19 MAR 1999	17 MAY 1999



## 10.1.9 Upgrading the NNP(s) on 3746-9x0.

	1.	
		On the MOSS-E View screen, double click on the 3746-9x0 icon.
—	2.	On the <b>3746-9x0 Menu</b> screen, click on <b>Network Node Processor (NNP) Management</b> .
	3.	Double click on Install/Remove/Change/Restore LIC/NNP.
	4.	Click on NNP-A, then click on Restore LIC on NNP.
	5.	When requested, insert the NNP installation diskette <b>PN 26L0237</b> in the SP then in the NNP diskette drive.
_	6.	Select the NNP type and follow the prompts until <b>Operation successfully completed</b> (Up to 45')
		<b>Note:</b> Click on OK to clear the alarm saying that the SP/APPN CP link has been lost.
	7.	Click on Close, then clear reconnection alarm.
_	8.	If installed, repeat on the above procedure on NNP-B; then, continue with next step.
	На	ave you a MAE installed?
•	N	IO go to 10.2.1 "Applying the Latest MCEs Bessived." on page 20
•	Y	<b>IO</b> , go to 10.2.1, "Applying the Latest MCFs Received." on page 30.
		(ES, are you migrating the MAE installed from FC 3000 to FC 3001?
		<b>ES</b> , are you migrating the MAE installed from <b>FC 3000</b> to <b>FC 3001</b> ?
		<ul> <li>TES, are you migrating the MAE installed from FC 3000 to FC 3001?</li> <li>NO, go to 10.1.10, "Installing the MAE" on page 23.</li> </ul>
		<ul> <li>TES, are you migrating the MAE installed from FC 3000 to FC 3001?</li> <li>NO, go to 10.1.10, "Installing the MAE" on page 23.</li> <li>YES, perform the following procedures in sequence:</li> <li>1 Verify the PN of the MAE system card plugged in your MAE. If the PN of the card is one of the following: 78H6297, 11J7464, or 89H8395, replace the card using the installation instructions PN</li> </ul>
		<ul> <li>TES, are you migrating the MAE installed from FC 3000 to FC 3001?</li> <li>NO, go to 10.1.10, "Installing the MAE" on page 23.</li> <li>YES, perform the following procedures in sequence:</li> <li>1 Verify the PN of the MAE system card plugged in your MAE. If the PN of the card is one of the following: 78H6297, 11J7464, or 89H8395, replace the card using the installation instructions PN 02L4064 then go to next step.</li> <li>2 Did your customer decide to remove the token-ring link</li> </ul>
		<ul> <li>TES, are you migrating the MAE installed from FC 3000 to FC 3001?</li> <li>NO, go to 10.1.10, "Installing the MAE" on page 23.</li> <li>YES, perform the following procedures in sequence:</li> <li>1 Verify the PN of the MAE system card plugged in your MAE. If the PN of the card is one of the following: 78H6297, 11J7464, or 89H8395, replace the card using the installation instructions PN 02L4064 then go to next step.</li> <li>2 Did your customer decide to remove the token-ring link between the MAE and the 3746-9X0?</li> <li>YES, using the installation instructions PN 26L0379, remove</li> </ul>

	l I	EC F52322 09 OCT 1998		EC F70015 17 MAY 1999		
--	-----	--------------------------	--	--------------------------	--	--



#### 10.1.10 Installing the MAE

- Double click on the "3746-9X0 object icon"
- 2. Click on "Multiaccess Enclosure Management".
- \_\_\_ 3. Now double click on Install/Remove/Change LIC on MAE.




Figure 2. Install Multiaccess Enclosure

- 4. What is the level of code that was installed on the SP hard disk:
  - F12430, click on Change LIC on MAE..., then go to step 8 on page 24.
  - Prior to F12430, click on Install MAE..., then go to step 5 on page 24.




Figure 3. Install Multiaccess Enclosure

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	23 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



\_\_\_ 5. Verify or enter the MAE IP address, then click on OK.




Figure 4. Service LAN Addresses

6. Click on Yes to record your parameters.




Figure 5. SP Customization Message

\_\_\_ 7. When completed, click on **OK**.




Figure 6. SP Customization Completed

8. The MAE code is now being installed (it takes about 10 mn), when completed click on Close.


3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	24 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



**Note:** After a few minutes, verify that the MAE link icon is **green** (polling the MAE does not start immediately to give the green icon).

#### 10.2 Installing the firmware

1. Double click on ASCII Console".



- 2. Press the **Reset** button on the MAE.
- \_\_ 3. Several window are displayed during tests. Wait until the Boot Information window is displayed.
- 4. Press **F1** when prompted (to prematurely terminate boot).
- 5. On the System Management Services window, select option 4 -Utilities, press Enter.




Figure 7. MAE

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	25 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



- \_\_\_ 6. Enter the Multiaccess Enclosure supervisory password when required: **2216**.
- \_\_\_ 7. Select **7. Update System Firmware** from the utilities panel, press **Enter**




Figure 8. MAE


**Attention:** Do not power off the multiaccess enclosure during the process of updating the firmware. If the update fails, the multiaccess enclosure will boot a backup firmware image. If this happens, repeat the update procedure to reload the onboard firmware image.

8. From the F/W Update Options menu, select 3. Use a Local Image File, then press Enter and follow the prompts.

PN 42L2446	EC F52322	EC F64822	EC F70015	
26 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	

3746






EC F52322	EC F64822	EC F70015	
09 OCT 1998	19 MAR 1999	17 MAY 1999	




9. Enter the Local File Name: c:\firm.ld, then press Enter

**Note:** If the firmware loaded on the MAE system card is at the same level as the firmware loaded on the SP hard drive, you will get the following message: "The firmware update file is at the same level as the system firmware. Firmware update cancelled. Press enter". Then go to 10.2.1, "Applying the Latest MCFs Received." on page 30, otherwise continue with the next step.



\_\_ 10. On confirmation window, press Y. Then when this window is displayed, press Enter.




	PN 42L2446
FBM	28 of 36


EC F52322	EC F64822	EC F70015	
09 OCT 1998	19 MAR 1999	17 MAY 1999	



\_\_\_ 11. When recovery image has been done, press **Enter**.



\_\_ 12. Several windows are displayed following by:




**Note:** Do not switch the system off. The process erases the old firmware and copies the new firmware into flash memory. If the machine is powered off before the process is complete, you will need to reload the firmware from the recovery image.

EC F52322	EC F64822	EC F70015	
09 OCT 1998	19 MAR 1999	17 MAY 1999	



13. A completed message appears when the firmware is updated.



- 14. Press Enter to restart the system.
- \_\_ 15. Press the **Space bar** to get the console.
- \_\_\_ 16. Then close the ASCII window.
- \_\_ 17. Using the installation instructions PN 02L1268, install the new hardware required to support FC 3001 when completed go to 10.2.1, "Applying the Latest MCFs Received.."

#### 10.2.1 Applying the Latest MCFs Received.

#### **Important**

Did you receive from your Support Center any MCFs to be installed on the new LIC?

No Go to 10.3, "Procedure 2 - 3746-9x0 Code Level Upgrade." on page 31

YES Apply the MCFs received according to procedure 'Handling the Microcode Fixes on the Licensed Internal Code' listed in the SPIM or Service User's Guide shipped with your SP.

End of Procedure 1, Go to 10.3, "Procedure 2 - 3746-9x0 Code Level Upgrade." on page 31.

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	30 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



## 10.3 Procedure 2 - 3746-9x0 Code Level Upgrade.

		Important
		Ask the Customer for a maintenance window on the 3746-9x0 with traffic deactivated.
10.3.1	3746-9x0	EEPROM Upgrade.  1. Click on 3746-9x0 Menu.
		2. Click on Change Management.
		3. Double click on <b>Upgrade/Downgrade EEPROM</b> .
		4. The <b>Upgrade Status</b> area will show the processors to be changed in reverse video.
		5. Click on <b>OK</b> to start the upgrade function, wait (up to 10 minutes) until the Upgrade Status is completed for each processor.
		6. Click on <b>Cancel</b> to leave the function.
10.3.2	Saving C	Configuration Parameters  1. Double click on the Service Processor icon.
		2. Click on Operation Management.
		3. Double click on Manage Disks and Databases.
		4. Use the radio button to select Save databases on diskette to save the configuration parameters. When prompted, insert Configuration Parameters diskette (PN 02L3427) into the diskette drive.
		5. Click on <b>OK</b> and wait for completion. If error, record the message and contact support.
		6. Remove the diskette, then click on <b>Cancel</b> to exit from the function.
10.3.3		Installation Parameters Diskettes Once you have upgraded the hardware of the machine, you have to regenerate the format on the Installation Parameters Diskettes using the following procedure: (Duration approximately 13 minutes)
		1. On the Service Processor menu, click on Configuration Management, click on Manage 3745/3746 Installation/Removal.
		2. On the Controller Installation menu, Click on the 3746-9x0 installed, ther Click on SAVE.
		Following pop up window confirming Saving Active CDF-E as Reference:
		3. Insert the <b>3746-900 installation parameters diskette (PN 17G5878)</b> of the 3746-9x0, then click on <b>OK</b> .
		4. On the third pop up screen confirming CDF-E saved to diskette, remove

			EC F64822		
FBM	31 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	

diskette as instructed, click on **OK**.



_	<ol><li>Perform the above saving procedure for the backup diskettes, then click on Cancel.</li></ol>
10.3.4 Performing	<ul><li>a General IML.</li><li>1. On the MOSS-E View screen, double click on the 3746-9x0 icon.</li></ul>
	2. On the <b>3746-9x0 Menu</b> screen, click on <b>Operation Management</b> .

### 4. On the Perform a General IML window, click on NO to start an IML

without diagnostic.

3. Double click on **Perform a General IML**; Then click on **Yes** button

#### Important Note

Following this installation of code you can get a lot of SRC/error messages about IP. Ignore these messages and using CCM re-activate the configuration currently in use. When opening or activating this configuration, take the option to migrate this configuration.

All the other configurations have to be migrated. This migration is done only once when opening or activating the configuration for the first time.

#### End of Procedure 2..

#### Is another 3746-9x0 installed?

- Yes, Go to 10.3, "Procedure 2 3746-9x0 Code Level Upgrade." on page 31.
- No, Go to 10.4, "Returning the Machine to Customer" on page 33.



### 10.4 Returning the Machine to Customer

If you are migrating a MAE from FC 3000 to FC 3001, read the following note.

**Note:** If your customer has decided to remove the Token-ring link between the MAE and the 3746-9X0 (no more APPN traffic between the MAE and 3746), ask him to update his configuration to remove the definition of the resources used for this link.

#### – Go To –

Before starting the installation of this EC, which level of code was installed on your SP?

- Microcode EC F12380X or above (microcode available on CD-ROM), go to 10.4.2, "Logging OFF from Service Processor." on page 35
- Any other EC level prior to F12380 (microcode available on OD), go to 10.4.1, "Adapter Code Loading per Processor Type.."

#### 10.4.1 Adapter Code Loading per Processor Type.


#### Note

This procedure is used to define which network routing protocol is loaded per processor type. If your customer do not want to specify this information, go to 10.4.2, "Logging OFF from Service Processor." on page 35 (All protocols will be loaded in all type of processors).


1. On the Service Processor menu, click on Configuration Management, then click on Manage 3745/3746 Installation/Removal



2. On the Controller Installation menu, select the 3746-9x0 by clicking on the <3746-9x0> line, then click on "Select Feature".




3. On the Feature Selection menu, click on OK.






4. According to the customer's requirement, On the Network Routing Protocol Selection Per Processor Type menu, disable or enable the protocol loaded per processor type, then click on OK button.



\_\_\_ 5. Read the information message, then click on "OK" button.



6. When completed, click on "OK" and perform a general IML to activate the feature installed, then go to 10.4.2, "Logging OFF from Service Processor."

#### 10.4.2 Logging OFF from Service Processor.

- On MOSS-E View window, click on Program.
- 2. Click on LOG OFF MOSS-E.

#### 11.0 Test Procedures

Not applicable.

## 12.0 Field Updating

None.

3746	PN 42L2446	EC F52322	EC F64822	EC F70015	
FBM	35 of 36	09 OCT 1998	19 MAR 1999	17 MAY 1999	



## After Installation (13-15)

### 13.0 Publications Update

None.

## 14.0 Parts Disposition

If during the installation of this EC you had to remove an optical disk drive, which is the property of IBM you MUST RETURN this Optical Disk Drive according to your local procedure.

The LIC (Optical Disk) is declared as Sensitive parts. Keeping the Master and Back-up Disks, RETURN all extra Optical disks to your local Branch office, to be returned to plant of Manufacturing HAVANT.

### 15.0 Machine Records

- Install updated machine history provided.
- Report the installation and quality according to the existing procedure.

End of instructions.

		-				
3746	PN 42L2446		EC F52322	EC F64822	EC F70015	
FBM	36 of 36	Ш	09 OCT 1998	19 MAR 1999	17 MAY 1999	