

**PAGE: 1/1** 

Model: Russian-C			Dat	te: 15-Dec-99	No.: RA265001
Subject: Quick dial problem				Prepared by: K. N	Miura
From: Technical	Services Dept., GTS Division				
Classification:	☐ Troubleshooting	☐ Part info	orma	tion Action	n required
1	☐ Mechanical	Electric	al	☐ Servi	ce manual revision
1	☐ Paper path	☐ Transm	it/rec	eive Retro	fit information
	☐ Other ( )				

#### **SYMPTOM**

In cases where the country code has been changed to France (00), the following error is displayed as soon as the quick dial key is selected:

"This destination is not available. Please check FAX number".

### **CAUSE**

The communication switch 06 bit 4 mode is a carryover from the previous model and is not used in the Russian-C1. However, the software activates the mode by changing the value from 0 to 1 when the country code is changed to 00. For modes that are carried over but not meant to be used, the software will normally not do this.

#### **SOLUTION**

After changing the country code to France (00) at installation, communication switch 06 bit 04 should be disabled by changing the value from 1 to 0.

As a permanent solution, a modified version (ver. 13.04) of the software has been released.



**PAGE: 1/4** 

Reissued: 29-Feb-00

Model: Russian-C Fax Option	Date: 31-Dec-99	No.: RA895001a
-----------------------------	-----------------	----------------

### **RTB** Correction

The items in bold italics have been corrected/added.

Subject: ROM History (Russian-C Fax Option)			Prepared by: M.Mano		
From: Technical	Services Dept., GTS Division				
Classification:	Troubleshooting	Part informa	tion	Action required	
		Electrical		Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	□ Retrofit information	
	Other ( )				

Firmware history for the Russian-C Fax Option.

- USA Model -

A2685582	File No. (A268Uxxx)	Version	C.SUM	Production
В	002	10.03	48D4	1st Mass Prod.
С	003	13.03	AE2E	December Prod. '99

### - European Model -

A2685584	File No. (A268Exxx)	Version	C.SUM	Production
С	103	10.03	2512	1st Mass Prod.
D	104	12.01	35B2	November Prod. '99
Е	105	13.03	A88A	December Prod. '99
F	106	13.04	1EDA	December Prod. '99
G	107	16.01	4C32	February Prod. '00

### - European 2nd Language -

A2685585	File No. (A268Exxx)	Version	
	200	12.01	E0B4
Α	201	13.03	0136
В	202	13.04	3C64
С	203	16.01	9112

### - European 3rd Language -

A2685586	File No. (A268Exxx)	Version	C.SUM
	300	12.01	BD3B
А	301	13.03	7265
В	302	13.04	EA5A
С	303	16.01	B4B1

#### - Asia Version -

A2685587	File No. (A268Axxx)	Version	C.SUM	Production
	000	10.03	87BE	1st Mass Prod.
A	001	13.03	34AB	December Prod. '99
В	002	13.05	8163	February Prod. '99



**PAGE: 2/4** 

Reissued: 29-Feb-00

Model: Russian-C Fax Option Date: 31-Dec-99 No.: RA895001a

	Symptom	Corrected			USA	EU	EU2	EU3	Asia/ TWN
The PC Fax Expander is not recognized (only for the Asia			-	-	-	-	В		
version).			-						
A ghost image m	ay appear on	the left of th	e page in JB	IG	-	G	С	С	-
direct transmissi									
(The page width		mes not rec	eived before						
making the page									
For CTR21 appro	•	_	•		-	G	С	С	-
(Communication									
were changed fro			•						
country code in l	France was ch	anged from	00 to 02 (UK	).					
Country Code	Comm SW06	G3 SW0B	G4i SW00						
Germany	bit 0 :0	bit 2 :0	-						
Austria	bit 1 :0	-	-						
Denmark	bit 3 :0	bit 5 :0	00000010						
France Switzerland	bit 5 :0	DIT 5 .U	-						
When using the		Transmissi	on function o	and	_	G	С	С	_
the rear side ima									
margin for the re									
left).	ai side is piac	ea on the m	giit (iiisteau (	or tire					
Quick Dial does no	ot work when th	ne country co	de is set to F	rance	-	F	В	В	-
If this problem occ				. a. 1001					
communication sw									
Conditions for prin					С	Е	Α	Α	-
This determines w			vill print out th	е					
incoming fax wher			•						
	Professional Station.								
User Paramete	r switch 31 bit	2							
0: Docume	ent not printed	1: Docur	ment will be p	rinted					
The German word					-	D	Α	Α	-
1.G3 Auto Sel.									
2.Etikett einf•ge	2.Etikett einf∙gen:progr.Wert -> Anweinf∙gen:progr.Name								
3.Etik.einf.:AUS -> Name einf.:AUS									
4.AnwProgr. Hauptmen -> AnwProgr.Hauptmen∙									
When the received CSI has only space data, it is ignored by this			В	С	Α	Α	""		
version of the firmware.									
Line Error Marks on the received page:			В	С	Α	Α	""		
A mark will be prin		•	•						
line error has occu		a, if the follov	ving bit is ena	bled.					
System switch									
0: Disabled	1: Enabled								



PAGE: 3/4

Reissued: 29-Feb-00

Model: Russian-C Fax Option Date: 31-Dec-99 No.: RA895001a

	Symptom Corrected			EU2	EU3	Asia/ TWN
	sure that the NSF/DIS signals (from the machine	В	С	Α	Α	66 39
that is to rece	ve the facsimile) will successfully be received by					
the sender, th	e transmission duration of these signals can now be					
extended as f	ollows:					
G3 switch	0F					
Bit 3 Bit 2	Settings					
0 0	32 seconds					
0 1	40 seconds					
1 0	50 seconds					
1 1	60 seconds					

PAGE: 4/4

Reissued: 29-Feb-00

Model: Russian-C Fax Option Date: 31-Dec-99 No.: RA895001a

С	H3491200001 ~
A2685582	A895-01

A2685584	A895-02
D	H3491003837~
E	H3491202306 ~
F	H3491202306 ~
G	TBA

A2685585	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	TBA

A2685586	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	TBA

A2685587	A895-03
Α	H3491202496 ~
В	H3400201122 ~



PAGE: 1/4

Model: Russian-C (Fax Option)

Date: 28-Apr-00

No.: RA265009

### **Number Correction, RTB Correction**

The bulletin number has been corrected. (RA895001 → RA265009)

The items in bold italics have been corrected or added.

Subject: ROM History (Russian-C Fax Option)		Prepared by: M.Mano		
From: Technical	Services Dept., GTS Division			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ( )	☐ Part informa☐ Electrical☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information

Firmware history for the Russian-C Fax Option USA Model

A2685582	File No. (A268Uxxx)	Version	C.SUM	Production
В	002	10.03	48D4	1st Mass Prod.
С	003	13.03	AE2E	December Prod. '99

#### European Model

	File No.			
A2685584	(A268Exxx)	Version	C.SUM	Production
С	103	10.03	2512	1st Mass Prod.
D	104	12.01	35B2	November Prod. '99
Е	105	13.03	A88A	December Prod. '99
F	106	13.04	1EDA	December Prod. '99
G	107	16.01	4C32	February Prod. '00
Н	108	18.00	BE30	April Prod. '00

### European 2nd Language

A2685585	File No. (A268Exxx)	Version	
	200	12.01	E0B4
Α	201	13.03	0136
В	202	13.04	3C64
С	203	16.01	9112
D	204	18.00	8720

### European 3rd Language

A2685586	File No. (A268Exxx)	Version	C.SUM
	300	12.01	BD3B
Α	301	13.03	7265
В	302	13.04	EA5A
С	303	16.01	B4B1
D	304	18.00	AAE2



PAGE: 2/4

Model: Russian-C (Fax Option)

Date: 28-Apr-00

No.: RA265009

### Asia Version

A2685587	File No. (A268Axxx)	Version	C.SUM	Production
	000	10.03	87BE	1st Mass Prod.
Α	001	13.03	34AB	December Prod. '99
В	002	13.05	8163	February Prod. '00
С	003	17.02	5C77	April Prod. '00
D	004	18.00	B27D	April Prod. '00



**PAGE: 3/4** 

Model: Russian-C (Fax Option)

Date: 28-Apr-00

No.: RA265009

Symptom Corrected (for older corrections, see previous	USA	EU	EU2	EU3	Asia/
RTBs)					TWN
When sending an original wider than the maximum paper	-	Н	D	D	D
width of the receiving machine (Auto-Reduction OFF / JBIG					
compression), the machine cuts the image to the smaller size but sends the left most area of the image instead of the					
central area.					
The symptom occurs only when the following software is					
used:					
European model: A2685584C (ver. 16.01)					
European 2 <sup>nd</sup> language: A2685585C (ver. 16.01)					
European 3 <sup>rd</sup> language: A2685586C (ver. 16.01)					
Asian model: A2685587D (ver. 17.02)					
Even though the following bit switch settings should disable	-	Н	D	D	D
the File Retention function, the machine retains files for 24					
hours:					
User Parameter switch 24 (swusr_18):					
(bit 1, bit 0) = (1, 0) When bit 4 of Communication switch 07 is 1 (Fallback from	_	Н	D	D	С
G4 to G3 when G4 communication fails on the ISDN B-		•			Ŭ
channel is enabled) and a G4 communication error occurs					
on the ISDN B-channel (ADF mode), the machine falls back					
to G3 and resumes transmission from the second page. This					
is because the first page has already fed out from the ADF.					
The PTT approval for Hungary has been passed.	-	Н	D	D	-
The following country code will be added for Hungary:					
22H (34)					
The following Chinese characters have been corrected for	-	-	-	-	С
the KANTAI display language:					
前頁 ,上一頁					
次頁 > 下一頁					
When using the Create Margin Transmission function and	-	G	С	С	С
the rear side image needs to be rotated 180 degrees, the					
margin for the rear side is placed on the right (instead of the left).					
A ghost image may appear on the left of the page in JBIG	-	G	С	C	С
direct transmission mode during dual operation.					
(The page width data is occasionally not received before					
making the page.)					

PAGE: 4/4

Model: Russian-C (Fax Option) Date: 28-Apr-00 No.: RA265009

A2685582	A895-01
С	H3491200001 ~

A2685584	A895-02
D	H3491003837~
Е	H3491202306 ~
F	H3491202306 ~
G	H3400200728 ~
Н	TBA

A2685585	A895-02
A	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	TBA

A2685586	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	TBA

A2685587	A895-03
Α	H3491202496 ~
В	H3400201122 ~
С	H3400404851 ~
D	TBA



PAGE:	1/1
-------	-----

Model: Russian-C (Fax Option)		e: 28-Apr-00		No.: RA265010		
Subject: V34 Modem ROM History (Russian-C SG3 Option)			Prepared by:	M.N	<i>l</i> lano	
From: Technical	Services Dept., GTS Division					
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion 🗌 Ad	ction	n required
	☐ Mechanical	☐ Electric	al	☐ Se	ervic	ce manual revision
☐ Paper path ☐ Transmit/rec		eive 🖂 Re	etrof	fit information		
	Other ( )					

Firmware history for the Russian-C SG3-V34 option.

Α	0334	885E	February Prod. '00
u 19	0331	6D4C	1st Mass Prod.
A8955590	Version	C.SUM	Production

Symptom Corrected	Version
A communication error occurs when the modem data is erased by a loader malfunction.	Α
The malfunction is caused by a buildup of static electricity.	
Note: * Panasonic modem only.	
* The loader is a function normally contained in the	
modem software that allows it to be overwritten to a newer version.	
To prevent this error, the manufacturer has removed the loader function from ROM version 0334.	
This function was also removed because the manufacturer does not	
intend to release any versions after 0334, as it has judged that the need will not arise in the field.	
As a result, customers who use an SG3 option with ver.0334 will need a technician to install a new SG3 board to update to the next version (if released).	

160	問
	Ш

**PAGE: 1/3** 

Model: Russian-C (Fax Option)		Date: 08-May-00		-00	No.: RA265011	
Subject: CTR21 Requirements			Prepared by: M.Mano		<i>l</i> lano	
From: Technical	Services Dept., GTS Division					
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	n required
l	☐ Mechanical	☐ Electrica	al		Service	ce manual revision
l	☐ Paper path	Transm	it/rec	eive	⊠ Retrof	fit information
l	Other ( )					

For European models, the following parameters <u>should not be changed from their default settings in the field</u>.

**REASON:** The default values for these parameters have been approved by CTR21 and/or EG201121. Therefore, a change in any one of these values would constitute a violation of these requirements.

### **Bit Switches**

Parameters	Descriptions
Communication switch 10	Memory transmission:
	Maximum number of dialing attempts to the same destination.
Communication switch 12	Memory transmission:
	Interval between dialing attempts to the same destination.



PAGE: 2/3

Model: Russian-C (Fax Option)

Date: 08-May-00

No.: RA265011

### RAM Addresses for Standard G3

Parameters	Descriptions
RAM Address: 680404	PSTN dial tone frequency upper limit (high byte)
RAM Address: 680405	PSTN dial tone frequency upper limit (low byte)
RAM Address: 680406	PSTN dial tone frequency lower limit (high byte)
RAM Address: 680407	PSTN dial tone frequency lower limit (low byte)
RAM Address: 680408	PSTN dial tone detection time
RAM Address: 680409	PSTN dial tone reset time (LOW)
RAM Address: 68040A	PSTN dial tone reset time (HIGH)
RAM Address: 68040B	PSTN dial tone continuous tone time
RAM Address: 68040C	PSTN dial tone permissible drop time
RAM Address: 68040D	PSTN wait interval (LOW)
RAM Address: 68040E	PSTN wait interval (HIGH)
RAM Address: 68044A	Time between opening or closing the DO relay and opening
	the OHDI relay
RAM Address: 68044B	Break time for pulse dialing
RAM Address: 68044C	Make time for pulse dialing
RAM Address: 68044D	Time between final OHDI relay closure and DO relay opening
	or closing
RAM Address: 68044E	Minimum pause between dialed digits (pulse dial mode)
RAM Address: 68044F	Time waited when a pause is entered at the operation panel
RAM Address: 680450	DTMF tone on time
RAM Address: 680451	DTMF tone off time
RAM Address: 680452	Tone attenuation level of DTMF signals while dialing
RAM Address: 680453	Tone attenuation value difference between high frequency
	tone and low frequency tone in DTMF signals
RAM Address: 680472	Acceptable ringing signal frequency: range1, upper limit
RAM Address: 680473	Acceptable ringing signal frequency: range1, lower limit
RAM Address: 680474	Acceptable ringing signal frequency: range2, upper limit
RAM Address: 680475	Acceptable ringing signal frequency: range2, lower limit
RAM Address: 680476	Number of rings until a call is detected
RAM Address: 680477	Minimum required length of the first ring
RAM Address: 680478	Minimum required length of the second and subsequent rings
RAM Address: 680479	Ringing signal detection reset time (LOW)
RAM Address: 68047A	Ringing signal detection reset time (HIGH)
RAM Address: 6804B4	PSTN: Tx level from the modem
RAM Address: 6804DA	T.30 T1 timer



PAGE: 3/3

Model: Russian-C (Fax Option) Date: 08-May-00 No.: RA265011

### **RAM Addresses for Optional G3**

Parameters	Descriptions
RAM Address: 680504	PSTN dial tone frequency upper limit (high byte)
RAM Address: 680505	PSTN dial tone frequency upper limit (low byte)
RAM Address: 680506	PSTN dial tone frequency lower limit (high byte)
RAM Address: 680507	PSTN dial tone frequency lower limit (low byte)
RAM Address: 680508	PSTN dial tone detection time
RAM Address: 680509	PSTN dial tone reset time (LOW)
RAM Address: 68050A	PSTN dial tone reset time (HIGH)
RAM Address: 68050B	PSTN dial tone continuous tone time
RAM Address: 68050C	PSTN dial tone permissible drop time
RAM Address: 68050D	PSTN wait interval (LOW)
RAM Address: 68050E	PSTN wait interval (HIGH)
RAM Address: 68054A	Time between opening or closing the DO relay and opening
	the OHDI relay
RAM Address: 68054B	Break time for pulse dialing
RAM Address: 68054C	Make time for pulse dialing
RAM Address: 68054D	Time between final OHDI relay closure and DO relay opening
	or closing
RAM Address: 68054E	Minimum pause between dialed digits (pulse dial mode)
RAM Address: 68054F	Time waited when a pause is entered at the operation panel
RAM Address: 680550	DTMF tone on time
RAM Address: 680551	DTMF tone off time
RAM Address: 680552	Tone attenuation level of DTMF signals while dialing
RAM Address: 680553	Tone attenuation value difference between high frequency
	tone and low frequency tone in DTMF signals
RAM Address: 680572	Acceptable ringing signal frequency: range1, upper limit
RAM Address: 680573	Acceptable ringing signal frequency: range1, lower limit
RAM Address: 680574	Acceptable ringing signal frequency: range2, upper limit
RAM Address: 680575	Acceptable ringing signal frequency: range2, lower limit
RAM Address: 680576	Number of rings until a call is detected
RAM Address: 680577	Minimum required length of the first ring
RAM Address: 680578	Minimum required length of the second and subsequent rings
RAM Address: 680579	Ringing signal detection reset time (LOW)
RAM Address: 68057A	Ringing signal detection reset time (HIGH)
RAM Address: 6805B4	PSTN: Tx level from the modem
RAM Address: 6805DA	T.30 T1 timer



Model: Russian-C (Fax Option)		Date: 10-Jul-00		00	No.: RA265016	
Subject: Manual Correction - LCT Paper Feed Selection		Prepared by: M. Mano			Mano	
From: Technical Services Dept., GTS Division						
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ( )	☐ Part info	al		Service	n required be manual revision fit information

This RTB explains two Service Manual corrections and the solution to a related symptom.

#### ■ Please correct your Service Manuals as follows:

**1. 6800CF(H)** - **User Parameter SW 15 (SWUSR\_0F) bits 0, 1 and 2, page 4-87:** The setting option labeled as "1 0 1 LCT" was mistakenly included. This should be <u>deleted</u>.

#### 2. Printer Switch 02, page 4-37:

LCT Usage for fax printing (bit 4) was also a misprint. Bit 4 should be 'Not used' (the same as bits 5 to 7). In addition, bit 2 should read as follows:

#### Old:

Bit No	FUNCTION
2	3rd paper feed station usage for fax printing  0: Enabled  1: Disabled

#### New:

Bit No	FUNCTION
2	3rd paper feed station usage for fax printing (includes
	LCT)
	0: Enabled
	1: Disabled

These corrections are necessary because the option installed just under the mainframe (LCT or Paper Feed Tray 1) is always recognized as Tray 3. Therefore, to enable or disable fax printout with these switches, Tray 3 must be selected.

#### Related symptom and solution:

#### Symptom:

Paper feed from the LCT is not possible with the fax application even if the LCT is selected for fax printout with User Parameter SW 15 (SWUSR 0F), page 4-87.

#### Solution:

As described above, select Tray 3 to enable fax printout from the LCT.

# Technical Bulletin

**PAGE: 1/4** 

Reissued: 25-Aug-00

#### **RTB Correction**

The items in bold italics have been corrected or added.

no home in bola hance have been corrected of added.				
Subject: ROM History (Russian-C Fax Option)		Prepared by: M.Mano		
From: Technical	Services Dept., GTS Division			
Classification:	<ul><li>☐ Troubleshooting</li><li>☐ Mechanical</li><li>☐ Paper path</li></ul>	☐ Part informa☐ Electrical☐ Transmit/rec	Service manual revision	
	Other ( )		Retront information	

Firmware history for the Russian-C Fax Option USA Model

A2685582	File No. (A268Uxxx)	Version	C.SUM	Production
В	002	10.03	48D4	1st Mass Prod.
С	003	13.03	AE2E	December Prod. '99
D	004	21.00	FFEE	August Prod. '00

#### European Model

	File No.			
A2685584	(A268Exxx)	Version	C.SUM	Production
С	103	10.03	2512	1st Mass Prod.
D	104	12.01	35B2	November Prod. '99
Е	105	13.03	A88A	December Prod. '99
F	106	13.04	1EDA	December Prod. '99
G	107	16.01	4C32	February Prod. '00
Н	108	18.00	BE30	April Prod. '00

#### European 2nd Language

	File No.		
A2685585	(A268Exxx)	Version	
	200	12.01	E0B4
Α	201	13.03	0136
В	202	13.04	3C64
С	203	16.01	9112
D	204	18.00	8720

### European 3rd Language

A2685586	File No. (A268Exxx)	Version	C.SUM
	300	12.01	BD3B
А	301	13.03	7265
В	302	13.04	EA5A
С	303	16.01	B4B1
D	304	18.00	AAE2

# Technical Bulletin

**PAGE: 2/4** 

Reissued: 25-Aug-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009a

### Asia Version

A2685587	File No. (A268Axxx)	Version	C.SUM	Production
	000	10.03	87BE	1st Mass Prod.
А	001	13.03	34AB	December Prod. '99
В	002	13.05	8163	February Prod. '00
С	003	17.02	5C77	April Prod. '00
D	004	18.00	B27D	April Prod. '00

# Technical Bulletin

**PAGE: 3/4** 

Reissued: 25-Aug-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009a

Symptom Corrected (new symptoms only - for older ones,	USA	EU	EU2	EU3	Asia/ TWN
see the older bulletins)					
The ICB-1 functions are available.	D	-	-	-	-
When the use of the PSTN-2 line is changed to Rx only, the	D	-	-	-	-
settings for PSTN-2 cannot be changed.					
The machine displays the clock for 12:xx as 0:xx	D	•	•	-	-
When a value more than 20H is input for the incoming signal	D	-	-	-	-
detection level (RAM address 6804BD), the minimum signal					
strength decreases.					
* The maximum value for this address is <u>1FH</u> .					
Even though the following bit switch settings should disable	D	Н	D	D	D
the File Retention function, the machine retains files for 24					
hours:					
User Parameter switch 24 (swusr_18):					
(bit1, bit0) = (1, 0)					
When using the Create Margin Transmission function and	D	G	С	С	С
the rear side image needs to be rotated 180 degrees, the					
margin for the rear side is placed on the right (instead of the					
left).					
A ghost image may appear on the left of the page in JBIG	D	G	С	С	С
direct transmission mode during dual operation.					
(The page width data is occasionally not received before					
making the page.)					

# Technical Bulletin

**PAGE: 4/4** 

Reissued: 25-Aug-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009a

A2685582	A895-01
С	H3491200001 ~
D	TBA

A2685584	A895-02
D	H3491003837~
E	H3491202306 ~
F	H3491202306 ~
G	H3400200728 ~
Н	H3400400875 ~

A2685585	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~

A2685586	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~

A2685587	A895-03
Α	H3491202496 ~
В	H3400201122 ~
С	H3400404851 ~
D	H3400404858 ~



**PAGE: 1/3** 

Reissued: 27-Sep-00

ividuel. Russiali-C   Date. 20-Api-00   INO RA200009t	Model: Russian-C	Date: 28-Apr-00	No.: RA265009b
---	------------------	-----------------	----------------

### **RTB Correction**

The items in bold italics have been corrected or added.

Subject: ROM History (Russian-C Fax Option)		Prepared by: M. Mano		
From: Technical	Services Dept., GTS Division			
Classification:	☐ Troubleshooting	Part informa	tion	Action required
	☐ Mechanical☐ Paper path	☐ Electrical ☐ Transmit/rec	eive	<ul><li>☐ Service manual revision</li><li>☐ Retrofit information</li></ul>
	Other ( )			

Firmware history for the Russian-C Fax Option USA Model

A2685582	File No. (A268Uxxx)	Version	C.SUM	Production
В	002	10.03	48D4	1st Mass Prod.
С	003	13.03	AE2E	December Prod. '99
D	004	21.00	FFEE	August Prod. '00

### European Model

	File No.			
A2685584	(A268Exxx)	Version	C.SUM	Production
С	103	10.03	2512	1st Mass Prod.
D	104	12.01	35B2	November Prod. '99
E	105	13.03	A88A	December Prod. '99
F	106	13.04	1EDA	December Prod. '99
G	107	16.01	4C32	February Prod. '00
Н	108	18.00	BE30	April Prod. '00
J	109	22.00	29 <i>AF</i>	September Prod. '00

#### European 2nd Language

A2685585	File No. (A268Exxx)	Version	C.SUM
	200	12.01	E0B4
Α	201	13.03	0136
В	202	13.04	3C64
С	203	16.01	9112
D	204	18.00	8720
Ε	205	22.00	9616

### European 3rd Language

A2685586	File No. (A268Exxx)	Version	C.SUM
	300	12.01	BD3B
Α	301	13.03	7265
В	302	13.04	EA5A
С	303	16.01	B4B1
D	304	18.00	AAE2
Ε	305	22.00	039C



**PAGE: 2/3** 

Reissued: 27-Sep-00

Model: Russian-C	Date: 28-Apr-00	No.: RA265009b
------------------	-----------------	----------------

Asia Version

A2685587	File No. (A268Axxx)	Version	C.SUM	Production
	000	10.03	87BE	1st Mass Prod.
A	001	13.03	34AB	December Prod. '99
В	002	13.05	8163	February Prod. '00
С	003	17.02	5C77	April Prod. '00
D	004	18.00	B27D	April Prod. '00

**PAGE: 3/3** 

Reissued: 27-Sep-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009b

Symptom Corrected	USA	EU	EU2	EU3	Asia/ TWN
When the use of the PSTN-2 line is changed to Rx only, the setting of PSTN-2 cannot be changed.	D	J	E	E	-
When over 20H is input for the incoming signal detection level (RAM address 6804BD), the minimum signal strength decreases.	D	J	E	E	-
The maximum value for this address is <u>1FH</u> .					

A2685582	A895-01
С	H3491200001 ~
D	TBA

H	H3400400875 ~ <b>TBA</b>
G	H3400200728 ~
F	H3491202306 ~
Е	H3491202306 ~
D	H3491003837~
A2685584	A895-02

A2685585	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~
E	TBA

A2685586	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~
E	TBA

A2685587	A895-03
Α	H3491202496 ~
В	H3400201122 ~
С	H3400404851 ~
D	H3400404858 ~

160	問
	Ш

<b>PAGE: 1/1</b>	
------------------	--

Model: Russian-C1			Dat	Date: 27-Sep-00		No.: RA265017
Subject: V34 ROM History (Russian-C SG3 Option)				Prepared by: M. Mano		
From: Technical Services Dept., GTS Division						
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	n required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	⊠ Retro	fit information
	☐ Other ( )					

Firmware history for the Russian-C SG3-V34 option

A8955580	Version	C.SUM	Production
Α	16	FE38	1st Mass Prod.
В	18	719C	April Prod. '00

Symptom Corrected	Version
The PTT approval for Hungary has been passed.	В
The following country code will be added for Hungary:	
22H (34)	
When over 20H is input for the incoming signal detection level (RAM	В
address 6805BD), the minimum signal strength decreases.	
The maximum value for this address is <u>1FH</u> .	



**PAGE: 1/5** 

Reissued: 23-Oct-00

Model: Russian-C	Date: 28-Apr-00	No.: RA265009c
------------------	-----------------	----------------

### **RTB Correction**

The items in bold italics have been corrected.

Subject: ROM History (Russian-C Fax Option)			Prepared by: M. Mano		
From: Technical	Services Dept., GTS Division				
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ( )	☐ Part informa☐ Electrical☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information	

Firmware history for the Russian-C Fax Option

- USA Model -

A2685582	File No. (A268Uxxx)	Version	C.SUM	Production
В	002	10.03	48D4	1st Mass Prod.
С	003	13.03	AE2E	December Prod. '99
D	004	21.00	FFEE	August Prod. '00

#### - European Model -

A2685584	File No. (A268Exxx)	Version	C.SUM	Production
С	103	10.03	2512	1st Mass Prod.
D	104	12.01	35B2	November Prod. '99
E	105	13.03	A88A	December Prod. '99
F	106	13.04	1EDA	December Prod. '99
G	107	16.01	4C32	February Prod. '00
Н	108	18.00	BE30	April Prod. '00
J	109	22.00	D0EA	September Prod. '00

#### - European 2nd Language -

A2685585	File No. (A268Exxx)	Version	C.SUM
	200	12.01	E0B4
Α	201	13.03	0136
В	202	13.04	3C64
С	203	16.01	9112
D	204	18.00	8720
E	205	22.00	0496

#### - European 3rd Language -

A2685586	File No. (A268Exxx)	Version	C.SUM
	300	12.01	BD3B
Α	301	13.03	7265
В	302	13.04	EA5A
С	303	16.01	B4B1
D	304	18.00	AAE2
Е	305	22.00	A262



**PAGE: 2/5** Reissued: 23-Oct-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009c

### - Asia Version -

	File No.				
A2685587	(A268Axxx)	Version	C.SUM	Production	
	000	10.03	87BE	1st Mass Prod.	
Α	001	13.03	34AB	December Prod. '99	
В	002	13.05	8163	February Prod. '00	
С	003	17.02	5C77	April Prod. '00	
D	004	18.00	B27D	April Prod. '00	



**PAGE: 3/5** 

Reissued: 23-Oct-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009c

Symptom Corrected	USA	EU	EU2	EU3	Asia/
Symptom Corrected  Nothing New Checksums at an 1 and n 2	00/1	LO		200	TWN
Nothing New – Only the Checksums etc on p 1 and p 2					
were changed	D	_	_	_	
ICB-1 function is available.	D	- J	- E	- E	-
When the use of the PSTN-2 line is changed to Rx only, the	U	J		E	-
setting of PSTN-2 cannot be changed.	D		_		
The machine displays the clock for 12:xx as 0:xx	D	J	E	E	-
When over 20H is input for the Incoming signal detection level	D	J		_	-
(RAM address 6804BD), the minimum signal strength decreases.					
* Maximum value for this address is <u>1FH</u> .		Н	D	D	D
When sending an original wider than the maximum paper width of	-	- ' '	"	D	D
the receiving machine (Auto-Reduction OFF / JBIG compression), the machine cuts the image to the smaller size but					
sends the left most area of the image instead of the central area.					
The symptom occurs only when the following software is used:					
European model: A2685584C (ver. 16.01)					
European 2 <sup>nd</sup> language: A2685585C (ver. 16.01)					
European 3 <sup>rd</sup> language: A2685586C (ver. 16.01)					
Asian model: A2685587D (ver. 17.02)					
Even though the following bit switch settings should disable the	D	Н	D	D	D
File Retention function, the machine retains files for 24 hours:					
User Parameter switch 24 (swusr_18):					
(bit1, bit0) = (1, 0)					
When bit 4 of Communication switch07 is 1 (Fallback from G4 to	-	Н	D	D	С
G3 when G4 communication fails on the ISDN B-channel is					
enabled) and G4 communication error occurs on the ISDN B-					
channel (ADF mode), the machine falls back to G3 and resumes					
transmission from the second page. This is because the first					
page has already exited from the ADF.					
The PTT approbal for Hangary has been passed.	-	Н	D	D	-
The following country code will be added for Hangary:					
22H (34)					
The following Chinese characters have been corrected for the	-	-	-	-	С
KANTAI display language:					
前頁,上一頁					
次頁 > 下一頁					
-	D	G	С	С	С
When using the Create Margin Transmission function and the rear side image needs to be rotated 180 degrees, the margin for	D	G			C
the rear side is placed on the right (instead of the left).  The ghost image may appear on the left of the page in JBIG	D	G	С	С	С
direct transmission mode during the dual operation.	ט	9			J
(The page width data is rarely not received before making the					
page.)					
PC Fax Expander is not recognized ( only for Asia version).	-	-	_	_	В
TO TAX Expanded to not recognized ( only for Asia version).					_



PAGE: 4/5

Reissued: 23-Oct-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009c

Symptom Correcte	ed	USA	EU	EU2	EU3	Asia/ TWN
(Communication SW06) are not used and were changed from "Enabled" to "Disabled"	For CTR21 approval, the unique dialing requirement (Communication SW06) are not used and their default setting were changed from "Enabled" to "Disabled". And G4 country code in France has been changed from 00 to 02 (UK).			С	С	-
Country Code         Comm SW06         G3 SW0           Germany         bit 0 :0         bit 2 :0           Austria         bit 1 :0         -           Denmark         bit 3 :0         -           France         -         bit 5 :0           Switzerland         bit 5 :0         -	- - - 00000010 -					
Quick Dial is not working when the country of this problem occurs on old firmware, ple SW06 - bit4 from 1 to 0.		-	F	В	В	-
		С	Е	А	A	-
The German wording is wrong.  1.G3 Auto Sel> G3 Autom.Wahl  2.Etikett einf•gen:progr.Wert -> Anweinf•gen:progr.Name  3.Etik.einf.:AUS -> Name einf.:AUS  4.AnwProgr. Hauptmen -> AnwProgr.Hauptmen•			D	A	А	-
When the received CSI have only space data, it is ignored by this version firmware.			С	Α	Α	u 11
Line Error Marks on received page: A mark will be printed on the left edge of the page anywhere a line error has occurred in the data if following bit is enabled. System switch00 bit4			С	А	A	u 11
System switch00 bit4  0: Disabled 1: Enabled  In order to ensure that the NSF/DIS signals (from the machine that is to receive the facsimile) will successfully be received by the sender, the transmission duration of these signals can now be extended as follows:  G3 switch0F  Bit 3 Bit 2 Settings  0 0 32 sec  0 1 40 sec  1 0 50 sec  1 1 60 sec		В	С	A	A	и п

**PAGE: 5/5** 

Reissued: 23-Oct-00

Model: Russian-C Date: 28-Apr-00 No.: RA265009c

A2685582	A895-01
С	H3491200001 ~
D	TBA

A2685584	A895-02
D	H3491003837~
Е	H3491202306 ~
F	H3491202306 ~
G	H3400200728 ~
Н	H3400400875 ~
J	TBA

A2685585	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~
Е	TBA

A2685586	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~
Е	TBA

A2685587	A895-03
Α	H3491202496 ~
В	H3400201122 ~
С	H3400404851 ~
D	H3400404858 ~



**PAGE: 1/4** 

Reissued: 26-Dec-00

Model: Russian-C	Date: 02-Nov-00	No.: RA265009d
------------------	-----------------	----------------

#### **RTB Correction**

The items in bold italics have been corrected or added

The items in bold italics have been corrected or added.					
Subject: ROM History (Russian-C Fax Option)		Prepare	d by: M. Mano		
From: Technical	Services Dept., GTS Division				
Classification:	Troubleshooting	☐ Part informa	tion	Action required	
	☐ Mechanical	☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	□ Retrofit information	
	Other ( )				

Firmware history for the Russian-C Fax Option. USA Model

A2685582	File No. (A268Uxxx)	Version	C.SUM	Production
В	002	10.03	48D4	1st Mass Prod.
С	003	13.03	AE2E	December Prod. '99
D	004	21.00	FFEE	August Prod. '00
E	005	23.00	F50B	November Prod. '00

### European Model

	File No.			
A2685584	(A268Exxx)	Version	C.SUM	Production
С	103	10.03	2512	1st Mass Prod.
D	104	12.01	35B2	November Prod. '99
Е	105	13.03	A88A	December Prod. '99
F	106	13.04	1EDA	December Prod. '99
G	107	16.01	4C32	February Prod. '00
Н	108	18.00	BE30	April Prod. '00
J	109	22.00	29AF	September Prod. '00
K	00A	23.00	4775	November Prod. '00

### European 2nd Language

A2685585	File No. (A268Exxx)	Version	C.SUM
	200	12.01	E0B4
Α	201	13.03	0136
В	202	13.04	3C64
С	203	16.01	9112
D	204	18.00	8720
Е	205	22.00	0496
F	206	23.00	E608



**PAGE: 2/4** 

Reissued: 26-Dec-00

Model: Russian-C	Date: 02-Nov-00	No.: RA265009d
------------------	-----------------	----------------

### European 3rd Language

A2685586	File No. (A268Exxx)	Version	C.SUM
	300	12.01	BD3B
Α	301	13.03	7265
В	302	13.04	EA5A
С	303	16.01	B4B1
D	304	18.00	AAE2
Е	305	22.00	A262
F	306	23.00	FAD9

#### Asia Version

A2685587	File No. (A268Axxx)	Version	C.SUM	Production
	000	10.03	87BE	1st Mass Prod.
Α	001	13.03	34AB	December Prod. '99
В	002	13.05	8163	February Prod. '00
С	003	17.02	5C77	April Prod. '00
D	004	18.00	B27D	April Prod. '00



**PAGE: 3/4** 

Reissued: 26-Dec-00

Model: Russian-C Date: 02-Nov-00 No.: RA265009d

Symptom Corrected (new ones only; for old ones, see older RTBs)	USA	EU	EU2	EU3	Asia/ TWN
The machine transfers messages received by G4 polling reception to the ICB-1.	E	K	F	F	-
The RTC detection conditions have been changed from 3 to 2 EOL signals.	E	K	F	F	-
ICB-1 function is available.	D	K	F	F	-

PAGE: 4/4

Reissued: 26-Dec-00

Model: Russian-C	Date: 02-Nov-00	No.: RA265009d
------------------	-----------------	----------------

A2685582	A895-01
С	H3491200001 ~
D	H3400800018 ~
E	TBA

A2685584	A895-02
D	H3491003837~
Е	H3491202306 ~
F	H3491202306 ~
G	H3400200728 ~
Н	H3400400875 ~
J	TBA
K	TBA

A2685585	A895-02
A	H3491202306 ~
B	H3491202306 ~
С	H3400200728 ~
	H3400400875 ~
<u>E</u>	TBA
F	TBA

A2685586	A895-02
Α	H3491202306 ~
В	H3491202306 ~
С	H3400200728 ~
D	H3400400875 ~
E	TBA
F	TBA

A2685587	A895-03
Α	H3491202496 ~
В	H3400201122 ~
С	H3400404851 ~
D	H3400404858 ~

# RIGOH

### Technical Bulletin

**PAGE: 1/1** 

Reissued: 29-Jul-02

Model: Russian-C	Date: 27-Sep-00	No.: RA265017a

### RTB Correction

The items in bold italics have been corrected or added.

Subject: V34 RO	M History (Russian-C SG3 Op	Prepared by: M.Mano		
From: Technical	Services sec. Service Planning			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ( )	☐ Part informate ☐ Electrical ☐ Transmit/rec		<ul><li>☐ Action required</li><li>☐ Service manual revision</li><li>☑ Retrofit information</li></ul>

Firmware history for the Russian-C SG3-V34 option.

A8955580	Version	C.SUM	Production
Α	16	FE38	1st Mass Prod.
В	18	719C	April Prod. '00
С	20	D444	December Prod. '00
D	21	2170	January Prod. '01
E	23	DDF2	June Prod. '02

Symptom Corrected	Version
1 <sup>st</sup> lot of mass production for the Uranos-C1 SG3 option.	Ε
Tx may be cancelled when sending a JBIG-compressed, well-log	E
original at Detailed resolution in V.34 mode.	
1 <sup>st</sup> lot of mass production for the Adonis-C2 SG3 option.	D
The machine sometimes freezes if an incoming fax is received while	D
transmitting.	
The machine does not try redialing following a polling reception error.	D
Tx/Rx with the 2 <sup>nd</sup> G3 line is disabled if an incoming fax is received	С
while transmitting. (However, other lines can be used, and the machine	
does not freeze.)	
The image at the bottom of the page may be disordered when receiving	С
JBIG-compressed data at Super Fine resolution.	
The PTT approval for Hungary has been passed.	В
The following country code will be added for Hungary:	
22H (34).	
When over 20H is input for the incoming signal detection level (RAM address	В
6805BD), the minimum signal strength decreases.	
* The maximum value for this address is <u>1FH</u> .	

# RIGOH

### Technical Bulletin

Model: Russian-C1 Date			Dat	ate: 2-Apr-04		No.: RA265030
Subject: System Switch 1E-4			Prepared by: Y. Ohtani			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ( )	☐ Part info	al		_ ⊠ Servic	n required ce manual revision fit information

Please apply the following description revision to your Russian-C1 Fax Service Manuals.

Pg. 4-28

Syst	em Switch 1E	SP No.1-101-031		
No	FUNCTION	COMMENTS		
4	This switch allows or prohibits all fax reception when Authorized Reception is enabled and no RTI/CSIs have been programmed.	This switch is only effective when Authorized Reception is enabled and there are no RTI/CSIs programmed.		
		Under these two conditions:		
	O: All fax reception is enabled  1: All fax reception is disabled	The default setting of "0" allows the machine to receive all incoming faxes. This is useful in cases where the customer has mistakenly enabled Authorized Reception with no RTI/CSIs programmed.		
		Setting this switch to "1" will cause the machine to reject all incoming transmissions.		