
| RIGOH | Technical Bulletin | | | No. RTB-014 | | |
|--|-------------------------------|------------------------|-------------|-----------------------------------|--|--|
| SUBJECT: FINISHER ENTRAN | ICE GUIDE | | | DATE:Jan. 31, '93 PAGE: 1 of 6 | | |
| PREPARED BY: S. MANO CHECKED BY: | | FROM: Copier | Techni | cal Support Section | | |
| CLASSIFICATION: Action Required Troubleshooting Retrofit Information | Revision of Information Other | service manual only | MOD F410 | EL: FINISHER | | |
| It has been reported that several sorter stapler (A377) entrance guide become deformed. (This is introduced in F400/F410 RTB No.13, please refer to it for details) Since the F400 finisher has the same type of guide plate, the entrance guide plate [A] is | | | | | | |
| separated from the finisher and kept in the accessory bag. This is implemented from the first February 1994 production machine. | | | | | | |

Whenever transporting the sorter stapler after taking out of the carton box, separate the guide plate from the finisher. Reset it just before you dock the finisher to the copier.

The installation procedure (accessory) has also been modified. Please refer to the following pages. Step #13 has been added. The other steps are the same as before.








No. RTB-014

SUBJECT: FINISHER ENTRANCE GUIDE

DATE:Jan. 31, '93 PAGE: 2 of 6

INSTALLATION PROCEDURE



CAUTION: Unplug the copier power cord before starting the following procedure.


- 1. Remove the strips of tape [A] and the cushion [B].
- 2. Open the front door and remove the strips of tape [C] and cushions [D].
- 3. Remove a clamp [E] (1 screw).
- 4. Slide out the staple unit [F].
- 5. Remove a strip of tape [G].




No. RTB-014

SUBJECT: FINISHER ENTRANCE GUIDE

DATE:Jan. 31, '93 PAGE: 3 of 6





- 6. Remove five plastic caps [A] on the copier's left cover.
- 7. Install the front connecting bracket [B] (2 screws– M4 x 12) and the rear connecting bracket [C] (2 screws– M4 x 12) on the copier.
- 8. Stick the entrance guide mylar [D] on the copier exit area as shown.

NOTE: Align the edge [E] of the cover and the mylar.




No. RTB-014

SUBJECT: FINISHER ENTRANCE GUIDE

DATE:Jan. 31, '93

PAGE: 4 of 6



9. Secure the protective earth wire [A]* (1 screw with spring washer) and the wire [B] (1 screw with spring washer).

NOTE*: For all models other than those intended for North America, the green wire is intended as a functional earth and should be connected as shown.

- 10. Connect the 4P connector [C] and the fiber optic connector [D].
- 11. Open the front door of the finisher and remove the screw [E] fixing the locking lever [F], then lower the locking lever.
- 12. Stick the cushions [G] (middle) [H] (short) [I] (long) as shown.

NOTE: Stick the cushion [G] on the metal stay (not on the cover). Align the upper edge of the cushion [H] with the edge of the stay [J]. Align the lower edge of the cushion [I] with the edge of the stay [K].

13. Install the entrance guide plate [L] (2 screws -M4 x 6).




No. RTB-014

SUBJECT: FINISHER ENTRANCE GUIDE

DATE:Jan. 31, '93

PAGE: 5 of 6



14. Align and press the finisher against the copier and fix them by raising the locking lever [A].

NOTE: At this time, confirm that the myler [B] locates between the guides [C].

- 15. Secure the locking lever [A] (1 screw).
- 16. Install the shift tray [D] with 4 screws M4 x 8. (Remove tape [E].)
- 17. Adjust the height of the copier by using the leveling feet [F] so that the difference in level [G] between the copier and the finisher will be 30 \pm 1 mm.




No. RTB-014

SUBJECT: FINISHER ENTRANCE GUIDE

DATE:Jan. 31, '93

PAGE: 6 of 6



18. Remove the green plastic clip [A] from the staple cartridge, and install the cartridge in the stapler.

NOTE: When installing the staple cartridge. Make sure that all the staple sheets [B] are in the initial position.

- 19. Plug in the copier.
- 20. Turn on the main switch of the copier and test the operation of the finisher.

NOTE: The copier recognizes automatically that the finisher is installed.

The stapler will not staple for the first 10 or so copies until the first staple comes to the proper position.

| Incorrect | |
|-------------------------------|--------------------------------------|
| Paper size Minimum: | 5 1/2" x 8 1/2" / <u>A5 sideways</u> |
| Weight: | 34.2 kg (75.4lb) |

 Correct Paper size Minimum: 5 1/2" x 8 1/2" / A6 lengthwise

Weight:

Page 1 of Finisher

35 kg (77.2lb)

SUBJECT: MANUAL CORRECTIONS

DATE: Jan. 31,'94 PAGE: 13 of 13

Page 2 of Finisher Staple position (2 staple)

Incorrect

$$b=5.20" \pm 0.12" (13.2 \pm 3 mm)$$

Correct

$$b=5.20" \pm 0.8" (132 \pm 2 mm)$$

Page 25 of Finisher Step #6


Incorrect

6. Remove the rear cover [G] (5 screws).


Correct

6. Remove the rear cover [G] (6 screws).

Page 29 of Finisher Illustration



Correct



Page 29 of Finisher Standard of item #1

Incorrect

Standard: 6mm deflection at $50 \pm 20g$ pressure

Correct


Standard: 6mm deflection at 180 ± 100g pressure

| RIGOH | Technical Bulletin | | | No. RTB-027 | | |
|---|--------------------|------------------------|---------|----------------------------------|--|--|
| SUBJECT: SC733 | | | | DATE:Mar. 15 '94 PAGE: 1 of 3 | | |
| PREPARED BY: S. MANO CHECKED BY: S. Hamano | | FROM: 2nd Ted | chnical | Support Section | | |
| CLASSIFICATION: Action Required Troubleshooting Retrofit Information | Revision of s | service manual only | MOD | EL: Finisher for F410 | | |

< POSSIBLE CAUSE - 1>

If the paper level actuator [A] is out of the position (See the illustration on page 2 of 3), the machine may sense that the shift tray [B] has not arrived at the proper level even though the shift tray [B] is at the maximum position (the stack height sensor 2 [C] is not actuated).

The fail safe mechanism (there is a safety switch [D] to detect the shift tray overrun condition) stops the shift tray lift motor from trying to raise the shift tray any more.



Under this condition, the machine indicates the "R2" jam indication. If the front door of the finisher is opened and closed and if the paper level actuator is still out of position, the machine indicates SC733.




No. RTB-027

SUBJECT: SC733 DATE: Mar. 15 '94

PAGE: 2 of 3

The paper level actuator may be out of the position under the following situation:

1) The customer places something (for example, book, copies, etc.) [A] on the shift tray, it pushes the actuator out of the position.



2) When the copy sets are delivered on the shift tray, the customer removes the copies. If the operator reaches for the copies from just in front of the operation panel the operator will not be able to see the actuator. It is possible for the operator to push the actuator out of position when removing the copies.

< countermeasure>

- 1. Instruct the customer to return the actuator to the correct position (so that the actuator becomes straight) and turn off then on the main switch.
- 2. The shift tray level actuator shape has been changed so that it cannot be bent easily. This modification will be implemented from April 1994 production.

We will issue a Modification Bulletin as soon as the cut-in serial number becomes available.



No. RTB-027

SUBJECT: SC733 DATE: Mar. 15 '94 PAGE: 3 of 3

< POSSIBLE CAUSE - 2>

If there is obstacle (for example, desk, chair, dust box etc.) below the shift tray and it prevents the shift tray from being lowered. The stack height sensor-1 [E] (See the illustration in page 1 of 3) cannot be actuated. In this case, SC733 occurs.

< countermeasure>

| Instruct the | e customer : | to remove | the o | bstacle | below | the | shift tray | and | then | turn | off | then | on |
|--------------|--------------|-----------|-------|---------|-------|-----|------------|-----|------|------|-----|------|----|
| the main s | witch. | | | | | | • | | | | | | |



No. RTB- 046

SUBJECT: SOFTWARE MODIFICATION

DATE: Dec. 31, '94 PAGE: 3 of 7

2. "B" version ROMs

From the following serial numbers, the EPROMs (A0965151A and A0965153A) on the main board have been updated to version "B".

NOTE: We will re-issue this RTB as soon as the cut-in serial number becomes available.

| Code | Serial Number |
|---------|---------------|
| A095-10 | 5204 |
| A095-15 | 264 |
| A095-17 | A3354 |
| 1095-22 | 5234 |
| A035-26 | 3D8 |
| A095-27 | A 3354 |
| A095-29 | A3354 |
| A096-10 | 5244 |
| A096-15 | 284 |
| A096-17 | A3364 |
| A096-22 | 5274 |
| A096-26 | 3D6 |
| A096-27 | A3364 |
| A096-29 | A3364 |
| A097 10 | |
| A027-15 | |
| .097-17 | |
| A097-22 | |
| A097-26 | |
| A097-27 | |
| A097-29 | |

Caution: Whenever replacing from the old main ROMs to the new version ROMs in the field, this modification is necessary.

The following are corrected by this software change:

2-1. Machine enters the screen saver mode during auto counting

If the time to enter the screen saver mode (this time can be changed by using User tools) comes during the auto count mode, the machine enters the screen saver mode. After counting all originals, the machine indicates the original jam condition.



No. RTB- 046

SUBJECT: SOFTWARE MODIFICATION

DATE: Dec. 31, '94

PAGE: 4 of 7

2-2. Operating time indication is incorrect

During operation, the time remaining before the end of the copy job is indicated by animation on the touch panel screen.

During the duplex mode by using RDH and Finisher, the indicated time was incorrect.

<Countermeasure>

For the single side original to duplex copy mode, it is impossible to calculate the time due to a highly complex operation using the alternate feed system. Therefore, in this mode, the operating time is not indicated.

For the duplex original to duplex copy mode, the accuracy of the indicated operation time has been improved.

2-3. RDH and Finisher, copy set limitation (maximum: 50 sets)

When using the RDH and Finisher, the selectable copy set for sort mode should be "999" (In the sort mode, due to the alternate feed operation, the paper stocked in the duplex tray is always less than 50 sheets). However, it was limited to 50. If a larger number was entered, it was canceled and "50" was displayed.

2-4. RDH and Finisher, Copier misfeed caused by the original misfeed

When an original exit jam occurs in the RDH, it should not cause a copier misfeed (the copier should exit all sheets in the copier then stop) but actually a misfeed also occurs in the copier. This symptom occurs depending on the copy tray selected and the size of the copy paper. (The combination of the longer paper path and shorter paper length tends to create this symptom.)