

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**33120A-05**

# S E R V I C E                      N O T E

Supersedes:  
NONE

33120A

Serial Numbers: MY40019072/MY40024190

**Front Panel or GPIB locks up after extended operation**

**To Be Performed By: Agilent-Qualified Personnel or Customer**

**Parts Required:**

P/N	Description	Qty.
1820-5562	U1201, SN74HC02D Quad 2-input NOR gate	1

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hour	
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Warranty	
AUTHOR: WOH                      PRODUCT LINE: PL9E			
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2003  
PRINTED IN U.S.A.



September 12, 2003

**Situation:**

After repeated use of commands sent through GPIB (< 16 hours), the Function Generator may not respond on GPIB or the front panel becomes completely inoperative. If a function generator within the above serial number range is sent repeated \*RST commands through GPIB (< 16 hours) and shows this behavior, then the defect is likely U1201 in the Display and Keyboard PC Assembly.

**Solution/Action:**Work around

In most cases recycling power on the function generator will temporarily restore operation.

Repair

Replace U1201 by replacing the PCB assembly 33120-66502. Caution: If attempting to obtain and replace U1201 independently. Observe that this is an SMT part and should only be repaired by a technician skilled in the repair of surface mounted components. Damage to the PC assembly can occur unless the proper tools are used to remove and replace the IC.