

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**54832B-07**

# S E R V I C E                      N O T E

Supersedes:  
None

## 54832B Infiniium Oscilloscope – 4 GSa, 4 Ch, 1 GHz

**Serial Numbers:**

**MY41002016**

**MY41002040**

**MY41002046 through MY41002050**

**MY41002053**

**MY41002054**

**MY41002056**

**MY41002061**

**MY41002062**

**MY41002072**

**MY41002073**

**MY41002076**

**Due to a manufacturing defect, a few probe interface boards may fail.**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
54810-66506	Probe Interface Board	1

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: KO     PRODUCT LINE: 1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004  
PRINTED IN U.S.A.



May 10, 2004

**Situation:**

Due to a manufacturing defect, a few probe interface boards may fail. The symptom will be that the oscilloscope will not ID probes correctly.

**Solution/Action:**

If the oscilloscope is under warranty, replace the probe interface board.

If the oscilloscope is out of warranty, verify that the serial number of the oscilloscope is listed on the first page of this service note. If the serial number is listed, then check the serial number on your warranty data base to see if the probe interface board was previously replaced.

If the probe interface board was previously replaced, then the customer pays for the replacement probe interface board. If the probe interface board was never replaced before, then replace the probe interface board and charge the cost of material and labor to extended warranty.