

S E R V I C E N O T E

SUPERSEDES: 6834A-03

6834A AC Power Source / Analyzer**Serial Numbers:**

6812A-06: 0000A00000 / 9999A99999
 6813A-06: 0000A00000 / 9999A99999
 6814A-02A: 0000A00000 / 9999A99999
 6834A-03A: 0000A00000 / 9999A99999
 6841A-01A: 0000A00000 / 9999A99999
 6842A-01A: 0000A00000 / 9999A99999
 6843A-01A: 0000A00000 / 9999A99999

Output Voltage Transient during Output Voltage Level Change**Duplicate Service Notes:** See Above**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

ROM, part number 5080-2390 Rev A.00.13
 ROM, part number 5080-2391 Rev A.00.13

Situation:

The AC source may randomly output a high voltage transient when being programmed from a high voltage level to a low voltage level. This random high voltage transient will only be generated if the programmed low voltage level is zero volts. The magnitude of the transient will be dependent upon programmed slew rate and waveform phase, the transient pulse width will be 200uS.

Continued

DATE: October 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 1.0 Hour	
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: BH	ENTITY: 2100	AGILENT RESPONSIBLE UNTIL: August 1998	
		ADDITIONAL INFORMATION:	

Solution/Action:

Replace ROMs U734 (p/n 5080-2390) and U735 (p/n 5080-2391) with Rev A.00.13 parts. The model number and ROM revision are displayed during power-on self test. If “Rev A.00.09” or lower is displayed the ROMs should be replaced.

To replace ROMs U734 and U735 with revision A.00.13 parts without destroying calibration data, perform the following:

- a. Disconnect AC mains power and remove top cover.

CAUTION

Static Sensitive Components. Use a static safe workstation.

- b. Carefully remove ROMs U734 and U735 from their sockets. These parts may be removed by gently prying them up from the corners with a sharp pointed tool such as a scribe. The socket is very fragile so use as little force as possible.
- c. Carefully install new ROMs and re-assemble unit (covers and AC mains cord).
- d. Turn instrument on.
- e. Turn calibration mode on: Press SHIFT (blue key) then 7 key, when CAL ON 0.0 is displayed, press ENTER.
- f. Press 0 and 9 keys simultaneously, then use command scroll keys to scroll till ROMUPD model # is displayed.
- g. Use command parameter keys to scroll till display reads ROMUPD 6834A, press ENTER.

If the commands are successful, the unit will go through a normal power-on sequence. If OUT OF RANGE is displayed, the unit will have to be re-initialized with the EEINIT command and re-calibrated. This can occur if non-volatile memory has become corrupted.

CAUTION

Be careful not to execute the EEINIT model # command when ROMUPD was intended in steps f and g or the unit will have to be re-calibrated.

Program the output voltage to 120 volts and check that the meter indicates the programmed value.

Software: A software solution is available until the ROM up-grade can be performed. Programming any voltage level except zero does not generate the high voltage transient. Program low voltage level to 0.1 volts, ie. VOLT:TRIG 0.1