


Mounting Instruction

SHV Cable Jack + Cable RG58

- 1) Remove the cable sheath



- 2) Push back the braided shield and strip the isolation from the center conductor




- 3) Push back the screen to the front end and twist it together




- 4) Put on the cable the screws, metal washer, clamping rubber and taper washer



- 5) Push back the braided shield and cut it along the outside of the taper washer



- 6) Solder the center contact



- 7) Push the parts together and screw them together

