

Field Feature Bill of Material

PN 43P1299

Installation of 3746 Extended Functions 6 (FC 5813) on IBM 3746 Model 9X0.

Written by: M. Ardisson
Checked by: J. Combes
Approved by: D. Esteve
Reviewed by: A. Bowen

3746 PN 43P1299 EC H60001 17 OCT 2001

© Copyright IBM Corp. 2001

1



3746	PN 43P1299	EC H60001		
FFBM	2 of 12	17 OCT 2001		



Before Installation (Steps 1-8)

1.0 Machines Affected

IBM 3746 Model 9X0.

This feature should only be applied on the machine serial for which it is specified.

2.0 Related BMs and ECs

2.1 Prerequisites

(Must be installed prior to this installation)

- Service Processor must be Type 3 (EC F70078), or Type 4 (EC F70110), or upgrade to Type 3 or 4.
- Microcode Level must be EC H10030 or H10040.

Note: Refer to Step 2.2 for displaying the level of code.

• FC 5810 or 5811, and FC 5812 must be installed.

2.2 Displaying the Level of Code Installed

- 1. On MOSS-E View window, click on help.
- 2. On Help window, click on About
- On the MOSS-E View About window, click on Licenced Internal Code. On the window obtained the code EC number is displayed.
- 4. Click on Close, then OK to leave the function.

2.3 Concurrent ECs

(Must be installed together) None.

2.4 Companion ECs

(May be installed together) None.

3746	PN 43P1299	EC H60001		
FFBM	3 of 12	17 OCT 2001		



3.0 BMs to be Installed

Feature BM **Feature Name**

43P1299 3746 Extended Functions 6 (FC 5813)

4.0 Preparation

- 1. Familiarize yourself with the purpose and details of the installation instruction before negotiating machine time with the customer.
- 2. Verify that the password sheet Form (PN 43P1297) is received and provides the password needed to enable the software feature.
- 3. Obtain the Service Processor Maintenance Password from the customer.

5.0 Programming

3746 Models 900 and 950 have a new requirement on NCP.

For compatibility with current reporting of 3746-900 statistics to NPM, the newly available Licensed Internal Code (H10030) requires NCP Version 7 Release 3, or later, with APAR IR46303 (MVS/VM) or IR46304 (VSE). The NCP APAR must be applied before the installation of the new Licensed Internal Code. Otherwise, the reporting of all statistics related to 3746-900 resources controlled by NCP will be interrupted.

3746 Models 900 and 950 have a new requirement on NPM.

The newly available Licensed Internal Code (H10030) requires:

- For the reporting of active PU counts per TIC3
 - NPM Version 2 Release 4 with APAR OW37743 (PTF UW59877) at a minimum.
- For NNP utilization reporting to NPM:
 - NPM Version 2 Release 4, Release 5, or Release 6, with APAR number OW49510.
- For reporting to NPM of adapter processor utilizations via NNP
 - NPM Version 2 Release 4, Release 5, or Release 6, with APAR number OW47153.



6.0 Purpose and Description

These instructions allow you to install Extended Functions 6 on a 3746 with FC 5810 or FC 5811, **and** FC 5812 installed.

7.0 Installation Time

FFBM	Machine Hrs.	System Hrs.	Nbr of CEs
43P1299	0.5	0.0	1

8.0 Tools/Material Required

None.

3746	PN 43P1299	EC H60001		
FFBM	5 of 12	17 OCT 2001		



Installation (Steps 9-12)

9.0 Safety

	Not	applicable.
10.0	Details of	f Installation.
	_	Ensure that 3746-9x0 is powered ON and IML'ed.
	_	Ask the Customer to stop the traffic on the 3746-9x0.
10.1	Unlocking	the Extended Functions 6
	_	1. If not already logged, enter the Service Processor Maintenance Password (Default is IBM3745).
	_	2. Double click on the Service Processor object icon.
		3. Click on Configuration Management.
		4. Double click on Manage 3745/3746-9x0 Installation/Removal



5. On the Controller Installation menu: Click on the 3746-950 or the 3746-900NN, on which the feature should be installed, then Click on Select Feature button.




Figure 1. Controller Installation

3746	PN 43P1299	EC H60001		
FFBM	7 of 12	17 OCT 2001		



 6. On	the Features Selection display:
_	a. Click on the Extended Functions 6 (FC 5813) selection box.
_	b. Enter the corresponding password (The password is recorded on the form - PN 43P1297).
	c. Click on OK button.




Figure 2. Features Selection

- 7. On the Features selection successful message display:
 - · If an error is reported,
 - Note message and code, click on **OK**, then
 - Contact your support.
 - If no error is reported, click on **OK**

		_			
746	PN 43P1299		EC H60001		
FBM	8 of 12		17 OCT 2001		






Figure 3. Features Selection Successful Message

10.2	Activating the installed Feature
	1. From the MOSS-E View screen, double click on the Controller 3746-9x0 object icon, on which the feature has been installed.
	2. Click on Operation Management.
	3. Double click on Perform General IML .
10.2.1	Saving Configuration Parameters on Diskette 1. Double click on the service processor object icon.
	2. Click on Operation Management.
	3. Double click on Manage Disks and Databases.
	4. Click on Save databases on diskette, and click on OK.
	5. Insert the configuration parameters diskette (1.44 diskette, PN 02L3427) and follow the prompts.
	6. When the save is completed, click on Cancel to exit from the function.
10.3	Returning the Machine to the Customer
	 Inform the Customer or his representative, that the 3746-9x0 is now ready to support the Extended Functions 6.
	2. Tell the customer that the traffic can be started.
	 3. Give the customer one of the Extended Functions 6 password sheets (Form - PN 43P1297).
11.0	Test Procedures

-	 _	 _	 	_	 _	-

No test required.

3746	PN 43P1299	EC H60001		
FFBM	9 of 12	17 OCT 2001		



12.0 Field Updating

None.

3746	PN 43P1299
FRM	10 of 12

EC H60001		
17 OCT 2001		



After Installation (Steps 13-15)

13.0 Publications Update

File the second Extended Functions 6 password sheet in the SPIM binder (PN 29H4652).

14.0 Parts Disposition

Not applicable.

15.0 Machine Records

- Install the new MACHINE HISTORY supplied.
- Report installation and quality problems using existing procedures.

End of instructions.

3746	PN 43P1299	EC H60001		
FFBM	11 of 12	17 OCT 2001		



3746	PN 43P1299	EC H60001		
FFBM	12 of 12	17 OCT 2001		