佪	$\bigcirc$	ПП
B	W	朏

PAGE:	1	"
-------	---	---

Model: Model K3 Date			te: 1-Nov-02		No.: MH310001	
Modified Article: Parts Catalog Corrections					by: M.	Mano
From: Technical Services sec. Service Planning Dept.						
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	(	)
	☐ Part standardization	☐ Othe	r			

The currency symbol for the Euro has been added to the Mask ROM, and the Controller Board modified to accommodate this new part.

NOTE: Both the new board and new ROM should be replaced together as a set.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B5165750	B5165753	Controller Board	1	X/O	3	17	
G0565901	G0565903	Mask ROM – PCL	1	X/O	-	-	

#### **Cut-in Serial Numbers:**

From October '02: J5221000004~

തത	пп
GO	IHI
$\omega$	uu

PA	CI	F٠	1/	1
	·O	۰.	1/	

Model: Model K3 Date			e: 9-Jan-03		No.: MH310002		
Modified Article: Parts Catalog Corrections					by: M.	Mano	
From: Technical Services Sec. Service Planning Dept.							
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve		☐ To improve reliability		(	)
	☐ Part standardization	☐ Othe	r				

The following part has been modified to improve paper size detection reliability.

#### Mainframe (H310/H311)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H5193033	H3103392	Paper Size Sensor - Rear	1	X/O	21	4	

#### Optional PFU (H206)

		•						
0	ld part	New part	Description	Q'ty	Int	Page	Index	Note
n	umber	number						
H5	193033	H3103392	Paper Size Sensor - Rear	1	X/O	5	5	

	ועוו
	II n I
ישעשו	/UU

PA	G	E:	1	ľ


Model: Model K3 Date			⊖: 23-Jan-03		No.: MH310003	
Modified Article: Parts Catalog Corrections					by: M.	Mano
From: Technical Services Sec. Service Planning Dept.						
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliabilit		e reliability	(	)
	☐ Part standardization	☐ Othe	r			

To facilitate assembly, the hole in the Exit Guide shown below has been closed (with no change in function).

#### Mainframe (H310/H311)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3101196	H3101199	Exit Guide	1	X/O	15	22	

New Part: The shaded hole [A] is closed



佪	ጠ	ПП
G	w	Ш

Model: Model K3

Reason for

Modification:

Modified Article: Parts Catalog Corrections

From: Technical Services Sec. Service Planning Dept.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

## Modification Bulletin

Date: 23-Jan-03			3	No.: мн	310004
		Prepared	by: M.	Mano	
ept.					
☐ Vendor change			☐ To n	neet stand	ards
☐ To improve reliability			(	)	

**PAGE: 1/1** 

The following parts have been modified to ensure the harness is not pinched when the PFU is installed.

Other

#### Optional PFU (H206)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3103538	H3103539	Connector Bracket	1	X/O	9	5	
H3105289	H3105270	Upper Relay Harness	1	X/O	9	13	
11050199	11050487	Harness Clamp	1	X/O	9	101	

മ്പ	ПΠ
IGO	Ш

Model: Model K3 Date			e: 5-Mar-03		No.: MH310005				
Modified Article: Parts Catalog Corrections					Prepared by: M. Mano				
From: Technical Services Sec. Service Planning Dept.									
Reason for	□ Parts catalog correction □ Vendo		lor ch	ange	☐ To n	neet standards			
Modification: ☐ To facilitate assembly ☐ T		☐ To improve reliability		(	)				
I		☐ Othe	r						

The Function Decal has been changed to the one used on the S-F2 due to a Marketing request for standardization.

### NIC Fax Unit (H210)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3114112	H3114113	Function Decal	1	X/O	3	23	