| | | ПП |
|---|--------|----|
| K | [[당(0) | 惴 |

Technical **B**ulletin

| Model: Adonis-C | 2 Two Tray Finisher | | Dat | e: 26-Jun-01 | No.: RB003007 |
|------------------|------------------------------|-------------|--------|-----------------------|--------------------|
| Subject: Softwar | e Release Information | | | Prepared by: S. Tomoe | |
| From: Technical | Services Dept., GTS Division | | | | |
| Classification: | ☐ Troubleshooting | ☐ Part info | orma | tion | |
| | | ☐ Electric | al | ☐ Servi | ce manual revision |
| | ☐ Paper path | ☐ Transm | it/rec | eive 🗌 Retro | fit information |
| | ⊠ Other () | | | | |

PAGE: 1/1

Software history

| B3525701 | Version | C. SUM |
|----------|---------|--------|
| В | 4.10 | 27C8 |

| Symptom Corrected | |
|---|---|
| When one of the trays is full and paper is fed to the other tray, the tray does not lower. | |
| When the door is opened soon after a staple job has finished, the finisher does not signal the copier that there is paper in the staple tray. | |
| Corrects the suffix of the finisher software part number that is displayed on the LCD with the SP mode. | В |
| Wrong: B3525701P -> Correct: B3525701A | |