

# Hi-Fi Products Service Bulletin

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** HCD-H5/H150

**No.** 447

**Subject:** Part Number Correction - Reference No. 205,  
Tension Detection Lever

**Date:** September 13, 1995

**Symptom:**

(\*\*)

The part number listed on page 50 of the Service Manual for Ref # 205,  
Tension Detection Lever, is incorrect.

**Solution:**

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
205	TENSION DETECTION LEVER	3-358-286-01	3-358-251-01



Filename: HFP0447.SB  
Directory: J:\SBDOC\SEP95  
Template: C:\WINWORD\TEMPLATE\S\_BULL.DOT  
Title:  
Subject:  
Author: Hoyt Wing Lee  
Keywords:  
Comments:  
Creation Date: 09/13/95 11:14 AM  
Revision Number: 2  
Last Saved On: 09/13/95 11:14 AM  
Last Saved By: Hoyt Wing Lee  
Total Editing Time: 0 Minutes  
Last Printed On: 04/01/96 11:03 AM  
As of Last Complete Printing  
Number of Pages: 1  
Number of Words: 124 (approx.)  
Number of Characters: 710 (approx.)