

# Car Stereo Service Bulletin

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDX-51, CDX-51RF, CDX-71, CDX-71RF**No. 392****Subject:** Part Number Discrepancies: Lower Case & Spring Arm.**Date:** April 5, 1996**Symptom:****(\*\*)**

Parts different than those described in the service manuals were used in production, depending upon the model. Also, the lower case and spring arm assemblies used in the CDX-51RF and CDX-71RF are not being supplied as spare parts, therefore, when changing either of these parts the other must be changed at the same time.

**Solution:**

For the CDX-51 and the CDX-71, order the following part when replacing the spring arm assembly:

REF	DESCRIPTION	PART NUMBER
12	ARM (SPRING) ASSY	X-3370-157-1

For the CDX-51RF and the CDX-71RF, when *either* of the spring arm assemblies *or* the lower case needs to be replaced, order *both* of the part numbers shown below and replace both on the unit being repaired:

REF	DESCRIPTION	PART NUMBER
12	ARM (SPRING) ASSY (2 PCS. REQUIRED)	X-3370-157-1
3	CASE, LOWER	3-919-139-01

