

CDX-51/51RF

SONY[®] SERVICE MANUAL

*US Model
Canadian Model
AEP Model
UK Model
E Model*

SUPPLEMENT-1


File this supplement with the service manual.

Subject: Mechanism Deck Modification

(ENG-95012)


The mechanism deck was changed from MG-108K-132 to MG-108Z-132.
This supplement contains only a new type mechanism deck.
No circuit is changed, and therefore for electrical parts, please refer to the
CDX-51/51RF service manual (9-959-909-11) previously issued.

• New Type Discrimination




Former type: Eject motor (M601) is invisible.
New type : Eject motor (M601) is visible.

(3) MECHANISM DECK SECTION - 2
(MG-108Z-132)



(MG-108Z-132)



[illegible]