

Letters

Correction to "Field Theory Design of Rectangular Waveguide Broad-Wall Metal-Insert Slot Couplers for Millimeter-Wave Applications"

F. ARNDT, SENIOR MEMBER, IEEE, B. KOCH, H.-J. ORLOK,
AND N. SCHRÖDER

In the above paper,¹ the designation of the columns "Slot Lengths (mm)" of Tables I-IV should have read "Half Slot Lengths (mm)," as is indicated correctly in Fig. 1 of the paper, by

Manuscript received April 28, 1986.

F. Arndt is, and B. Koch, H.-J. Orlok, and N. Schröder were, with the Microwave Department, University of Bremen, Kufsteiner Str., NW 1, D-2800 Bremen 33, West Germany.

¹F. Arndt *et al.*, *IEEE Trans. Microwave Theory Tech.*, vol. MTT-33, pp. 95-104, Feb. 1985.

IEEE Log Number 8609600.




Fig. 1. Figure of Table I with correct designation of the slot lengths.

$z = l_1$, $z = 2l_1$, respectively, for the first slot. S_1, S_2, \dots , in the figure of Table I, therefore, should have read $2S_1, 2S_2, \dots$, as shown above.

The authors thank Dr. Rebollar, Universidad Politecnica de Madrid, Spain, for drawing our attention to this oversight.