

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**54832-01**

# S E R V I C E N O T E

Supersedes:  
NONE

54832B

Serial Numbers: **ALL**

**Error's in service manual 54830-97001.**

**Parts Required:**

P/N	Description	Qty.
NONE		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: [initials]      PRODUCT LINE: [product line]

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2001  
PRINTED IN U.S.A.



**Agilent Technologies**

January 14, 2002

**Situation:**

**Error in service manual 54830-97001.**

- 1. There is no CD-ROM removal Procedure. Use the procedure in the 54845B/46B service manual until revision comes out.**
- 2. External Trigger Sensitivity is as follows:**
  - a. Dc to 100MHz: 0.05x(signal range)**
  - b. 100MHz to 500MHz: 0.10x(signal range)**
- 3. Input Impedance (resistance) is as follows:**  
**50 Ohm:  $\pm$  1.0%**

**Solution/Action:**

There will be an updated manual release around May 2002. Until then just use this service note as your information to correct these errors.