

## S E R V I C E N O T E

SUPERSEDES: NONE

**6834B Three Phase AC Source****List mode On Phase A Affects Phases B and C****Serial Numbers:** 0000A00000 /9999Z99999**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

Reference	Description	Part Number
U734	ROM	5080-2390
735	ROM	5080-2391

**Situation:**

In some units, when phase A is programmed in list mode, phases B and C output the same waveform. Therefore, the programmed values of B and C are not represented at their respective outputs, but instead have a waveform identical to phase A.

**Solution / Action:**

Replace the firmware with revision A.00.16 or higher.

ATE: August 1998

DATE: August 1998

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 1 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: GS		ENTITY: 2100	
AGILENT RESPONSIBLE UNTIL: June 2000			
ADDITIONAL INFORMATION: None			