RICOH Modification Bulletin

Model: Triton-C1 E750 Controller	Date: 29-Jul-04	No.: MB728001

Modified Article: Parts Catalog Correction			Prepared by: Y. Ohtani
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ( )

Please correct your parts catalog as follows:

= Description correction = (no part number change)

Part number	Old Description	New Description	Q'ty	Int	Page	Index	Note
B728 5003	Memory (6LA96605100)		1		3	1	
		Control Board (6LA96605100)	1		3	1	
B728 5010	Control Board (C0-08231000)		1		3	3	
		Memory (C0-08231000)	1		3	3	
B728 5008	Harness (6LA96625000)		2		3	5	
		Fan Motor (6LA96625000)	2		3	5	

= Parts number correction =

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7285103	B7285013	System CD (6LA96681000)	1		3	6	

= Parts number addtion =

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B7288807	User Guide CD (6LA96673000)	1		3	12	
	B7288817	User Utility CD (6LA96672000)	1		3	13	

RICOH **M**odification **B**ulletin

Reissued: 24-Nov-04

Model: Triton-C1 EFI Controller	Date: 28-Oct-04	No.: MB728002a

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Service CD ROM			Prepared by: M. Tsuyuki
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ( )

Please correct your parts catalog as follows:

Old part number	New part number	Description	Q'ty	Int	Page	Index
B7285013	***B1865023***	System CD	1		3	6

Model: Triton-C1 EFI Controller (E-750)	Date: 12-Jan-05	No.: MB728003

Modified Article: CDs			Prepared by: M. Tsuyuki
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ( )

Old part number	New part number	Description	Q'ty	Int	Page	Index
B1865103	B7285033	System CD (6LA96658200) System CD (6LA96756000)	1	X/O	3	6
B7288807	B7288808	User Guide CD(6LA96673000) User Guide CD(6LA99673000)	1	X/O	3	12
B7288817	B7288818	User Utility CD(6LA96672000) User Utility CD(6LA99672000)	1	X/O	3	13

The new firmware for B728 has been released.
The CDs have been changed.
Please refer RTB No. RB186011 for details.

Cut-in Serial Numbers:

B728-17: K394110001~

RICOH **M**odification **B**ulletin

Model: Triton-C1 EFI Controller (E-750)	Date: 12-Jan-05	No.: MB728004

Modified Article: Interface Board for E850			Prepared by: M. Tsuyuki
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ( )

Old part number	New part number	Description	Q'ty	Int	Page	Index
	B7288002	E850 Interface Board	1		3	14

The interface board for E850 has been registered as a spare part.

RICOH **M**odification **B**ulletin **PAGE: 1/1**

Model: Triton-C1 EFI Controller (E-750)	Date: 25-Mar-05	No.: MB728005

Modified Article: Fan Motor			Prepared by: M. Tsuyuki
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ( )

Old part number	New part number	Description	Q'ty	Int	Page	Index
B7285011	B7285061	Fan Motor (E0-07104000) Fan Motor (G0-00353000)	1	X/O	3	4

Change: The material of the mounting screw was changed from plastic to metal.
Reason: To attach the fan motor to the controller board more securely.



RICOH

Modification Bulletin

Model: Triton-C1 EFI Controller (E-750)	Date: 25-Mar-05	No.: MB728006

Modified Article: Harness			Prepared by: M. Tsuyuki
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ( )

Old part number	New part number	Description	Q'ty	Int	Page	Index
B5285006	B7285056	Harness (6LA96623000) Harness (6LA96723000)	1	O/O	3	9
B7285007	B7285057	Harness (6LA96624000) Harness (6LA96724000)	1	O/O	3	10

Change/Reason: Parts standardization with another model.