USB Driver Installation

(1) Connect one end of a USB cord to your PC.

(2) Connect the other end of USB cord to the Communication Adapter.

(3) After connecting them properly, following balloon appears.

Found New Hardware

MODEL 8212USB

   * A figure shown below appears after following steps (4) to (13) complete.
     Step (4) to (13) will be repeated twice.

Found New Hardware

USB Serial Port

Installing ...

(4) (3) but after being indicated, the following figure is indicated. Click "Next".

Found New Hardware Wizard

Welcome to the Found New Hardware Wizard

This wizard helps you install a device driver for a hardware device.

To continue, click Next.

< Back   Next >   Cancel

(5) Select "Search for a suitablr driver for my device (recommended)", and click "Next".

(6) Check the box for "Specify location", and click "Next".

(7) Click "Browse...".

(8) Select a folder to download the file.
   Select "ftdibus" in the folder, and click "Open".

(9) It's confirmed that a chosen folder is indicated, and click "OK".

(10) Click "Next".

(11) In case that following window appears on Windows 2000, click "Yes".

(12) Install is completed when the wizard finishes. Click "Finish".

(13) When 2 being installed as shown in the lower figure, a driver was normally installed.

USB Driver Un-installation

When install of the USB driver is interrupted and reinstall cannot be
done, follow the procedure below and delete the existing driver, and
then install it again.

(1) Connect a PC and the instrument with a USB cord.
(2) Click the "Control Panel" in the Start menu.
(3) Click "System" in the Control panel.
(4) Then click "Device Manager".
(5) **Right click** on "MODEL 8212USB" in the Other devices
(6) Click "Uninstall" to uninstall the USB driver.

(7) Remove the USB cord connecting your PC and the instrument once, and connect them again.
(8) When "Found New Hardware Wizard" window appears, follow the
    procedures described at "USB Driver Installation" and install the driver.