Errata

Redundant Integrated Flight-Control/Navigation Inertial Sensor Complex

R. E. Ebner and J. G. Mark
Litton Systems, Inc., Woodland Hills, Calif.

THERE was an error in Eq. (6), which should read:

$$[A^T A] = \sum_{i=1}^{n} [P_i]^T [P_i] \tag{6}$$

Equation (8) was inadvertently omitted. It should read:

$$[A^T A] = \sum_{i=1}^{n} [P_i] \tag{8}$$