


SERVICE INTERPHONE SYSTEM

HAP
OCT 10/06

23-41-00
SECTION TITLE
PAGE 1

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23410003 REV 082

INTERPHONE INSTL-SVCE MAIN WHL WELL

FIGURE 3

23-41-00-03

HAP
OCT 10/06

23-41-00-03
PAGE 0

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

 BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
3			INTERPHONE INSTL-SVCE MAIN WHL WELL		
- 1	284A0820-1		INTERPHONE INSTL-SVCE POSITION DATA: MAIN WHL WELL FOR NHA SEE: 23-40-00-01	001030 201967	RF
- 1	MODREF243340		INTERPHONE INSTL-SVCE MODULE NUMBER: 284A0820-1 REV B POSITION DATA: MAIN WHL WELL	031200 968999	1
20	BACW10CR7		.WASHER		2
- 200	286A5355-002		WIRE BUNDLE ASSY	001001 006007	RF
- 200	286A5355-003		WIRE BUNDLE ASSY	002005 008028 201967	RF
- 200	286A5355-007		WIRE BUNDLE ASSY	101101 968971	RF
- 200	286A5355-008		WIRE BUNDLE ASSY	029043	RF
- 200	286A5355-012		WIRE BUNDLE ASSY	102105 972999	RF
- 200	286A5355-013		WIRE BUNDLE ASSY	044046 054100	RF
205	2J1865A		.JACK-INTPH WHEEL WELL SUPPLIER CODE: V82389 POSITION DATA: LH ELECTRICAL EQUIP NUMBER: D06011 WIRING DIAGRAM REF: 234111 OPTIONAL PART: BCREFD00032 V82389	001046 054105 201999	1
205	2J1659		.JACK-INTPH WHEEL WELL SUPPLIER CODE: V82389 POSITION DATA: LH ELECTRICAL EQUIP NUMBER: D06011 WIRING DIAGRAM REF: 234111	001046 054105 201999	1
- 300	286A5357-002		WIRE BUNDLE ASSY	001001 006007	RF

MISSING ITEM NUMBERS NOT APPLICABLE

- ITEM NOT ILLUSTRATED

HAP

23-41-00-03

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-00
FIG. 03
PAGE 1
JUN 15/09

BOEING
 737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
3					
- 300	286A5357-003		WIRE BUNDLE ASSY	002005 008043 101101 201971	RF
- 300	286A5357-004		WIRE BUNDLE ASSY	044046 054100 102105 972999	RF
305	2J1865A		.JACK-INTPH WHEEL WELL SUPPLIER CODE: V82389 POSITION DATA: RH ELECTRICAL EQUIP NUMBER: D06057 WIRING DIAGRAM REF: 234111 OPTIONAL PART: BCREFD00032 V82389	001046 054105 201999	1
305	2J1659		.JACK-INTPH WHEEL WELL SUPPLIER CODE: V82389 POSITION DATA: RH ELECTRICAL EQUIP NUMBER: D06057 WIRING DIAGRAM REF: 234111	001045 054103 201971	1
MISSING ITEM NUMBERS NOT APPLICABLE					

— ITEM NOT ILLUSTRATED


HAP

23-41-00-03

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-00
 FIG. 03
 PAGE 2
 JUN 15/09

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23410004 REV 082

INTERPHONE INSTL-REFUELING STA. OUTBD FIXED LE
FIGURE 4

23-41-00-04

HAP
OCT 10/06

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-00-04
PAGE 0

 BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
4			INTERPHONE INSTL-REFUELING STA. OUTBD FIXED LE		
- 1	284A0172-1		INTERPHONE INSTL-REFUELING STA. POSITION DATA: OUTBD FIXED LE FOR NHA SEE: 57-00-00-06	001030 201967	RF
- 1	MODREF85456		INTERPHONE INSTL-REFUELING STA. MODULE NUMBER: 284A0172-1 REV A POSITION DATA: OUTBD FIXED LE	031200 968999	1
5	BAC27DEX5385		.DECAL- PLACARD CONTENT: D6013		1
10	BAC27NEX0502		.DECAL- PLACARD CONTENT: INTERPHONE SERVICE		1
15	BACB30XD3K12		.BOLT		2
20	NAS1149D0316J		.WASHER		2
25	PLH53CD		.NUT SUPPLIER CODE: VF0224 SPECIFICATION NUMBER: BACN10YR3CD OPTIONAL PART: H52732-3CD V15653		2
30	284A3172-5		.SPACER		1
35	BACW10CR7		.WASHER		1
40	284A2172-2		.SUPPORT ASSY		1
45	BACG20ZC000190		..GROMMET		1
50	69B40302-7		..PLATE ATTACHING PARTS		1
- 55	BACR15BB3AD4C		..RIVET -----*-----		4
60	284A3172-4		..CHANNEL		1
- 200	286A1664-004		WIRE BUNDLE ASSY	001008 202967	RF
- 200	286A1664-005		WIRE BUNDLE ASSY	009009	RF
- 200	286A1664-006		WIRE BUNDLE ASSY	010011 201201	RF
- 200	286A1664-007		WIRE BUNDLE ASSY	012013 015027	RF
- 200	286A1664-009		WIRE BUNDLE ASSY	028030	RF
- 200	286A1664-021		WIRE BUNDLE ASSY	031035	RF
- 201	286A1664-028		WIRE BUNDLE ASSY	014014	RF
MISSING ITEM NUMBERS NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HAP

23-41-00-04

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-00
FIG. 04
PAGE 1
FEB 15/09

BOEING
 737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
4					
- 201	286A1664-034		WIRE BUNDLE ASSY	101101 968971	RF
- 201	286A1664-039		WIRE BUNDLE ASSY	036043	RF
- 201	286A1664-040		WIRE BUNDLE ASSY	102105 972999	RF
- 202	286A1664-042		WIRE BUNDLE ASSY	044046 054100	RF
205	2J1865A		.JACK- SUPPLIER CODE: V82389 ELECTRICAL EQUIP NUMBER: D06013 WIRING DIAGRAM REF: 234111 OPTIONAL PART: BCREFD00032 V82389	001046 054105 201999	1
205	2J1659		.JACK- SUPPLIER CODE: V82389 ELECTRICAL EQUIP NUMBER: D06013 WIRING DIAGRAM REF: 234111	001046 054105 201999	1
MISSING ITEM NUMBERS NOT APPLICABLE					

— ITEM NOT ILLUSTRATED


HAP

23-41-00-04

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-00
 FIG. 04
 PAGE 2
 JUN 15/09

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23410007 REV 004

ELECTRICAL INSTL AND ASSY-P5 AFT OVHD (COMMUNICATIONS ONLY)
FIGURE 7

23-41-00-07

HAP
OCT 10/06

23-41-00-07
PAGE 0

 BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
7			ELECTRICAL INSTL AND ASSY- P5 AFT OVHD (COMMUNICATIONS ONLY)	001036 201967	
- 1	233A3306-1		ELECTRICAL ASSY-P5 OVHD (COMMUNICATIONS ONLY) POSITION DATA: AFT FOR NHA/OTHER SYS DET SEE: 31-11-95-02A	001007	RF
- 1	233A3306-300		ELECTRICAL INSTL-P5 OVHD (COMMUNICATIONS ONLY) POSITION DATA: AFT FOR NHA/OTHER SYS DET SEE: 31-11-00-01C 31-11-00-01J	008027 201967	RF
- 1	233A3306-303		ELECTRICAL INSTL-P5 OVHD (COMMUNICATIONS ONLY) POSITION DATA: AFT FOR NHA/OTHER SYS DET SEE: 31-11-00-01C	028029	RF
- 1	233A3306-306		ELECTRICAL INSTL-P5 OVHD (COMMUNICATIONS ONLY) POSITION DATA: AFT FOR NHA/OTHER SYS DET SEE: 31-11-00-01C	030030	RF
- 1	MODREF82494		ELECTRICAL INSTL-P5 OVHD (COMMUNICATIONS ONLY) MODULE NUMBER: 233A3306-306 REV A POSITION DATA: AFT FOR OTHER SYS DETAILS SEE: 11-31-01-19 31-11-95-03 32-61-00-02 33-14-00-07 34-61-51-03	031036	1
5	69-44578-2		.CAP-	001036 201967	1
10	MS24523-23		.SWITCH- ELECTRICAL EQUIP NUMBER: S00050	001036 201967	1
MISSING ITEM NUMBERS NOT APPLICABLE					

- ITEM NOT ILLUSTRATED


HAP

23-41-00-07

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-00
FIG. 07
PAGE 1
OCT 15/08

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23415101 SHT 1 REV 153

PANEL ASSY-E/E COMPT SVCE (COMMUNICATIONS ONLY)
FIGURE 1 (SHEET 1)



23-41-51-01

HAP
JUN 15/09

23-41-51-01
PAGE 0

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23415101 SHT 2 REV 050

PANEL ASSY-E/E COMPT SVCE (COMMUNICATIONS ONLY)
FIGURE 1 (SHEET 2)


23-41-51-01

HAP
OCT 10/06

23-41-51-01
PAGE 0A

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23415101 SHT 3 REV 153

PANEL ASSY-E/E COMPT SVCE (COMMUNICATIONS ONLY)
FIGURE 1 (SHEET 3)

23-41-51-01

HAP
JUN 15/09

23-41-51-01
PAGE 0B

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

 BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1			PANEL ASSY-E/E COMPT SVCE (COMMUNICATIONS ONLY)		
- 1	284A2211-1		PANEL ASSY-E/E COMPT SVCE (COMMUNICATIONS ONLY) FOR NHA/OTHER SYS DET SEE: 25-50-51-65	001030 201967	RF
- 1	284A2211-10		PANEL ASSY-E/E COMPT SVCE (COMMUNICATIONS ONLY) FOR NHA/OTHER SYS DET SEE: 25-50-51-65	031200 968999	RF
	5 BAC27DEX6173		.DECAL- PLACARD CONTENT: D6025 INTERPHONE SERVICE		1
	10 69B40302-7		.PLATE-INSULATION ATTACHING PARTS		1
- 15	BACR15BB3AC		.RIVET- SIZE DETERMINED ON INSTL. -----*-----		4
- 300	286A5337-002		WIRE BUNDLE ASSY	001007	RF
- 300	286A5337-006		WIRE BUNDLE ASSY-	201967	RF
- 300	286A5337-007		WIRE BUNDLE ASSY-	008030	RF
- 300	286A5337-008		WIRE BUNDLE ASSY-	031100	RF
- 300	286A5337-010		WIRE BUNDLE ASSY-	101200 968999	RF
R R R R R R R R	305 2J1865A		.JACK-SVCE INTPH SUPPLIER CODE: V82389 ELECTRICAL EQUIP NUMBER: D06025 WIRING DIAGRAM REF: 234111 OPTIONAL PART: BCREFD00032 V82389		1
	305 2J1659		.JACK-SVCE INTPH SUPPLIER CODE: V82389 ELECTRICAL EQUIP NUMBER: D06025 WIRING DIAGRAM REF: 234111		1
MISSING ITEM NUMBERS NOT APPLICABLE					

- ITEM NOT ILLUSTRATED


HAP

23-41-51-01

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-51
FIG. 01
PAGE 1
JUN 15/09

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23415102 REV 076

RECEPTACLE INSTL-EXT PWR (SERVICE INTERPHONE SYSTEM ONLY)

FIGURE 2

23-41-51-02

HAP
OCT 15/08

23-41-51-02
PAGE 0

 BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2			RECEPTACLE INSTL-EXT PWR (SERVICE INTERPHONE SYSTEM ONLY)	201967	
- 1	284A1807-102		RECEPTACLE INSTL-EXT PWR (SERVICE INTERPHONE SYSTEM ONLY) FOR NHA/OTHER SYS DET SEE: 24-40-00-01	201967	RF
	5 BAC27DEX6600		.MARKER	201967	RF
	10 BACW10CR7		.WASHER	201967	1
	15 BACW10P236L		.WASHER	201967	1
- 300	286A0048-003		WIRE BUNDLE ASSY-	201967	RF
310	2J1865A		.JACK-EP LIGHT SUPPLIER CODE: V82389 ELECTRICAL EQUIP NUMBER: D06007 WIRING DIAGRAM REF: 234111 OPTIONAL PART: BCREFD00032 V82389	201967	1
	310 2J1659		.JACK-EP LIGHT SUPPLIER CODE: V82389 ELECTRICAL EQUIP NUMBER: D06007 WIRING DIAGRAM REF: 234111	201967	1
MISSING ITEM NUMBERS NOT APPLICABLE					

- ITEM NOT ILLUSTRATED


HAP

23-41-51-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-51
FIG. 02
PAGE 1
JUN 15/09

BOEING
737-600/700/800/900
PARTS CATALOG (MAINTENANCE)



E 23415103 REV 114

ELECTRICAL INSTL-P5 AFT OVHD (COMMUNICATIONS ONLY)

FIGURE 3

23-41-51-03

HAP
OCT 10/06

23-41-51-03
PAGE 0

BOEING
 737-600/700/800/900
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
3			ELECTRICAL INSTL-P5 AFT	037200	
			OVHD (COMMUNICATIONS	968999	
			ONLY)		
- 1	MODREF293913		ELECTRICAL INSTL-P5 OVHD	037038	1
			(COMMUNICATIONS ONLY)	968968	
			MODULE NUMBER:		
			233A3326-1 REV B		
			POSITION DATA:		
			AFT		
			FOR OTHER SYS DETAILS SEE:		
			11-31-01-41		
			31-11-95-04		
			32-61-52-04		
			33-14-00-22		
			34-61-51-01		
- 1	MODREF332905		ELECTRICAL INSTL-P5 OVHD	039200	1
			(COMMUNICATIONS ONLY)	969999	
			MODULE NUMBER:		
			233A3326-1 REV C		
			POSITION DATA:		
			AFT		
			FOR OTHER SYS DETAILS SEE:		
			11-31-01-41		
			31-11-95-04		
			32-61-52-04		
			33-14-00-22		
			34-61-51-01		
5	69-44578-2		.CAP	037200	1
				968999	
10	MS24523-23		.SWITCH-	037200	1
			ELECTRICAL EQUIP NUMBER:	968999	
			S00050		
MISSING ITEM NUMBERS NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HAP

23-41-51-03

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

23-41-51
 FIG. 03
 PAGE 1
 OCT 15/08