


LAVATORY SMOKE DETECTION

BOEING
767
PARTS CATALOG (MAINTENANCE)



V 26130001 SHT 1 REV 173

EQUIPMENT INSTL-COMM (FIRE PROTECTION ONLY)

FIGURE 1

26-13-00-01

HXL
DEC 22/06

26-13-00-01
PAGE 0

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1			EQUIPMENT INSTL-COMM (FIRE PROTECTION ONLY)		RF
- 1	284T4201-10		EQUIPMENT INSTL-COMM (FIRE PROTECTION ONLY) VARIABLE DRAWING REF: 284T4201-5020 284T4201-5053 284T4201-5096 FOR NHA/OTHER SYS DET SEE: 24-00-58-01L		RF
15	284T4209-1		.LABEL- POSITION DATA: FWD	155162	1
15	284T4209-17		.LABEL- POSITION DATA: FWD	163999	1
20	284T4209-2		.LABEL- POSITION DATA: AFT	155162	1
20	284T4209-11		.LABEL- POSITION DATA: AFT	163999	1
45	PU90-13000-1		.PANEL- SUPPLIER CODE: VS5065 ELECTRICAL EQUIP NUMBER: M01640 M01641 COMPONENT MAINT MANUAL REF: 26-10-01	163163	2
45	PU90-13000A1		.PANEL- SUPPLIER CODE: VS5065 ELECTRICAL EQUIP NUMBER: M01640 M01641 COMPONENT MAINT MANUAL REF: 26-10-01	155162 164999	2
45	PU90-13000A101		.PANEL- SUPPLIER CODE: VS5065 ELECTRICAL EQUIP NUMBER: M01640 M01641 OPTIONAL PART: PU90-13000A1 VS5065	155162 164999	2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

26-13-00-01

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

26-13-00
 FIG. 01
 PAGE 1
 DEC 22/07




767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1					
- 50	NAS514P832-6		ATTACHING PARTS . SCREW -----*-----		4
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

BOEING
767
PARTS CATALOG (MAINTENANCE)



V 26130101 REV 179

SMOKE DETECTOR INSTL-LAV F1
FIGURE 1

26-13-01-01

HXL
DEC 22/06

26-13-01-01
PAGE 0

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1			SMOKE DETECTOR INSTL-LAV F1		
- 1	BS061740-511		SMOKE DETECTOR INSTL-LAV F1 SUPPLIER CODE: VS5065 FOR NHA SEE: 25-41-01-32B		RF
5	PU90-419R3		.DETECTOR ASSY- SUPPLIER CODE: VS5065 COMPONENT MAINT MANUAL REF: 26-10-03		1
10	BS061743-511		.WIRE BUNDLE- SUPPLIER CODE: VS5065		1
15	DAMA15S		.CONNECTOR- SUPPLIER CODE: V71468		1
20	DA20961		.HOUSING- SUPPLIER CODE: V71468		1
25	DA51220-1		.LOCK-SLIDING SUPPLIER CODE: V71468 POST SERVICE BULLETIN: 26-0087		1
30	BS060701-27		.BRACKET- SUPPLIER CODE: VS5065 ATTACHING PARTS		1
- 35	MS35206-241		.SCREW -----*-----		2
40	BACC45FN16-24P		.CONNECTOR ATTACHING PARTS		1
- 45	MS35206-215		.SCREW		2
- 50	MS21042-04		.NUT -----*-----		2
55	PU90-13000-1		.PANEL-CONT SUPPLIER CODE: VS5065 CONFIG CHG DATA FROM A CMM: SUPSD BY PU90-13000A1 COMPONENT MAINT MANUAL REF: 26-10-01		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

26-13-01-01

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

26-13-01
 FIG. 01
 PAGE 1
 DEC 22/07



767

PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1					
55	PU90-13000A1		.PANEL-CONT SUPPLIER CODE: VS5065 CONFIG CHG DATA FROM A CMM: SUPERSEDES PU90-13000-1 COMPONENT MAINT MANUAL REF: 26-10-01		1
60	DAMA25S		.CONNECTOR- SUPPLIER CODE: V71468 CONFIG CHG DATA FROM A CMM: SUPSD BY DBMA25S		1
60	DBMA25S		.HOUSING- SUPPLIER CODE: V71468 CONFIG CHG DATA FROM A CMM: SUPERSEDES DAMA25S		1
65	M2430819-3		.HOUSING-ANGLE SUPPLIER CODE: V71468 CONFIG CHG DATA FROM A CMM: M2430819-3 IS REF/CODE NO. FOR M24308-19-3		1
70	DB51221-1		.RETAINER-SLIDING SUPPLIER CODE: VU3384 CONFIG CHG DATA FROM A CMM: SUPERSEDES DM5122-1		1
70	DM5122-1		.ANGLE-SLIDING SUPPLIER CODE: V71468 CONFIG CHG DATA FROM A CMM: SUPSD BY DB51221-1		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED


HXL

26-13-01-01

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

26-13-01
FIG. 01
PAGE 2
DEC 22/07

BOEING
767
PARTS CATALOG (MAINTENANCE)



V 26130102 REV 160

SMOKE DETECTOR INSTL-LAV
FIGURE 2

26-13-01-02

HXL
DEC 22/06

26-13-01-02
PAGE 0

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
- 1	BS063740-501		SMOKE DETECTOR INSTL-LAV SMOKE DETECTOR INSTL-LAV MS15 AND MS17 MS27 AND MS29 SUPPLIER CODE: VS5065 FOR NHA SEE: 25-41-03-46B		RF
- 1	BS063740-511		SMOKE DETECTOR INSTL-LAV MS16 AND MS18 SUPPLIER CODE: VS5065 FOR NHA SEE: 25-41-03-46B	163999	RF
- 5	BS063740-502		SMOKE DETECTOR INSTL-LAV MS16 AND MS18 MS28 AND MS30 SUPPLIER CODE: VS5065 FOR NHA SEE: 25-41-03-46B		RF
- 5	BS063740-512		SMOKE DETECTOR INSTL-LAV MS15 AND MS17 SUPPLIER CODE: VS5065 FOR NHA SEE: 25-41-03-46B	163999	RF
10	PU90-419		.DETECTOR-SMOKE SUPPLIER CODE: VS5065		1
15	BS063743-501		.WIRE BUNDLE-LAV MS15 AND MS17 MS27 AND MS29 SUPPLIER CODE: VS5065		1
15	BS063743-502		.WIRE BUNDLE-LAV MS16 AND MS18 MS28 AND MS30 SUPPLIER CODE: VS5065		1
16	BS063743-511		.WIRE BUNDLE-LAV MS16 AND MS18 SUPPLIER CODE: VS5065	163999	1
16	BS063743-512		.WIRE BUNDLE-LAV MS15 AND MS17 SUPPLIER CODE: VS5065	163999	1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

26-13-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

26-13-01
FIG. 02
PAGE 1
DEC 22/07




767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
20	DAMA15S		.CONNECTOR- SUPPLIER CODE: V71468		1
25	DA20961		.HOUSING- SUPPLIER CODE: V71468		1
30	DA51220-1		.LOCK-SLIDING SUPPLIER CODE: V71468		1
35	BACC45FN12-12P		.CONNECTOR ATTACHING PARTS		1
- 40	MS35206-215		.SCREW		2
- 45	MS21042-04		.NUT		2
			-----*-----		
50	BS060701-29		.BRACKET- SUPPLIER CODE: VS5065 ATTACHING PARTS		1
- 55	MS35206-241		.SCREW		2
			-----*-----		
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

BOEING
767
PARTS CATALOG (MAINTENANCE)



SMOKE DETECTOR INSTL-MID LAV
FIGURE 3

26-13-01-03

HXL
DEC 22/06

26-13-01-03
PAGE 0



767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
3			SMOKE DETECTOR INSTL-MID LAV		
- 3	BS066740-511		SMOKE DETECTOR INSTL-LAV M31 AND M32 SUPPLIER CODE: VS5065 FOR NHA SEE: 25-41-03-52		RF
5	PU90-419		.DETECTOR-SMOKE LAV M31 AND M32 SUPPLIER CODE: VS5065		1
10	BS066743-511		.WIRE BUNDLE-LAV M31 AND M32 SUPPLIER CODE: VS5065		1
15	DAMA15S		.CONNECTOR- SUPPLIER CODE: V71468		1
20	DA20961		.HOUSING- SUPPLIER CODE: V71468		1
25	DA51220-1		.LOCK-SLIDING SUPPLIER CODE: V71468		1
30	BACC45FN12-12P		.CONNECTOR ATTACHING PARTS		1
- 35	MS35206-215		.SCREW		2
- 40	MS21042-04		.NUT		2
			-----*-----		
45	BS060701-29		.BRACKET- SUPPLIER CODE: VS5065 ATTACHING PARTS		1
- 50	MS35206-241		.SCREW		2
			-----*-----		
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

26-13-01-03

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

26-13-01
FIG. 03
PAGE 1
DEC 22/07



767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7 NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
3				
55	48-1825-02	.CONTACT-PIN LAV M31 AND SUPPLIER CODE: V77820 SPECIFICATION NUMBER: BACC47CN2 OPTIONAL PART: ZZL4016-36LT V49367 48-1825-02 V02660 417-1616-902 V92069 LRM16M15F74 V09922 M32		1
60	48-7191	.RECEPTACLE-LAV M31 AND M32 SUPPLIER CODE: V02660		1
65	418-1616-902	.CONTACT-SOCKET LAV M31 SUPPLIER CODE: V55104 SPECIFICATION NUMBER: BACC47CP2T OPTIONAL PART: ZZL4116-36LT V49367 248-136-1600S02 V77820 LRC16M15F74 V09922 AND M32		1
70	48-7190	.PLUG-LAV M31 AND M32 SUPPLIER CODE: V02660		1
75	P90-90720-1	.LIGHT ASSY-INDICATOR LAV M31 AND M32 SUPPLIER CODE: VS5065		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE				

— ITEM NOT ILLUSTRATED

HXL

26-13-01-03

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

26-13-01
FIG. 03
PAGE 2
DEC 22/07