

Service Information Index

L5 = iR2200/2800/3300 iR2200i/3300i (Image Reader B1)

S.I. No.	Model	Type	Description / Symptom	Date Issued
L5-000002-02	iR22/28/33	System	Network Scan Function	11/06/01
L5-000003-01	iR22/28/33	Software	Modification to S/Ware items for iR22/28/3300	20/09/01
L5-000007-01	iR22/28/33	Mech	Removal of the developing clutch	13/12/01
L5-000009-01	iR22/28/33	Mech	Laser Mirror Cleaning	19/12/01
L5-000011-02	iR22/28/33/ iR22i/33i	E-Code	Hard Disk Error Code E602	21/10/02
L5-000016-01	iR22/28/33	Mech	Measure against Cassette Lifter Failure to Rise	24/05/02
L5-000019-01	iR22/28/33	Mech	Preventing Wrong Detection of Cassette Size	29/04/02
L5-000021-01	iR22/28/33/ 22i/33i	Mech	Countermeasure Against Delay Jam 0101	07/04/03
L5-000023-01	iR22/28/33	Mech	Preventing lifting of the copyboard cover	23/05/02
L5-000025-UK1	iR22/28/33	Software	Release of System Software V31.04	30/05/02
L5-000029-01	iR2200i / 3300i	Dimm	Flash ROM DIMM of Reader Controller PCB Assembly will be masked.	14/06/02
L5-000031-01	iR22/28/33	Mech	Handling the Inlet Harness	25/06/02
L5-000033-01	iR22i/33i	Software	Release of the iR2200i Series System Software(Ver.5.04)	23/10/02
L5-000035-01	iR22/28/33/ iR22i/ 33i	Dimm	Flash DIMM-ROM of DC Controller PCB Assembly	14/10/02
L5-000039-01	iR22/28/33	Software	Releasing the iR2200 Series System Software(Ver32.07)	25/09/02
L5-000045-03	iR22/28/33 iR22i/33i	Mech	Disuse of Fan Motor on Controller Box	23/06/03
L5-000052-02	iR22/28/33	Software	Release of System Software (Ver 33.01)	19/12/02
L5-000054-01	iR22i/33i	Software	Release of System Software (Ver 6.01)	19/12/02
END				