

SUPERSEDES: None

HP 3070 Board Test System**Part Number Changes for Ithaca Printer****Situation:**

Two parts set up to supply Ithaca printer replacement parts are being discontinued. The two parts are 5959-4655, the magnet, and 5959-4656, the clip. There have been problems with printers in the field, so Ithaca will provide SMO/SME with a new kit.

Solution:

The new kit, part number 5041-6208, was set up at SMO/SME during January. It includes the magnet, clip and a screw.

DATE: July 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

GS

0980

© 1998 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

 **HEWLETT
PACKARD**

1 of 1