

IBM INSTALLATION INSTRUCTION

TITLE: HANDBOOK FOR LIC REINSTALLATION/REMOVAL IN CASE
OF:

- RPQ 7L1069, 7L1070, 7L1072, 7L1105
7L1106, 7L1107, 7L1108, 7L1109
7L1110, 7L1112.

- LIC1, LIC3, LIC4A/4B, MES REMOVAL.

1.0 MACHINES AFFECTED:

3745 model 150/170.

2.0 INSTRUCTIONS

For LIC reinstallation/removal use the Maintenance Information Procedures (MIP) chapter 4. It would be useful to begin first with chapter 1 (START).

3.0 END OF INSTRUCTIONS

ENG CHANGE NO. DATE OF CHANGE	A97885 16MAR90				PART NO. 61F4436 PAGE 1 OF 1
----------------------------------	-------------------	--	--	--	---------------------------------