



取扱説明書

縦置きスタンド VS01

Part No. Z1-004-270, IB017101

Mar. 2008

本製品は、当社の機器を縦置きにして使用するためのスタンドです。立ち作業やデスク作業をするときの操作性に優れ、キャスタ付なので移動も容易になります。

対応機種については、購入先または営業所にお問い合わせください。

NOTE


本製品は当社の機器と組み合わせて使用することを目的に設計されています。ご使用になる前に、当該機器の取扱説明書に記載されている警告および注意事項をよくお読みください。

ご使用上の注意


- 移動するときには、本製品を取り付ける機器の POWER スイッチをオフにして、接続されている全ての配線を外してください。
POWER スイッチをオンにしたまま移動すると、感電や破損の原因になります。
ケーブル類を外さないで移動すると、断線や転倒によるケガの原因となります。
- ハンドルを使用して機器を持ち上げないでください。
ハンドルはキャスタ移動用です。段差を乗り越える程度の、一時的な持ち上げには使用できます。
- 無理に押したり引いたりしないでください。
縦置きにして機器を使用しているときには、キャスタをロックして使用してください。
倒れたりして、破損やけがの原因になります。
- ケーブル類を接続するときには、機器を横置きにしてください。
- 接続しているケーブル類が、床に付かないようにしてください。

部品構成

部品が正しく添付されているか、損傷していないか、確認してください。万一、損傷や不備がありましたら、購入先または当社営業所にお問い合わせください。




取り付け



- 1 機器を机などの平らな台に置いて、機器の後面を台の端から出します。
上下に余裕があると、作業性が良くなります。
機器の質量が 20 kg を超える場合には、必ず二人以上で持ち上げてください。

- 2 付属のねじを使用して、ハンドルを取り付けます。




3 付属のねじを使用して、台座を取り付けます。


4 機器の端子にケーブル類や端子カバーなどを接続します。
接続方法や警告および注意事項は、製品の取扱説明書を参照してください。

NOTE


側板を取り付けた後は、ケーブル類や端子カバーなどを接続するのに作業性が悪くなります。
手順 5 に進む前に接続を完了してください。




5 付属のねじを使用して、機器の上面側になる側板を取付ます。



6 取り付け台座のキャスタがロックしているのを確認します。机などの台からおろして、本体を立てます。付属のねじを使用して、機器の底面側の側板を取り付けます。
本製品を含めた機器の質量が 20 kg を超える場合には、必ず二人以上で台から降ろしてください。



7 平らな床に置いて、がたつきがないか確認します。傾いてがたつくときには、手順 3 で取り付けした側面のねじを少し緩めて調整してから締め直してください。




ケーブルの固定例

8 ケーブル類が床に付かないように固定します。
側板の穴などを利用して、結束バンドで固定すると便利です。

取り付け完了です。

外形図



質量：約 5 kg (機器本体は除く)

単位：mm

菊水電子工業株式会社

本社・技術センター
〒224-0023 横浜市都筑区東山田 1-1-3
TEL: 045-593-0200 (代)
<http://www.kikusui.co.jp/>



ASSEMBLY INSTRUCTIONS

Vertical Stand VS01

The VS01 is used as a stand to hold the equipment in a vertical position. The VS01 is designed for easy operation when the equipment is used in standing operation or placed beside the desk, and it is equipped with caster wheels that can be moved easily.

For the applied equipment which can be used with the VS01, contact your Kikusui agent or distributor.

NOTE


The VS01 is designed to be used with the applied KIKUSUI equipment. Carefully read the warnings and precautions given in the Operation Manual of the applied equipment before attempting to use it.

Safety Precautions


- When moving the VS01 assembled with the equipment, make sure that the POWER switch of the equipment is turned off and all the cables are disconnected from the equipment.
Moving the VS01 assembled with the equipment while the POWER switch is turned on may cause electric shock or damage.
Moving the VS01 assembled with the equipment with the cables connected may cause wires to break or injuries due to the equipment falling over.
- Do not use the handles for lifting the equipment.
The handles are used to help for moving caster wheels. The handles may be used for lifting the equipment to climb over the bumps.
- Do not push or pull the VS01 by force.
When the VS01 is in used as a vertical angle operation, always lock the caster wheels.
It may cause injuries or damage the equipment due to the equipment falling over.
- When connecting the cables, place the equipment in a horizontal position.
- Make sure that the connected cables are not touched on the floor.

Components

Check that all parts are included and that they are not damaged. If any of the parts are damaged or missing, contact your Kikusui agent or distributor.




Assembly



- 1 Place the equipment on the flat surface such as a table top, then face the rear panel of the equipment towards out of the table.

For easy assembly, allow enough space on the top and bottom of the equipment. When the equipment weighs more than 20 kgs, use two or more persons to lift the equipment.

- 2 Use the screws included as accessories to attach the handles.




3 Use the screws included as accessories to attach the caster platforms.

4 Connect the cables and/or terminal covers to the terminals of the equipment.


Refer to the operation manual of the applied equipment for wiring instructions, warnings and cautions.

NOTE

After installing the side panels, connecting cables and/or terminal covers may be difficult.
All of the wirings must be completed before proceeding to the Step 5 .




5 Use the screws included as accessories to attach the side panel on the top side of the equipment.




6 Check that the caster wheels on the caster platforms are locked. Unload the equipment from the table, then place the VS01 in a vertical position. Use the screws included as accessories to attach the side panel on the bottom side of the equipment.

When the equipment weighs more than 20 kgs, use two or more persons to unload the equipment.



7 Place the equipment on the flat floor, and check that the equipment is firmly assembled. In case the VS01 is wobbling, loosen the screws attached in Step 3 , then adjust and tighten the screws again.




Bind the cable example

8 Check that the cables are not touching on the floor.
Use the holes on the side panels to bind the cable with cable ties.

Assembly is completed.

Outline drawing



Weight: Approx.5 kg (Excluding the weight of the equipment)

Unit: mm

KIKUSUI ELECTRONICS CORP.

1-1-3, Higashiyamata, Tsuzuki-ku, Yokohama,

244-0023, Japan

Tel : +81-45-593-7570

Fax : +81-45-593-7571

<http://www.kikusui.co.jp/>

Printed in Japan