
SECURITY BULLETIN

Kodak PACS Product Security Bulletin – Microsoft MS04-011 and MS04-012 Security Patches

Recent Vulnerabilities Reported By Microsoft. Kodak recommends the installation of the patches MS04-011 and MS04-012 to resolve the vulnerabilities announced by Microsoft in Security Bulletin MS04-011 and MS04-012, with the Microsoft Windows NT 4.0 and Windows 2000 operating systems found in many of our products.

It is important to note that these new vulnerabilities have been exploited in several recent malware attacks

Customers should contact their Kodak Service Representative for assistance in installing these service packs and security updates. The Kodak Service organization will provide support for customers who choose to purchase patch upgrades for the products listed below. This will include the appropriate installation and verification for the products involved.

Customers also have the option of choosing to install the Service Pack and Security Update on their own, but do so at their own risk. Kodak has detailed the necessary procedures that customers choosing to perform the installations themselves must follow. Ignoring the documented procedures may result in extended downtime, performance degradation, increased service costs, and may place patient data at risk of compromise of its integrity or of its confidentiality. Customers who wish to acquire these procedures should contact their Kodak Service Representatives. Repairs made by Kodak Service personnel that are a direct result of customer installation of the Service Pack and Security Update will be charged on a time and material basis.

Kodak PACS Product Implications

To guard against unauthorized access of Kodak servers and workstations, Kodak has performed a validation of the Microsoft Patches MS04-011 and MS04-012 contained in Microsoft Security Bulletins MS04-011 and MS04-012. The following recommendations are being made for the following Kodak products:

ClinicalAccess 4.1 client workstations: Customers still running this version are strongly encouraged to upgrade to DirectView TX 4.2. The application of Service Packs and Security Updates are the responsibility of the customer/user and is at their own risk. Kodak Service is not responsible for these systems.

DirectView TX 4.2 client workstations: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. (*Note: Microsoft Windows NT 4.0 Service Pack 6a or Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.*) The application of Service Packs and Security Updates is the responsibility of the customer/user and is at their own risk. Kodak Service is not responsible for these systems.

DirectView Web Distribution System 4.5 / PACS System 5.x web client workstations: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. (*Note: Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.*) The application of Service Packs and Security Updates is the responsibility of the customer/user and is at their own risk. Kodak Service is not responsible for these systems.

AccuRad 4.0.x/4.1.x on Windows NT: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. (*Note: Microsoft Windows NT 4.0 Service Pack 6a should be installed before applying these patches.*) Customers should contact their Kodak Service Representative for assistance in installing service packs and security updates. Customers who choose to install these updates themselves do so at their own risk. Customers still running this version are strongly encouraged to upgrade to DirectView CX/DX version 4.2/4.3.

SECURITY BULLETIN

(Note: HP LC3 Netserver running Windows NT may experience degraded performance after upgrading to DirectView CX/DX 4.2.)

SECURITY BULLETIN

ClinicalAccess Server 4.1.x on Windows NT: Customers still running this version are strongly encouraged to upgrade to DirectView TX 4.2. The application of Service Packs and Security Updates are the responsibility of the customer/user and are at their own risk. Kodak Service is not responsible for these systems.

DirectView TX Server 4.2 on Windows NT and Windows 2000: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. *(Note: Microsoft Windows NT 4.0 Service Pack 6a or Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.)* Customers should contact their Kodak Service Representative for assistance in installing service packs and security updates. Customers who choose to install these updates themselves do so at their own risk.

DirectView CX/DX 4.2.x on Windows NT or Windows 2000: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. *(Note: Microsoft Windows NT 4.0 Service Pack 6a or Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.)* Customers should contact their Kodak Service Representative for assistance in installing service packs and security updates. Customers who choose to install these updates themselves do so at their own risk.

DirectView CX/DX 4.3.x on Windows 2000: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. *(Note: Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.)* Customers should contact their Kodak Service Representative for assistance in installing service packs and security updates. Customers who choose to install these updates themselves do so at their own risk.

Note: Customers with DirectView CX/DX 4.3.x systems which include Dictaphone Powerscribe integration should verify, with Dictaphone, the level of Service Pack and Security Updates that are compatible with their version of Powerscribe, before applying any updates.

DirectView Diagnostic Workstation 5.0 on Windows 2000: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. *(Note: Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.)* Customers should contact their Kodak Service Representative for assistance in installing service packs and security updates. Customers who choose to install these updates themselves do so at their own risk.

DirectView Distribution Suite 5.0 on Windows 2000: Kodak is recommending the installation of Windows Security Updates MS04-011 and MS04-012, which are available from Microsoft. *(Note: Microsoft Windows 2000 Service Pack 4 should be installed before applying these patches.)* Customers should contact their Kodak Service Representative for assistance in installing service packs and security updates. Customers who choose to install these updates themselves do so at their own risk.