

|                                   |  |   |  |
|-----------------------------------|--|---|--|
| Model: Mail Box for NAD 30S/30/40 |  | Date: 28-Feb-99                                 | No.: 1   |
| Modified Article: Mail Box 3      |  | Prepared by: S. Tomoe                           |  |
| From: GTSS Field Information Dept |  |   |  |
| Reason for Modification:          | <input checked="" type="checkbox"/> Parts catalog correction | <input type="checkbox"/> Vendor change          | <input type="checkbox"/> To meet standards<br>(      ) |
|                                   | <input type="checkbox"/> To facilitate assembly              | <input type="checkbox"/> To improve reliability |  |
|                                   | <input type="checkbox"/> Part standardization                | <input type="checkbox"/> Other                  |  |

The following should be corrected. Please correct your parts catalog.

| Part number | Description     | Qty | Int | Page | Old Index | New Index | Note |
|-------------|-----------------|-----|-----|------|-----------|-----------|------|
| G9090340    | Spacer          | 10  |     | 7    | 40        | 41        |      |
| G9090341    | Bracket Tension | 2   |     | 7    | 41        | 40        |      |

|   |  |   |  |
|---|--|---|--|
| Model: NAD 30S/30/40 Mail Box               |  | Date: 31-May-99   | No.: MG909002  |
| Modified Article: Microswitch               |  | Prepared by: S. Tomoe   |  |
| From: Technical Service Dept., GTS Division |  |   |  |
| Reason for Modification:                    | <input checked="" type="checkbox"/> Parts catalog correction<br><input type="checkbox"/> To facilitate assembly<br><input type="checkbox"/> Part standardization | <input type="checkbox"/> Vendor change<br><input type="checkbox"/> To improve reliability<br><input type="checkbox"/> Other | <input type="checkbox"/> To meet standards<br>(      ) |

The following should be corrected. Please correct your parts catalog.

| Old part number | New part number | Description | Q'ty | Int | Page    | Index    | Note |
|-----------------|-----------------|-------------|------|-----|---------|----------|------|
| G9090428        | G9090726        | Microswitch | 1-1  |     | 9<br>15 | 28<br>26 |      |

|  |  |   |  |
|--|--|---|--|
| Model: NAD 30S/30/40 Mail Box                |  | Date: 07-Mar-00                                 | No.: MG909003  |
| Modified Article: Feeler Sensor              |  | Prepared by: E. Fukuyama                        |  |
| From: Technical Services Dept., GTS Division |  |   |  |
| Reason for Modification:                     | <input checked="" type="checkbox"/> Parts catalog correction | <input type="checkbox"/> Vendor change          | <input type="checkbox"/> To meet standards<br>(      ) |
|  | <input type="checkbox"/> To facilitate assembly              | <input type="checkbox"/> To improve reliability |  |
|  | <input type="checkbox"/> Part standardization                | <input type="checkbox"/> Other                  |  |

The following part number should be corrected. Please correct your parts catalog.

| Old part number | New part number | Description   | Q'ty | Page | Index |
|-----------------|-----------------|---------------|------|------|-------|
| G9090235        | G9090523        | Feeler Sensor | 1    | 9    | 29    |