

Model: Model K-P1/P2 4-bin Mailbox (CS380)		Date: 3-Jul-03	No.: MG553001
Modified Article: Main Control Board		Prepared by: A. Ishiyama	
From: 1st Technical Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()
Modification Schedule:	From October 2002 production		

An IC on the PCB has been changed to further minimize any effects of static electricity.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5535105A	G5535110	Main Control Board	1→1	X/O	7	10	

Model: Model K-P1/P2 4-bin Mailbox (CS380)		Date: 3-Jul-03	No.: MG553002
Modified Article: Parts Catalog Correction		Prepared by: A. Ishiyama	
From: 1st Technical Support Sec. Service Support Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following have been added to the Parts Catalog for the above option, as they were found to be missing during catalog revisions in preparation for the K-P3 (G091) launch.

Note: The Parts Catalog will be re-released in July 2003 together with the K-P3 Service Manual, containing all recent revisions made.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
	G5531016	Film: Guide: Auxiliary	0→2		3	20	
	G5531019	Paper Guide Mylar	0→2		3	21	