Reason for

Modification:

Modification Bulletin


PAGE: 1/1

Please correct the following part numbers in the DF65 part catalog.

Product Code: A661-10 for Savin A661-15 for Gestetner

A661 -17 for RICOH A661-26 for Danka A661-55 for Lanier

Old P/N	New P/N	Description	Q'ty	Index No.
A6615010	A6615511	ARDF Control Board	1→1	5-21
AW010066		Photosensor -PS-R50D1-B	3→1	5-23
	AW010074	Photosensor -PS-R11D1-E	0→2	5-50



RIGOH

Modification Bulletin

PAGE: 1/1

Model: DF65 (A661-	-10,-15,-17,-26,-55)		Date	e: 15-Mar-98	No: 2
Modified Article: A	RDF control board and some	exterior pa	ırts	Prepared by: ĸ.৻	Jgaeri
From: QAC Field Inf	ormation Dept.				
Reason for	☐ Parts catalog correction	☐ Vendo	or cha	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly	☐ To imp	orove	e reliability ()
	□ Part standardization	Other			

To standardize the parts with a new ARDF, some part numbers have been changed.

Product Code: A661-10 for Savin A661-15 for Gestetner

A661 -17 for RICOH A661-26 for Danka A661-55 for Lanier

Old P/N	New P/N	Description	Int	Index No
A5481771	A6612211	Side Fence	O/O	5-16
A6615735	A6615760	Relay Harness – Original Tray	O/O	5-22
A6612165B	A6612165C	Original Tray Bracket	O/O	5-29
A6612141C	A6612141D	Front Original Table	0/0	5-47
A6615011	A6615510	ARDF Control Board 2	0/0	5-21

16	か	叩
ルりし		H

Modification Bulletin

PAGE: 1/1

Model: DF65 (All)		Dat	e: 15-Mar-98	No: 3
Modified Article: A	RDF control board		Prepared by: ĸ.เ	Jgaeri
From: QAC Field Inf	ormation Dept.			
Reason for	Parts catalog correction	☐ Vendor ch	nange 🔲 To r	neet standards
Modification:	☐ To facilitate assembly	☐ To improv	e reliability ()
	□ Part standardization	Other		

To standardize the PWB (Printed wire board), the following number has been changed.

Old P/N	New P/N	Description	Int	Index No.
A6615510	A6615540	ARDF Control Board 2	0/0	5-21



Modification Bulletin

PAGE: 1/1

Reissued: 27-Mar-00

Model: AD1 ARDF	Date: 15-Jan-00	No.: MA661004a

MB Correction

The items in bold italics have been corrected or added.

Modified Article: ARDF Original Table			Prepared by: K. Ugaeri		
From: Technical Services Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Other			

Correct the part catalog for DF65 as follows

Incorrect P/N No.	Correct P/N	Description	Int	Page	Index	Note
A6612141	A6612441	Front Original Table	X/O	5	47	

Note1)

The A6612141 is a daughter part of A6612441 and does not have an arrow printed on it.