RIGOH


Modification **B**ulletin

PAGE: 1/1

Model: Triton-C1 ADF (DF81)			Date	e: 3-Jun-05		No.: MB721001		
Modified Article: Grounding Tape				Prepared by: M. Tsuyuki				
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	☐ Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☑ To improve reliability☐ Other		()			
	☐ Part standardization							

Old part number	New part number	Description	Q'ty	Int	Page	Index
	B7215006	Grounding Tape (6LA56652000)	1		11	6

Change: Grounding tape was added. **Reason:** To reduce static electricity buildup and improve the stacking of the originals.



CUT-IN SERIAL NUMBERS

Model: From:


B186-17 From First Production

Model: Triton-C1 ADF (DF81)			Date	e: 2-Aug-05	;	No.: MB721002		
Modified Article: Holder Pad Etc.				Prepared by: M. Tsuyuki				
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	□ Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability		()			
	☐ Part standardization	☐ Othe	☐ Other					

Change/Reason: The Parts Catalog was corrected as follows.

Old part	New part	Description	Q'ty	Int	Page	Index
number	number					
B7211030		Holder Pad (4408090680)	1->0		3	30
B7211032		Pad (4408692190)	1->0		3	32
B7211033		Mylar Hld Pad (4408690730)	1->0		3	33
B7213014	B7213214	Roller Exit (4408691210) Roller Exit (4408694720)	1	X/O	7	14
B7215102	B7215152	Spring Ass'y (4408691820) Spring Ass'y (4408693020)	1	X/O	13	3

3. ASM EXIT



6. Hinge

