

Model: Kir-C2 Fax Option (B620)		Date: 20-Jul-04	No.: MB620001
Modified Article: Fax Cover		Prepared by: M. Ishihara	
From: 1 <sup>st</sup> Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards (      )

Please note the following changes:

1. A vinyl bag was added to the Fax Cover for more protection.

**Note:** This is the only difference, so both the new and old parts can be used in the field.

2. The page number for the Fax Cover was corrected:

Incorrect: pg. 12

**Correct: pg. 3**

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6201421	B6201415	Fax Cover NA	1-1	O/O	<b>3</b>	3	
B6201450	B6201422	Fax Cover EU	1-1	O/O	<b>3</b>	3	

Model: Kir-C2 Fax Option		Date: 4-Aug-04	No.: MB620002
Modified Article: PCB GWFCU3		Prepared by: H.Yokoyama	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input checked="" type="checkbox"/> To meet standards (EMI)

The PCB GWFCU3 has been modified for the following reasons.

- The noise margin has been increased to meet EMI standards.
- To include a jumper on the PWB pattern.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6205172	B1685172	PCB GWFCU3 NA Ass'y	1	X/O	2	8	
B6205174	B1685174	PCB GWFCU3 EU Ass'y	1	O/O	2	8	

Cut in serial number: April '04 production.

Reissued: 8-Sep-04

Model: Kir-C2 Fax Option	Date: 4-Aug-04	No.: MB620003a
--------------------------	----------------	----------------

## MB Correction

The items in bold italics have been corrected or added.

Modified Article: FAX Option : PCB GWFCU3		Prepared by: H.Yokoyama	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards (      )

## Symptom

Black stripe appears at the time of image rotation.  
 Fax option (FCU) is not detected  
 SC820 (~~still under investigation~~)

## Modification

1 x Resistor has been removed  
 1 x Jumper has been added

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
<b><i>B1685172</i></b>	<b><i>B1685182</i></b>	PCB GWFCU3 NA Ass'y	1	X/O	2	8	
<b><i>B1685174</i></b>	<b><i>B1685184</i></b>	PCB GWFCU3 EU Ass'y	1	X/O	2	8	

## Cut in Serial Number

This modification will be applied to mass production from July 1st.  
 The cut in serial number information is as follows.

B620-27 : J9346700543  
 B620-17 : J9346703578  
 B620-29 : J9346700001  
 B620-21 : no production in July  
 B620-19 : from 22nd July

Additional information for the June production (see below for details)

### The following fax options contain the modified FCU

#### B620-17 (1017 units)

J346604774-4846, 4852, 4860, 4869, 4876, 4915-4984, 4994, 5002, 5011, 5023, 5036, 5048, 5053, 5056-5145, 5147-5157, 5159-5164, 5166-5175, 5177-5182, 5322-5324, 5326-5333, 5335-5341, 5343-5373, 5375-5389, 5391-5401, 5403-5411, 5413-5419, 5421-5425, 5427, 5428, 5430-5438, 5696-5706, 5708-5714, 5716-5721, 5723-5735, 5737-5744, 5746-5751, 5753-5759, 5761-5766, 5909, 5916, 5924, 5932, 5941, 5974, 5982, 5990, 5998-6068, 6070-6077, 6079-6094, 6096-6156, 6159, 6161, 6162, 6165, 6167, 6169, 6170, 6173, 6174, 6176, 6185, 6195, 6203, 6216, 6237, 6259-6648

**Reissued: 8-Sep-04**

Model: Kir-C2 Fax Option	Date: 4-Aug-04	No.: MB620003a
--------------------------	----------------	----------------

**B620-21 (2 units)**

J346600106, 0111

**B620-27 (1043 units)**

J346601795, 1806, 1828, 1845, 1975, 1988, 2005, 2011, 2020, 2032, 2045, 2056,  
2071-2231, 2233-2246, 2248-2251, 2253-2261, 2263-2266, 2430, 2527-2535, 2537-  
2545, 2547-2564, 2566-2571, 2573-2582, 2584-2594, 2596-2602, 2604-2609, 2611-  
2617, 2619-2714, 2716, 2718-2727, 2733, 2734, 2737, 2739-2803, 2819, 2827, 2836,  
2845, 2850-3114, 3116, 3125, 3136, 3143, 3154, 3165, 3185, 3195, 3203, 3213, 3222,  
3254-3553

**B620-29 (20 units)**

J346600338, 0403, 0404, 0406-0410, 0412-0414, 0417, 0421, 0424-0428, 0433, 0435