Modification Bulletin


PAGE: 1/1

Model: NAD 30S/30/40 LCT (RT36)			te: 30-Aug-0	0	No.: MA683001		
Modified Article: Side Plate				Prepared by: E. Fukuyama			
From: Technical Services Dept., GTS Division							
Reason for	eason for Parts catalog correction		hange	☐ To n	neet standards		
Modification: ☐ To facilitate assembly ☐ T		☐ To improve reliability		()		
	☐ Part standardization	Other					

The following have been registered as service parts.

New part number	Description	Q'ty	Int	Page	Index
A6832550	Side Plate : Front	0-1	-	7	28
A6832560	Side Plate : Rear	0-1	-	7	29

3.PAPER TRAY (A683)



D	Π	つ	ጠ	ПП
	Ш	رال	(0)	빖

Reason for

Modification:

Model: NAD 30S/30/40 LCT (RT36)

From: 1st Tech. Support Sec. Service Support Dept.

Modified Article: Hinge Bracket

Modification **B**ulletin

Other

	Date: 5-Jun-03			No.: MA68	3002
		Prepared	by: Y.U	Jrushihara	
t.					
			☐ To n	neet standar	ds
☐ To improve reliability			()	

PAGE: 1/1

The following has been changed due to a vendor change.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A6831280	B5431280	Hinge Bracket	1	0/0	3	18	



Modification **B**ulletin

PAGE: 1/1

Reissued: 9-Jul-03

	Model: NAD 30S/30/40 LCT (RT36)	Date: 2-Jul-03	No.: MA683003a
--	--------------------------------	---	----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: F	rame – Large Capacity Tray	Prepared by: Y.Urushihara			
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	Other			

The following P/N has been added to the Parts Catalog, as it was previously missing.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B5431050	Frame – Large Capacity Tray	0-1		9	19	

