# RIGOH

## Modification Bulletin

**PAGE: 1/1** 

Reissued: 22-Oct-04

Model: Russian-C2 500 Finisher (	(SR820)	Date: 12-Aug-02	No.: MB442001a

#### **MB Correction**

The items in bold italics have been corrected or added.

Modified Article: Balancer			Prepared by: S. Tomoe		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		( )	
☐ Part standardization ☐ Other					

Please apply the following index number corrections to your Parts Catalogs:

Old index	New index	Part number	Description	Page	Note
number	number				
40	41	G3143102	Balancer – Lever Paper Exit	9	
41	40	G3141125	Lower Plate - Left Ass'y	9	
			Protection - Paddle		

# RIGOH

## Modification Bulletin

**PAGE: 1/1** 

Reissued: 9-Mar-04

Model: Russian-C2 500 Finisher (SR820)	Date: 12-Feb-04	No.: MB442002a

#### **MB Correction**

The items in bold italics have been corrected or added.

Modified Article: Main Controller Board			Prepared by: S. Tomoe		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly	, – ,		( )	
	☐ Part standardization				

The ROM on the main controller board has been changed to a Mask ROM.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B4420410	B4420450	Main Control Board Ass'y	1-1	O/O	13	14	

	നതന	П
K	1G0	Ln

### Modification Bulletin

**PAGE: 1/1** 

Model: Russian-C2 500-sheet Finisher (SR820)			ate	e: 12-Feb-0	4	No.: MB442003
Modified Article: Main control Board Ass'y			Prepared	by: S.	Tomoe	
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor	r cha	ange	☐ To m	neet standards
Modification:	☐ To facilitate assembly	<ul><li>☑ To improve reliability</li><li>☑ Other</li></ul>		(	)	
	☐ Part standardization					

The finisher PCB software has been modified so that:

- The jam condition is not triggered when the paper is pulled out of the finisher before the job is completed.
- Stapling is cancelled if the paper is removed from the finisher before stapling is done.

In accordance with this, the following has been changed.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4420450	B4580400	Main control Board Ass'y	1-1	X/O	13	14	

**Japan Production** 

MODEL NAME	DESTINATION	CODE	SERIAL NO.
SR820	All RICOH subsidiaries, NRG, SAVIN	B442-17	J1830900106-13, 184, 204-218, 224-
SR820	Infotec	B442-26	4N61030001

$\sim$	пп
Œ0	
II In I II I	l n l
1001001	ш

# Modification Bulletin

**PAGE: 1/1** 

							_
Model: Russian-C2 500-sheet Finisher (SR820)			Date: 12-Feb-04		4	No.: MB442004	
Modified Article: Main control Board Ass'y			Prepared by: S. Tomoe			_	
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction ☐ To facilitate assembly	<ul><li>✓ Vendor change</li><li>☐ To improve reliability</li><li>☐ Other</li></ul>		☐ To n	neet standards )		
Modification:	Part standardization						

The following has been changed due to a vendor change.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B4580400	B4420460	Main Control Board Ass'y	1-1	O/O	13	14	

$-\infty$	пп
]Œ0	4
ונוחנטו	ını
	ш

Reason for

Modification:

Model: Russian-C2 500-sheet Finisher (SR820)

From: 1st Tech. Support Sec. Service Support Dept.

Modified Article: Holder Spring

# Modification Bulletin

Date	e: 27-Apr-04	4	No.: MB442005			
	Prepared	by: Y.	Ohtani			
t.						
☐ Vendor change		☐ To meet standards				
☐ To improve reliability		(	)			

**PAGE: 1/1** 

Please apply the following P/N correction to your Parts Catalogues.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Incorrect	Correct	Description	Q'ty	Int	Page	Index	Note
part number	part number						
G302 1120	G302 1114	Holder Spring	1-1		9	18	

Other