

Model: STR-G3

No. 495

Subject: Loses Memory

Date: October 10, 1996

Symptom:

(***)

The customer complaint states that the unit loses memory when it is unplugged, after a power failure, or when using an external timer.

Solution: Add a 10K pull up resistor as outlined below.

REF	DESCRIPTION	PART NUMBER
N/A	10K OHM CARBON RESISTOR	1-247-855-11

