

CDX-51/51RF

SONY SERVICE MANUAL

*US Model
Canadian Model
E Model
AEP Model
UK Model*


SUPPLEMENT-3

File this supplement with the service manual.

Subject: Hideaway Unit Modification


(ENG-96020)

• New/Former Discrimination



NOTE:

- Items marked “*” are not stocked since they are seldom required for routine service. Some delay should be anticipated when ordering these items.
- The mechanical parts with no reference number in the exploded views are not supplied.



Ref. No.	Part No.	Description	Remark	Ref. No.	Part No.	Description	Remark
1	1-473-881-11	RF UNIT (HIDEAWAY)		F1	1-532-416-00	FUSE (3.15A)	
2	1-777-519-11	CORD (WITH CONNECTOR)		F2	1-532-360-XX	FUSE (1A)	