

VESTEL ELEKTRONİK A.Ş.	TECHNICAL CHANGE BULLETIN TEKNİK DEĞİŞİKLİK BÜLTENİ	CHANGE NO: 102
		REF NO :
		DATE :06.12.2001

AFFECTED MODELS: CP2842AN , CL2842AN , C2842N , CP2142AN , CL2142AN , C2142N

START DATE : 15.12.2001

REASONS OF CHANGE:

DEFECT OF THE RGB AMPLIFIER TDA 6108 (IC 901)

TO CATCH A BETTER RELIABILITY ACCORDING SPARKS OF THE PICTURE TUBE THE LAYOUT OF THE CRT-BOARD WAS CHANGED .

NOTE 1: THE SPARE-PART NUMBER OF THE COMPLETE INSERTED CRT-BOARD DOES NOT CHANGED .
FROM DATE 15.12.2001 THE NEW PCB 11TP19Y3 WILL BE USED UNSTEAD OF 11TP19Y1 .

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	CRT-Board 30007743	30014245	PCB 11TP19Y1		1
2					
3					
4					
5					

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	CRT-Board 30007743	30016572	PCB 11TP19Y3		1
2					
3					
4					
5					

APPLICATION ENGINEER	APPLICATION ENGINEER CHIEF	APPLICATION ENGINEER MANAGER
S.DEMIRKAYA		BEYHAN DAĞITAN

