

<b>VESTEL</b> ELEKTRONİK A.Ş.	<b>TECHNICAL CHANGE BULLETIN</b>	<b>CHANGE NO: 66</b>
		<b>REF NO : UMB-1334</b>
		<b>DATE : 27/10/1999</b>

**AFFECTED MODELS: ALL 11AK19 CHASSIS INCLUDING STEREO SOUND BOARD WITH MSP34XX DECODER IC.**

**START DATE : 06.12.1999**

**REASONS OF CHANGE: POP NOISE PROBLEM.**

**OUT**

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11 <sup>ST</sup> 19	30000721	RES SMD 1/10W 4.7K J	R303	1
2	11 <sup>ST</sup> 19	30000534	RES SMD 1/10W 15K J	R304	1
3	11 <sup>ST</sup> 19	30000475	RES SMD 1/10W 10K J	R305	1
4					
5					

**IN**

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11 <sup>ST</sup> 19	30000359	CAP EL 1000UF 16V M	R303	1
2	11 <sup>ST</sup> 19	30000469	RES SMD 1/10W 1K J	R304	1
3	11 <sup>ST</sup> 19	30000717	RES SMD 1/10W 470R J	R305	1
4					
5					

APPLICATION ENGINEER	APPLICATION ENGINEER CHIEF	APPLICATION ENGINEER MANAGER
	YILDIRAY BAŞKURT	CELAL ÖZKUL