

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 80 REF NO : -
-----------------------------------	----------------------------------	-------------------------------------

AFFECTED MODELS: ALL MODELS WITH 11AK19-B1 AND 11AK19-E3 CHASSIS.

START DATE : 1th July.2000

REASONS OF CHANGE: All models with 11AK19-B1 & 11AK19-E3 chassis including SDA545X controller family have been replaced with 11AK19-P chassis including SDA555X controller family.

NOTE 1: The ordering code of the new service manual for 11AK19-P chassis is 50014848.

NOTE 2: New controller SDA555X is not compatible with the previous ones SDA525X & SDA545X from the view of hardware side. For detailed explanation please refer to Service Manual /11AK19-P.

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19-B1	Model Based	11AK19-B1 CHASSIS	-	1
2	11AK19-E3	Model Based	11AK19-E3 CHASSIS	-	1

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19-P	Model Based	11AK19-P	-	1

APPLICATION ENGINEER	APPLICATION ENGINEERING CHIEF	APPLICATION ENGINEERING MANAGER
-	YILDIRAY BAŞKURT	BEYHAN DAĞITAN