

VESTEL ELEKTRONİK A.Ş ORGANİZE SANAYİ BÖL.MANİSA/ TURKEY	PRODUCT CONTENT CHANGE BULLETIN				REF NO
					UMB - xx
CHANGE REQUEST					
EXPLANATION: <p>THE BREAKDOWN PROBLEM OF THE IC TDA 6111Q ON THE POSITIONS IC901, IC902 AND IC903 ON THE 11TP28 BASE BOARD.</p> <p>11TP28 VER E:5 PCB SHOULD BE REPLACED WITH 11TP28-7 IMMEDIATELY.</p>					
APPLICATION REQUEST DATE			* IMMEDIATELY <input checked="" type="checkbox"/>	* RUNNING CHANGE <input type="checkbox"/>	
AFFECTED PRODUCTS					ADD. LIST <input type="checkbox"/>
COMPONENTS OUT					
No	PCB Code / Pic. No	VESTEL Code	Description	Position	Amount
1		30016571	PCB 11TP28 (VER:E5)		1
2	11 TP 28 VER-5	30000433	CAP CER 1NF 1KV M B	C 937	1
3	11 TP 28 VER-5	30000428	SPARK GAP 300V	SP 901, SP XX	2
4	11 TP 28 VER-5	30000580	RES CF 1/4W 22R J	R 940	1
5	11 TP 28 VER-5	30001994	FIXED COIL 22UH J AXIAL	J 921	1
6	11 TP 28 VER-5	30002583	KISA DEVRE TELİ 0.6MM	J 920	1
7	11 TP 28 VER-5	30000295	CAP CER 100NF 50V Z F	C 940	1
8	11 TP 28 VER-5	30002876	CABLE ASSY 1/25 AK19 EMC		1
9					
10					
COMPONENTS IN					
No	PCB Code / Pic. No	VESTEL Code	Description	Position	Amount
1		30017573	PCB 11TP28-7		1
2	11 TP 28-7	30000428	SPARK GAP 300V	SP 901, SP 903, SP 904 SP 905, SP 906, SP 907	6
3	11 TP 28-7	30001994	FIXED COIL 22UH J AXIAL	L 921	1
4	11 TP 28-7	30002583	KISA DEVRE TELİ 0.6MM	J 915, J 916	2
5					
6					
7					
8					
9					
10					
COMPONENT IN		ALTERNATIVES FOR COMPONENTS IN			EXIST <input type="checkbox"/> NOT EXIST <input type="checkbox"/>
		COMPONENT IN	ALTERNATIVE	DIFFERENCE COMP.	
				ADD. LIST <input type="checkbox"/>	
RESPONSIBLE ENGINEER		App. Eng. Manager Approval		FINAL NOTES	
NAME SURNAME / SIGNATURE		DATE/TIME SIGNATURE			