

Technical Information

Page 1 of 1

Calibration Unit PGT 2000

(Part No.: 7100.PGT2000.C)

- The Calibration Unit contains resistors within the specified tolerances for testing the **Personnel Grounding Tester PGT 2000** (7100.PGT2000.NET)
- The Calibration Unit requires no battery or any external power supply
- The user is guided through the calibration procedure by the software and can print a certificate after successful calibration.
- Contacting the footwear electrode requires an additional probe (i.e. Model 850 Part No. 7220.850)
- A standard digital voltmeter is needed for checking the test voltage



Dimensions:
125 x 60 x 26 mm

Technical data:

Drehschalter	Widerstand	Toleranz	Bereich
A	0Ω	± 1%	0 ... 5Ω
B	17kΩ	± 1%	16,83kΩ ... 17,17kΩ
100k	100kΩ	± 1%	99kΩ ... 101kΩ
1M	1MΩ	± 1%	990kΩ ... 1010kΩ
35M	35MΩ	± 1%	34,65kΩ ... 35,35kΩ
100M	100MΩ	± 1%	99MΩ ... 101MΩ
200M	200MΩ	± 1%	196MΩ ... 204MΩ



We believe all the information in these pages including technical data to be reliable. However we make no warranties expressed or implied and assume no liability regarding any use of this information.

V0203