


## Spare parts list

### CUTBEND VB

0.8 mm

Cutting and bending machine for axial taped components



Pos. Art.Nr Designation

|      |      |                                    |
|------|------|------------------------------------|
| 01   | 1113 | Clamp                              |
| 02   | 9680 | Base plate                         |
| 03   | 9681 | Left-hand side panel               |
| 03.1 | 9682 | Mounting screw M6x25               |
| 04   | 9683 | Right-hand side panel              |
| 05   | 9684 | Crank                              |
| 05.1 | 9643 | Hex socket head screw M6x6         |
| 06   | 1103 | Collector bin                      |
| 07   | 9685 | Cover with skimmer                 |
| 07.1 | 9650 | Skimmer                            |
| 08   | 9704 | Left-hand bending unit 0.8 mm      |
| 08.1 | 9676 | Bending spring support LH 0.8 mm   |
| 08.2 | 9678 | Guide plate LH 0.8 mm              |
| 08.3 | 9743 | Sunk screw M2x4                    |
| 09   | 9705 | Right-hand bending unit 0.8 mm     |
| 09.1 | 9677 | Bending spring support RH 0.8 mm   |
| 09.2 | 9679 | Guide plate RH 0.8 mm              |
| 10   | 9645 | Bending spring 0.8                 |
| 11   | 9706 | Left-hand cutting unit 0.5-0.8 mm  |
| 12   | 9707 | Right-hand cutting unit 0.5-0.8 mm |
| 13   | 1108 | 1 set cutters with screws Ø+Ø      |

Pos. Art.Nr Designation

|      |      |                                     |
|------|------|-------------------------------------|
| 14   | 9708 | Upper shaft                         |
| 15   | 9691 | Center shaft                        |
| 16   | 9693 | Left-hand cutting wheel 0.5-0.8 mm  |
| 16.1 | 9642 | Lock screw                          |
| 16.2 | 9742 | Sunk screw M3x4                     |
| 17   | 9694 | Right-hand cutting wheel 0.5-0.8 mm |
| 18   | 9695 | Left-hand bending wheel 0.8 mm      |
| 19   | 9696 | Right-hand bending wheel 0.8 mm     |
| 20   | 9697 | Square rod                          |
| 20.1 | 9690 | Mounting screw M6x12                |
| 21   | 9698 | Left-hand belt guide complete       |
| 21.1 | 9651 | Left-hand belt guide                |
| 22   | 9699 | Right-hand belt guide complete      |
| 22.1 | 9652 | Right-hand belt guide               |
| 23   | 9640 | Knurled screw M6x12                 |
| 24   | 9641 | Knurled screw M3x4                  |
| 25   | 9644 | Hex wrench 2.5 mm                   |
| 26   | 9700 | Hex wrench 5 mm                     |
| 27   | 9701 | Guide plate                         |
| 28   | 9702 | Strip-off lever                     |
| 29   | 9703 | Knurled screw M4x8                  |
| 30   | 1102 | Setting tool metric/inch            |

We believe all the information in these pages including technical data to be reliable. However we make no warranties expressed or implied and assume no liability regarding any use of this information.

Siemens Nederland N.V.  
ESD Services  
Remmerden 5  
3911 TZ Rhenen  
P.O. Box 129  
3910 AC Rhenen  
The Netherlands  
Phone +31 31 7398 787  
Fax +31 31 7398 780