

Erratum

Discharge Current Oscillation in Hall Thrusters

Naoji Yamamoto
Kyushu University, Fukuoka 816-8580, Japan
and
Kimiya Komurasaki and Yoshihiro Arakawa
University of Tokyo, Tokyo 113-8656, Japan

[J. Propulsion, 21 (5), pp. 870–876, 2005]

A wrong correction was done at equation 22. It lacks “ $\bar{N}_n SL$ ” as follows:

$$S_1 V_{e1} - S_0 V_{e0} - \overline{(\sigma_{di} v_e)}_{T_e} > 0 \quad (22)$$

The correct one is shown as follows:

$$S_1 V_{e1} - S_0 V_{e0} - \overline{(\sigma_{di} v_e)}_{T_e} \bar{N}_n SL > 0 \quad (22)$$