

**From:** [Taylor, Mark](#)  
**To:** [Joaquin Mavares](#)  
**Cc:** [Marshall, Donald](#)  
**Subject:** RE: P.O. 5100077213; VENDOR: ProEnergy Services; SUB-VENDOR: Wood Group; W.O. 2232  
**Date:** Monday, February 08, 2010 11:08:23 AM  
**Attachments:** [TP2 Rotor Test Data.pdf](#)  
[TP2 Rotor Rewind.pdf](#)  
[TP2 Stator Inspection Data.pdf](#)  
[TP2 Rotor Assembly.pdf](#)

---

Joaquin,

Attached, for your review is the data and photos on the inspection and rotor rewind for TP2. Please note that Tom Moran and I flew to Los Angeles last Thursday and had pulled together a full crew of WG individuals to work through the weekend to address the following items noted in the BIE report. I'm now at JAX walking down the Control Room, of which Tom Moran will stay in LA to ensure the items are completed prior to the next inspection.

Regards  
Mark

- \* Paint rusting and peeling off - Currently under going clean and painting
- \* No structural damage apparent
- \* Generator shaft at both ends in good shape - no damage noted
- \* junction box missing cover - Cover has been manufactured
- \* Conduit runs missing brackets - Bracket have been located
- \* Minor bolting missing on covers - Bolts purchased / covers manufactured
- \* suspect conduit wiring broken in various locations, - Wiring inspected and verified
- \* Flanged connections covered with wood to protect - Wooden covers are being replaced with metal, paint yellow to indicate remove/termination points.

-----Original Message-----

From: Joaquin Mavares <jmavares@proenergyservices.com>  
To: Marshall, Donald  
CC: Jeff Canon <JCanon@proenergyservices.com>  
Sent: Mon Feb 08 09:47:16 2010  
Subject: FW: P.O. 5100077213; VENDOR: ProEnergy Services; SUB-VENDOR: Wood Group; W.O. 2232

Don see the report from the inspector.

Thanks

Joaquin

Joaquin Mavares  
Director of International Sales  
ProEnergy Services  
2031 ProEnergy Boulevard  
Sedalia, Missouri 65301  
660-829-5100 office  
660-829-1160 fax  
713-992-1790 cell

<http://www.proenergyservices.com> <<http://www.proenergyservices.com/>>

P Please consider the environment before printing this e-mail

This e-mail is the property of ProEnergy Services, LLC and/or its relevant affiliate and may contain confidential and privileged material for the sole use of the intended recipient (s). Any review, use, distribution or disclosure by others is strictly prohibited. If you are not the intended recipient (or authorized to receive for the recipient), please contact the sender or reply to ProEnergy Services at [chowatt@proenergyservices.com](mailto:chowatt@proenergyservices.com) <<mailto:chowatt@proenergyservices.com>> and delete all copies of the message. This e-mail (and any attachments hereto) are not intended to be an offer (or an acceptance) and do not create or evidence a binding and enforceable contract between ProEnergy Services LLC (or any of its affiliates) and the intended recipient or any other party, and may not be relied on by anyone as the basis of a contract by estoppel or otherwise. Thank you.

From: lmedina@psi.pdv.com [<mailto:lmedina@psi.pdv.com>]  
Sent: Monday, February 08, 2010 8:35 AM  
To: Omar Petit; Joaquin Mavares  
Subject: Fw: P.O. 5100077213; VENDOR: ProEnergy Services; SUB-VENDOR: Wood Group; W.O. 2232

Buenos dias, por favor lean el reporte de inspeccion y realicen los trabajos pertinentes de pintura y adecuacion los mas pronto posible ya que este equipos pertenece al item 04 y el mismo debe de ser liberado en su totalidad esta semana.

BIE recommend PI (Polarization Index Testing) before acceptance.

Sincerely  
Leiro Medina  
Inspection Coordinator  
PDVSA Services INC.  
1293 Eldridge Parkway  
Citgo Houston Texas 77077  
Work Phone: 281-588-6252  
Fax: 2815886274

----- Forwarded by LEIRO MEDINA/PSI on 02/08/2010 08:30 AM -----

"aeturner@bieusa.com" <[aeturner@bieusa.com](mailto:aeturner@bieusa.com)>

02/06/2010 10:59 AM

To

"Bill Bates (bill.bates@bienl.com)" <bill.bates@bienl.com>,  
Denise op der Heijde <Denise.Heijde@bienl.com>,  
"rita.vollebregt@bienl.com" <rita.vollebregt@bienl.com>

cc

Subject

P.O. 5100077213; VENDOR: ProEnergy Services; SUB-VENDOR: Wood  
Group; W.O. 2232

BIE BV Ref. No.: I-BA-003/10  
BIE USA Ref. No.: 4519C

Good Morning -

Attached is Inspection Report 22 (4519C.04) for Bill Skoug's visit Wood  
Group Santa Fe Springs, California on 03 February 2010.

Best regards,

B.I.E. International Inc.

E. Angela Turner  
Phone : (281) 556-0234  
Fax : (281) 556-8748  
email : aeturner@bieusa.com  
<http://www.bie-international.com>