

# Manual Supplement

Manual Title:	DSP-FTA410 Users	Supplement Issue:	1
Part Number:	691656	Issue Date:	6/02
Print Date:	September 1998	Page Count:	1
Revision/Date:	1, 2/00		

---

---

This supplement contains information necessary to ensure the accuracy of the above manual.

## Change #1

On page 28, under Autotest Results for Far End Source Mode, add the following:

### *If Loss Readings are Negative*

Negative loss values can occur under the following conditions:

- The connections to the fiber test adapters were disturbed after referencing.
- The fiber ends were dirty during referencing.
- There was a kink in the reference patch cords during referencing.
- The connectors were not properly aligned during referencing.
- The fiber test adapters were much cooler during referencing than during testing.

If a loss value is negative, reset the reference and retest the fiber.