

S E R V I C E N O T E

SUPERSEDES: None

54753A TDR Module**Serial Numbers:** 0000A00000 / 9999Z99999**54753A TDR Module fails vertical cal. in 54750A/83480A after use in 86100A****Duplicate Service Notes:** 54754-02**Situation:**

A 54753A TDR module that is used in an 86100A Infiniium DCA will fail vertical calibration if used again in either an 83480A or 54750A mainframe.

Solution / Action:

This problem has been solved in a new firmware version A.07.12 for both the 83480A and the 54750A. The new firmware can be obtained at:

http://lwd.marketing.agilent.com/Service&Support/Firmware/54750/agilent_54750_software.htm

-or-

http://lwd.marketing.agilent.com/Service&Support/Firmware/83480A/agilent_83480a_software.htm

View the readme files at these sites for more information on the files.

DATE: June 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

RC

ENTITY:

5360

ADDITIONAL INFORMATION:

