

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**54832B-06**

# S E R V I C E                      N O T E

Supersedes:  
NONE

54832B

Serial Numbers: [0000A00000 / 9999Z99999]

**Update on errors in service manual 54830-97006. They will be corrected in next revision.**

**Parts Required:**

P/N	Description	Qty.
-----	-------------	------

NONE

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: [initials]      PRODUCT LINE: 1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



**Agilent Technologies**

August 5, 2002

**Situation:**

In CH 7 “Replaceable Parts” Add the following replaceable parts.

MP40	54832-01201	CLIP FOR LOGIC CABLE	qty:1
MP41	54832-09103	PS HOLE SPRING	qty:1
MP42	54832-09102	CRT SPRING	qty:1
MP43	9170-2094	FERRITE CORE	qty:1
MP44	54832-40601	BNC SPRING	qty:1

On Chapter 7-12 to 7-13

Item W12, the p/n for Keyboard Cable is 54826-61601 instead of 54826-61602.

Item MP12, the quantity should be 1 instead of 2.

On Chapter 7-11

Item A8, the Mesa HDD has been changed from 0950-3933 (5GB) to 0950-4166 (10GB) hard disk.

**Solution/Action:**

**They will be corrected in next revision of service manual.**