

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

54832D-06

S E R V I C E N O T E

Supersedes:
NONE

54832D

Serial Numbers: [0000A00000 / 9999Z99999]

Update on errors in service manual 54830-97006. They will be corrected in next revision.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: [initials] PRODUCT LINE: 1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



Agilent Technologies

August 5, 2002

Situation:

In CH 7 "Replaceable Parts" Add the following replaceable parts.

MP40	54832-01201	CLIP FOR LOGIC CABLE	qty:1
MP41	54832-09103	PS HOLE SPRING	qty:1
MP42	54832-09102	CRT SPRING	qty:1
MP43	9170-2094	FERRITE CORE	qty:1
MP44	54832-40601	BNC SPRING	qty:1

On Chapter 7-12 to 7-13

Item W12, the p/n for Keyboard Cable is 54826-61601 instead of 54826-61602.

Item MP12, the quantity should be 1 instead of 2.

On Chapter 7-11

Item A8, the Mesa HDD has been changed from 0950-3933 (5GB) to 0950-4166 (10GB) hard disk.

Solution/Action:

They will be corrected in next revision of service manual.