United States Of America

Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

Number SA00143BO

This Certificate issued to

Avidyne Corporation 55 Old Bedford Road Lincoln, Massachusetts 01773

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number :

A00009CH

Make:

Cirrus Design Corporation

Model :

SR20, SR22

Description of Type Design Change:

Installation of Avidyne Corporation Model 700-00004-XXX-() Multi-Function Display with Software Part Number 530-00117-000 in accordance with Avidyne Corporation Master Document List, Document No. AVPRO-101, Revision 10, dated June 25, 2002, or later FAA-approved revisions.

Limitations and Conditions:

- Avidyne Corporation Aircraft Flight Manual Supplement for Cirrus Design Corporation Models SR20/SR22, Document 600-00074, Revision B, dated June 12, 2002, or later FAA-approved revisions, is required and must be carried in the aircraft during all flights.
- 2. Instructions for Continued Airworthiness (ICA), Avidyne Corporation Document AVPRO-107, Revision 06, dated June 25, 2002, or later FAA accepted revision shall be made available to the operator at the time of installation.
- 3. Compatibility of this design change with previously approved modifications must be determined by the installer.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the

Date of application . March 26, 2001

Date reissued :

Date of issuance : January 15, 2002

Date amended: June 25, 2002

Federal Aviation Administration.

By direction of the Administrator

(Signa Robert G. Mann

Manager

Manage

Boston Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.