

NEWS BULLETIN



Bulletin #123 C
August 1, 1968

Charging Table for Super 8 batteries with line voltage in
United States and abroad.

NR * Batteries should be charged with caution in this position since both charger
and battery will operate at high temperature which could shorten battery life.

AC line voltage 50/60 CPS.	Charging Current mA	Charger Switch Position	Charging Time 250mA 500mA	
			HOURS	
90	18	120	17 hrs.	32 hrs.
110	26	120	12 1/4	22 1/2
115	28	120	12	22
120	30	120	11 1/2	21
135	34.5	120	10	18
140	37	120*	9.5 (NR)	(NR)
150	42	120*	8 (NR)	(NR)
160	48	120*	7 (NR)	(NR)
160	13	220	28	52
175	17	220	19 1/2	32
190	21	220	14 1/2	27
200	23	220	14	26
205	24.5	220	13	24
210	25.5	220	12 1/2	23
220	27.5	220	12	22
230	30	220	11 1/2	21
240	32	220	11	20
250	34	220	10 1/2	19

After initial charge, batteries should be put on a two hour
charge every two weeks when not in use.